


1994 Annual Report



January 1995

Flambeau Mining Company
Subsidiary of Kennecott Corporation
N4100 Highway 27
Ladysmith, WI 54848
(715) 532-6690
FAX (715) 532-6885

Kennecott

January 30, 1995

Mr. Lawrence J. Lynch
Mine Reclamation Unit
Bureau of Solid & Hazardous Waste Management
101 South Webster Street, GEF II
Madison, WI 53707

RECEIVED

FEB 01 1995


**BUREAU OF SOLID
HAZARDOUS WASTE MANAGEMENT**

Dear Mr. Lynch:

Flambeau Mining Company (Flambeau) is submitting 12 copies of the attached 1994 Annual Report pursuant to Part 1-8 of the conditions of the Flambeau Mine Permit (Docket No. IH-89-14). This submittal also addresses other requirements of the Mining Permit and associated approvals.

If you have any comments or questions regarding this submittal, please contact me at (715) 532-6690.

Sincerely,



Jana E. Murphy
Supervisor of Environmental Affairs

Distribution

No. of Copies

Sent to

12	Mr. Lawrence J. Lynch Mine Reclamation Unit Bureau of Solid and Hazardous Waste Management 101 South Webster Street, GEF II Madison, WI 53707
3	Thomas R. Myatt General Manager Flambeau Mining Company N4100 Hwy 27 Ladysmith, WI 54848
1	Mr. Paul Kent DeWitt Ross & Stevens S.C. 2 E. Mifflin Street-Suite 600 Madison, WI 53703-2685
1	Bernice Dukerschein, Chairperson Rusk County Board of Supervisors 311 East Miner Avenue Ladysmith, WI 54848
1	Tom Riegel, Chairman Town of Grant N2937 Highway 27 Ladysmith, WI 54848
1	Al Christianson, Administrator City of Ladysmith P. O. Box 431 Ladysmith, WI 54848
1	Melvin Spencer Rusk County Zoning Administrator 311 East Miner Avenue Ladysmith, WI 54848
1	James B. Hutchison, P.E. Project Engineer Foth & Van Dyke Associates 2737 South Ridge Road Green Bay, WI 54307

FLAMBEAU MINING COMPANY
1994 ANNUAL REPORT

CONTENTS

1.0	Purpose and Need	1
2.0	Operating Activities	4
2.1	1994 Summary	4
2.2	Deviations and Modifications	7
2.3	Construction Reports	7
2.4	Incident Log	8
2.5	Drillholes	8
3.0	Reclamation Activities	10
4.0	Site Monitoring	11
4.1	Groundwater Quality Sampling and Analysis	11
4.2	Surface Water	12
4.2.1	Sediments	12
4.2.2	Fish	14
4.2.3	Macroinvertebrates	18
4.2.4	Surface Water Quality	18
4.2.5	Habitat Characteristics	18
4.2.6	Wetland Surface Flows	20
4.3	Meteorology	26
4.4	Total Suspended Particulates (TSP)	26
4.5	Asbestiform Fibers	37
4.6	Operational Monitoring	37

TABLES

Table 1-1	Location Information Key	3
Table 2-1	1994 Incident Log	9
Table 4-1	Downstream Sediment Sampling Results	16
Table 4-2	Blackberry Lane Sediment Sampling Results	17
Table 4-3	Surface Water Quality Data	19
Table 4-4	Wetland 5C Staff Gauge Readings	21
Table 4-5	Wetland 6C Staff Gauge Readings	22
Table 4-6	Wetland 7 Staff Gauge Readings	23
Table 4-7	Wetland 10A Staff Gauge Readings	24
Table 4-8	Wetland 1 Staff Gauge Readings	25

Table 4-9	TSP Data Summary	27
Table 4-10	TSP Filter Metal Results	38
Table 4-11	Type I Lysimeter Data	41
Table 4-12	Pit Inflow Summary	42
Table 4-13	Pit Development Data	43
Table 4-14	Type II Leachate Data	45

FIGURES

Figure 2-1	Pit Pumping/Water Discharged	6
Figure 4-1	Monitoring Well Locations	13
Figure 4-2	Sampling Locations	15
Figure 4-3	TSP Graph - Site 0001	32
Figure 4-4	TSP Graph - Site 0003	33
Figure 4-5	TSP Graph - Site 0004	34
Figure 4-6	TSP Graph - Site 0005	35
Figure 4-7	Air Monitoring Station Locations	36

APPENDICES

Appendix A	List of Deviations
Appendix B	Surge Pond/Runoff Pond Side Slope Evaluation
Appendix C	Groundwater Quality & Elevation/Surface Water Quality/Trends
Appendix D	Sediment Sampling
Appendix E	Fish Sampling
Appendix F	Macroinvertebrate Sampling
Appendix G	Habitat Characterization
Appendix H	Results of Wetland Monitoring Efforts for 1994
Appendix I	Monitoring Well/Piezometer Construction Logs
Appendix J	Liner Repair Documentation

1.0 PURPOSE AND NEED

This report serves to document the work that was done at the Flambeau Mine site in 1994 and to satisfy the requirements of the Mining Permit (MP) and the Type I and Type II storage area Conditional Approval (CA) letter dated March 9, 1993.

Mining Permit, Part 1, Condition 8:

In accordance with sec. 144.89, Stats., Flambeau shall submit a report annually to the Department summarizing the activities which took place on the mining site during the year and shall include other additional information specified in this permit and associated plan approvals.

Mining Permit, Part 2, Condition 4:

The annual report required under sec. 144.89, Stats., shall include discussion of all modifications received during the previous year and shall include an inventory of all modifications received subsequent to permit issuance. The annual report shall also discuss deviations from the approved Mining Plan as a result of final engineering refinements of subsequent plan approvals if these deviations do not require modifications, under Part 2, Conditions 2 and 3.

Mining Permit, Part 2, Condition 6:

Flambeau shall keep a log of all incidents, such as spills, pond overflows and embankment failure or leakage, reported to its environmental compliance staff. This log shall, at all reasonable times, be available for inspection by any duly authorized Department employee. A summary of incidents subject to various Department reporting requirements shall be included in the annual report required under sec. 144.89, Stats.

Mining Permit, Part 2, Condition 7 (Excerpt):

The annual report required under sec. 144.89, Stats, shall include a summary of all exploration drilling activities conducted on mining site during the previous year.

Mining Permit, Part 2, Condition 14 (Excerpt):

The evaluation of the Type II collection system shall be included in the annual report required under this permit.

Mining Permit, Part 3, Condition 10:

Flambeau shall conduct a program of in-field trials for reclamation methods and materials prior to final reclamation. A description of methods, materials, analyses and results shall be submitted to the Department on an annual basis.

Mining Permit, Part 4, Condition 9:

Monitoring data and results shall be submitted to the Department within 30 days after completion of the required analyses. The annual report required in this permit shall summarize the year's monitoring activities and any observed trends in the monitoring data.

Conditional Approval, Condition 13:

The annual report required under the Mining Permit should include documentation of the following:

- a. *Inspection of the sideslopes of the surge pond and runoff pond for any sign of washout or deformation.*
- b. *Inspection of the 36" diameter drain from the Type II stockpile, the entrance manhole, access manholes, outlet and the geomembrane-covered seam in the pipe junction prior to the outlet.*
- c. *Inspection of the scuff strip below the outlet of the 36" pipe outlet in the surge pond.*

Groundwater Withdrawal Permit, Condition 4 (Excerpt):

At the end of each year of pit excavation and ore extraction, Flambeau shall submit to the Department of Natural Resources, Bureau of Water Supply a written tabulation of the monthly totals for: precipitation volume, surface water run-on, groundwater inflow and dewatering pumping.

The location of the information which fulfills the requirements of the above conditions are referenced in Table 1-1.

TABLE 1-1**Location Information Key**

Condition No.	Location of Information
MP, Part 1-8	Section 2.1
MP, Part 2-4	Section 2.2 and Appendix A
MP, Part 2-6	Section 2.4
MP, Part 2-7	Section 2.5
MP, Part 2-14	Section 4.6
MP, Part 3-10	Section 3
MP, Part 4-9	Section 4 and Appendix C through H
CA, Condition 13a	Section 4.6 and Appendix B
CA, Condition 13b	Section 4.6
CA, Condition 13c	Section 4.6 and Appendix B
GWP, Condition 4	Section 4.6

2.0 OPERATING ACTIVITIES

2.1 1994 SUMMARY

Construction of the Flambeau Mining Company (Flambeau) Type II/Phase II stockpile was completed during 1994 in accordance with plans approved in the Mine Permit. The document titled "Construction Documentation Report Type II Stockpile Phase 2 Construction" dated October 26, 1994 was submitted to the Wisconsin Department of Natural Resources (WDNR) Mine Reclamation Unit for review. Final approval of the construction document was granted by the WDNR on December 22, 1994.

During January 1994 mine production continued in the Phase I portion of the pit (west half) at the 1050 elevation and by year's end the mine had reached the 1000 elevation. Overburden removal in Phase II commenced during the second quarter of 1994 and reached the 1080 elevation by the end of the year. A total of 1,170,000 tons of Type I material, 694,600 tons of Type II material and 430,990 tons of ore were removed from the open pit in 1994.

Shipments of ore sent to Canada for processing totaled 449,900 tons. Shipments during 1994 were supplemented with 19,000 tons from the on-site ore stockpile generated during 1993. Mill ore shipped to Timmins, Ontario total 292,400 tons and the remaining 157,500 tons of ore were shipped to Rouyn-Noranda, Quebec as either direct smelter ore (DSO) or as gossan ore.

During May 1994 a second shift of contractor personnel was added to meet production requirements. The second shift continued through to the end of 1994. The percentage of all mine personnel consisting of local content as defined by the Local Agreement ranged from 78% to 82% throughout the year. The operational workforce ranged from a high of 85 in August (including contractors) to a low of 50 in March. As of the end of the year there were 64 employees.

The wastewater treatment plant (WWTP) discharged an average 500,400 gallons per day through Outfall 001 to the Flambeau River. No difficulties were experienced in achieving the required effluent standards.

In December 1993 Flambeau initiated a Toxicity Reduction Evaluation (TRE) which was the result of the second acute reaction experienced by *Ceriodaphnia dubia* (*C. dubia*) in 100% effluent within a twelve month period. While the WWTP effluent discharge was in complete compliance with chemical specific limitations, the effluent was deficient in constituents which reduce the bioavailability of metal ions. As a result, *C. dubia* was affected by metal ions at low concentrations in 100% effluent. However, through research it was realized that *C. dubia* was not affected by metal ions at these same concentrations within the Flambeau River water. The reason being that the Flambeau River contains naturally occurring constituents which reduce the bioavailability of metal ions. Flambeau proposed simulating this characteristic of the Flambeau River within the WWTP treatment process. Following extensive research, Flambeau found that by utilizing citric acid as part of the pH adjustment in the sulfide precipitation process, the

bioavailability of metal ions is reduced as in the Flambeau River. Following WDNR approval, Flambeau initiated the use of citric acid within the WWTP process during September 1994. Bioassays performed in the remainder of 1994 have resulted in no acute reaction for any of the three test species in 100% effluent.

During 1994, effluent discharge to the river was greater than the 1993 level by 16% at 129.1 million gallons; the increase is due to three additional months of operation as compared to 1993. The average monthly discharge of 10.8 million gallons per month during 1994 remained relatively constant as compared to 1993. As evident in Figure 2-1, effluent discharge peaked during September due to excessive precipitation events producing a 100-year flood condition for the Flambeau River on September 15. The difference in quantity of water pumped from the pit as compared to the quantity of water discharged can be attributed to the additional surface runoff from the crusher/ore stockpile area and Type II stockpile which must be treated within the WWTP. During September an average of 808,000 gallons per day was treated within the WWTP. The plant capacity is 1.152 million gallons per day.

During the Flambeau River flood the mine was not in danger, however, precautions were taken on the night of September 15 to protect the pit in the event the 100-year flood was substantially exceeded. A temporary three to four foot berm was constructed around the mine's west end at the 1100 elevation. The berm was removed subsequent to the flood.

While no river water entered the pit, approximately four million gallons of mine site surface runoff flooded the pit bottom. The surface runoff was the result of rains during the time period September 12-16. Copper ore production was able to recommence on September 21. The WWTP treated the stored water within the pit and normal operating conditions resumed September 27.

Reclamation activities throughout the year included routine inspection and maintenance of vegetation throughout the project area. The construction associated with the Type II/Phase II stockpile required erosion control and establishment of vegetation. The erosion control measures were effective in minimizing off-site sedimentation and will remain in place until stabilization is evident. The prairie seed test plots and aquascape continue to be monitored annually to determine best methods to be utilized during final reclamation and to document naturally occurring fluctuations in performance. The buffer screen between the mine site and the Flambeau River required 110 trees to be planted to replace trees damaged by natural occurrences such as damage from deer.

During 1994 there was one lost time accident involving a contractor employee. As of the end of the year the operation has worked 184 days accident free.

A significant effort was devoted to general monitoring of the air, groundwater, surface water and the biological environment with the subsequent generation of reports. This Annual Report summarizes much of the collected data, most of which has been submitted to the WDNR throughout the year.

FLAMBEAU MINING COMPANY
PIT PUMPING \ WATER DISCHARGED

1994 MONTH	PIT PUMPING	WATER DISCHARGED
JAN	7.71	8.35
FEB	7.56	8.93
MAR	8.66	11.08
APR	9.15	10.08
MAY	7.20	9.86
JUN	8.63	11.19
JUL	10.63	10.86
AUG	10.65	12.26
SEPT	16.09	21.00
OCT	11.65	12.52
NOV	9.20	10.62
DEC	9.03	9.65




Figure 2-1

The following is a summary of significant milestones throughout the year:

- | | |
|---|--------------|
| ◦ Reinitiated Phase II Open Pit Development | May 1994 |
| ◦ Net Proceeds Tax Early Payment to Local Governments | June 15 |
| ◦ WDNR Approval of Increased Production | August 17 |
| ◦ TSP Air Monitoring Schedule Reduced | August 18 |
| ◦ Flambeau River Flood | September 15 |
| ◦ WWTP Citric Acid Feed Implemented | September 28 |
| ◦ WDNR Approval of Type II/Phase II Construction | December 22 |

2.2 DEVIATIONS AND MODIFICATIONS

Condition 2-4 in the Mine Permit requires an inventory of deviations and modifications to the Permit received subsequent to permit issuance.

During 1994 Flambeau had requested a modification of the Mining Permit to increase the production rate from 320,000 tons/year to 450,000 tons/year. The WDNR solicited input from the County, City and Town governments to determine the significance of the requested change. The WDNR determined that the requested change did not constitute a substantial modification of the project and would not result in significant additional impacts in the area. The WDNR issued the requested modification in their letter dated August 17, 1994.

Minor deviations of constructed facilities were made and approved to accommodate specific site conditions. Deviations were reviewed and approved by WDNR prior to construction.

A list of the modifications and deviations for 1994 is included in Appendix A.

2.3 CONSTRUCTION REPORTS

One construction documentation report was submitted in 1994 to complete the construction reporting required by the Mine Permit for the Type II/Phase II stockpile. "Construction Documentation Report Type II Stockpile Phase 2 Construction" (October 1994) is incorporated by reference.

Additionally, in its original letter authorizing mine start-up (March 9, 1993), WDNR requested that certain documentation be included in the Annual Report:

- Inspection of sideslopes of surge pond and runoff pond
- Inspection of Type II stockpile piping
- Inspection of scuff strip below the surge pond outlet

The required documentation is described in Section 4.6 of this report and included in Appendix B.

2.4 INCIDENT LOG

Mine Permit Condition 2-6 requires a log of all incidents such as spills, pond overflow, embankment failure or leakage. This log is maintained on-site and is available for inspection. A summary of incidents reported to the environmental compliance staff is included in Table 2-1. Spills are reported in accordance with s. NR 158, CERCLA Reportable Quantities and SARA Section 302 Extremely Hazardous Substances Reportable Quantities.

2.5 DRILLHOLES

Mine Permit Condition 2-7 requires a summary of all exploration drilling activities conducted on the mine site during the previous year. Two drilling programs were either completed or commenced in 1994. The first program commenced March 24, 1994 and was completed on June 15. Three holes were drilled for a total footage of 3,993 consisting of 574 feet of rotary and 3,419 of cored volcanic "greenstone" rock. All holes were permanently abandoned with neat cement.

The second program was commenced on December 7, 1994 and will be completed the first quarter of 1995. The hole for the second program was drilled to a depth of 470 feet but permanently abandoned on December 10 due to severe hole wandering. The replacement hole has been hammer drilled to 970 feet during 1994 and will be completed during 1995.

**TABLE 2-1
FLAMBEAU MINING COMPANY
1994 INCIDENT LOG**

DATE	INCIDENT	ACTION
6/10/94	10-15 gal. waste oil spill into Surge Pond due to overflow of oil/water separator.	Contaminated material contained and cleaned up. Operator training of correct management of oil/water separator. WDNR official notified 6/10/94.
12/02/94	14-15 gal. hydraulic fluid spill due to haul truck hydraulic lines bursting.	Contaminated material contained and cleaned up. Continued inspection and replacement of hydraulic lines as necessary. WDNR notified on 12/02/94.
12/14/94	Dozer rolled onto its side resulting in 5 gal. anti-freeze solution and 1 gal. oil spilled.	Contaminated material contained and cleaned up. Reinforce safe dozer operation. National Response Center, Wisconsin Division of Emergency Government, and WDNR notified on 12/15/94.

3.0 RECLAMATION ACTIVITIES

As required by the Mine Permit Section 3, reports on progress of reclamation are prepared throughout the year. An annual report is required by Condition 3-26(d). The 1994 Annual Reclamation Report dated November 14 was submitted to the WDNR and is incorporated by reference. Other reclamation updates submitted on January 28 and September 26, 1994 are incorporated by reference. Reclamation activities reported in the November 1994 report included removal of woodchips from topsoil stockpile, erosion control associated with Type II/Phase II stockpile, prairie seed test plot and aquascape assessment, buffer screen tree planting and remedial seeding.

Additional reclamation activities completed subsequent to the November 14 submittal included alterations to the Outfall 002 discharge channel within the mine site. The alterations were made to maintain the quality of effluent discharges through Outfall 002. Additionally, the reconfiguration of the roadway accessing the west wall improved safe operating conditions.

The open discharge channels to Outfall 002 and the hydric topsoil stockpile were converted to 12-inch diameter buried HDPE pipe. The buried pipe to Outfall 002 terminates at a point approximately 30 feet from the flow metering weir. In-line valves divert flow to Outfall 002 and/or the hydric soil stockpile. The valves will be normally open to the hydric soil stockpile and closed to Outfall 002.

Straw bales were placed adjacent to the hydric soil stockpile to minimize sedimentation from the disturbed areas. Silt fence installation and seeding will occur when weather conditions permit.

4.0 SITE MONITORING

4.1 GROUNDWATER QUALITY SAMPLING AND ANALYSIS

Quarterly groundwater monitoring was performed in accordance with descriptions provided in the Updated Monitoring Plan (July 1991), the Revised Mining Permit Quality Assurance/Quality Control Document (August 1991) and the Local Agreement. Results of the monitoring were submitted to the WDNR Mine Reclamation Unit March 9, June 23, September 9 and December 21, 1994. Those reports are incorporated by reference.

Monitoring data for each groundwater monitoring site is graphed and tabulated in Appendix C. A statistical trend test (Mann-Kendall test) was performed on the results for each compound within each well. Those results are also shown with the tabulated data. Only those water quality parameters which showed a statistically significant trend upward or downward are discussed in this section. More detailed information on trend analysis and other trends is contained in Appendix C. Sample results from the following wells appeared to show statistically significant trends:

MW1000P	Iron	(Downward Trend)
	Alkalinity	(Downward Trend)
	Copper	(Upward Trend)
MW1010P	Manganese	(Downward Trend)
MW1005	Iron	(Upward Trend)

Iron and alkalinity showed a slight downward trend in MW1000P. The trends are not consequential because iron concentrations vary by less than 2 mg/l and alkalinity values vary by less than 80 mg/l sitewide. As the open pit develops, the hydraulic gradient will be toward the pit which may slightly impact these wells within the west wall. Copper showed a slight upward trend in MW1000P. The trend analysis may have been influenced by a single result which could prove to be anomalous. The sitewide variability of copper results has been less than 50 ug/l which is not consequential.

MW1005 shows an upward trend for iron concentrations. The Ladysmith area is known to have higher concentrations of iron in shallow wells than is typical for other areas. MW1005 serves as a background well since it is upgradient from the mine site in regards to groundwater flow. Groundwater quality from MW1005 will continue to be monitored for continuing trends.

The trend analysis for manganese in MW1010P also suggests a slight downward trend; the difference between the highest and lowest manganese values is 0.27 mg/l. Therefore the trend appears not to be consequential.

Iron, TDS and manganese standards contained in Condition 1-9 of the Mine Permit were inadvertently established well below some background levels at the site. The WDNR agreed that these standards should be corrected. Flambeau submitted a report to the WDNR on August 17, 1994 requesting a correction of the iron, manganese and TDS groundwater standards.

Elevations of groundwater in wells and piezometers near the pit continue to show decreasing trends from approximately 10 to 30 feet as anticipated in the Groundwater Model for the Kennecott Flambeau Project (July 1989). Groundwater elevations intermediate (1200 feet) and remote (2400 feet) from the pit are not as extreme as predicted by the model. Following pit construction, water levels have been temporarily drawn down around the pit, though when natural groundwater fluctuations prior to pit construction are taken into account, the new drawdown is minimal. Groundwater drawdown from pit dewatering can be seen in the following wells located within 500 feet from the pit: 1000R, 1000P, 1010P, PZ-S1, OW-42, 1004, 1004S, 1004P, 1001, 1001G, 1001P, OW-7, 1003, 1003P, ST-9-23, ST-9-23A, PZ-S3, ST-9-26, OW-39, PZ-1A and PZ-R1. Those wells located within close proximity of the pit are either dry or continue to show a strong downward trend in groundwater elevations as the pit is developed. Figure 4-1 presents the locations of monitoring wells. Graphs and further discussion on groundwater elevations are included in Appendix C.

During September 1994, the Flambeau River level exceeded a 100-year flood level. While the pit was not in danger, reports of upstream dam instability caused Flambeau to take immediate action to construct a supplementary flood control berm on the west pit wall at the 1100 elevation. During the berm construction, MW1000P was carefully cut off at ground level and covered by a metal plate to prevent materials from entering the well. Following verification that materials had not filled MW1000P, the well was reconstructed with a casing elevation of 1101.88. The well was redeveloped by purging until clean water was produced.

4.2 SURFACE WATER

The surface water monitoring program includes sampling and analyses of the following elements: sediments, fish, macroinvertebrates, water quality, habitat characteristics and wetland surface flows. The Revised Mining Permit Quality Assurance/Quality Control Document (August 1991) specifies that an annual surface water monitoring report will be prepared and submitted to WDNR in March of each year. This portion of this report, submitted in January is the surface water monitoring report referenced in the Quality Assurance Document.

4.2.1 SEDIMENTS

Sediment samples are collected once per year at two locations in the Flambeau River. Sediment traps were installed on July 11, 1994 and retrieved a month later on August 9, 1994. WDNR was advised of the installations and collection dates prior to installation.

During 1993, a third sediment sample location (S-3) had been established approximately 9,500 feet upstream from the Port Arthur Dam sample location (S-2) to evaluate the need for

replacement of S-2. The substrates in the vicinity of the Port Arthur Dam sample location had been determined to be very dissimilar to substrates of the Blackberry sample location (S-1) upstream from the mine site. The highly erodible banks located in the vicinity of Port Arthur Dam may contribute to the differing substrate characteristics. The comparison of data between these two locations would be difficult due to the differing nature of the substrates. Following 1993 sediment sampling, S-3 was determined to be suitable for downstream sampling and replaces S-2. Sample point S-3 is located near the Sister's Farm downstream from Outfall 001.

Figure 4-2 shows the sediment sampling locations. Results from both downstream sample sites are noted on Table 4-1. Results from the Blackberry Lane sampling site upstream of the mine are noted in Table 4-2. More detailed information about the sediment sampling is contained in Appendix D.

In general, samples collected in 1994 were uniform in consistency being made up of soft sediment with no gravel. The lack of gravel can be attributed to a change in collection methodology. Inert screen had been placed over the sample containers to prevent crayfish from importing gravel as had been experienced in the previous year's samples. In comparing 1994 analyses to previous years, slight variability can be seen in individual parameters. For example, iron continues to appear to decrease in upstream and downstream samples compared to previous years; the change does not necessarily indicate a trend. An important comparison is samples downstream of the mine to upstream of the mine. No significant increases of any constituent are seen in the upstream/downstream comparison, consistent with monitoring results in previous years. It can be concluded that no impact on Flambeau River sediments from mine activities has occurred.



4.2.2 FISH

Walleye are collected once per year during the annual low flow period. Samples are collected upstream and downstream of the mine. Metals are analyzed from samples of fish tissue, while length, sex and stomach contents of each fish are noted. In 1994, fish were collected on October 16 and 17 using a boat mounted with an electroshocker. Collection had originally been scheduled for September, however, significant flooding of the Flambeau River during September required rescheduling. Procedures described in the Updated Monitoring Plan (July 1991) and Revised Mining Permit Quality Assurance/Quality Control Document (August 1991) were followed.

General observations showed that species observed during the collection event were consistent with those collected in previous years. The stomach contents of the walleye collected were either empty or contained minnows which tend to be a fall diet. There were no significant differences in metal content of fish tissue sampled downstream of the mine compared to upstream of the mine. Mercury concentrations in fish tissues have decreased during 1994 at both the upstream and downstream locations. Appendix E contains more detailed information about the fish sampling. Fish sampling locations are shown in Figure 4-2.

FIGURE 4-2
Page 15

NOTE: SEE FIGURE NO. 4-1 FOR THE LOCATION OF WETLAND STAFF GAUGES WT-1, WT-3, WT-4 AND WT-5.



- LEGEND**
- SW-1 SAMPLING LOCATIONS FOR SURFACE WATER SAMPLES
 - S-1 SAMPLING LOCATION FOR SEDIMENTS
 - M-1 SAMPLING LOCATION FOR MACRO-INVERTEBRATES
 - F-1 SAMPLING LOCATION FOR FISH
 - ||||| HC-1 LOCATION FOR HABITAT CHARACTERISTICS OBSERVATIONS
 - ⊗ WT-2 WETLAND STAFF GAUGE

MAP SOURCE: U.S.G.S. LADYSMITH, WI. 15 MINUTE QUADRANGLE

FOTH & VAN DYKE
SCIENCE & ENVIRONMENTAL MANAGEMENT DIVISION
GREEN BAY, WISCONSIN

FLAMBEAU PROJECT
LADYSMITH, WISCONSIN

KENNECOTT
MINERALS
COMPANY
1215 MINERAL SQUARE
SALT LAKE CITY, UTAH

FIGURE NO. 4-2
CONSTRUCTION AND OPERATION
SURFACE WATER MONITORING
SITE LOCATIONS

MICROFILM	JOB
DRAWING NO.	REV.
DIVISION DRAWING NO.	
SCALE	

NO.	DATE	BY	DATE	BY	DATE
1	12/89	DHS			

TABLE 4-1
 FLAMBEAU RIVER SEDIMENT SAMPLING RESULTS
 DOWNSTREAM SAMPLING
 (S-2 & S-3)

Metals (ppm)	1989 Baseline ¹	1991 (S-2)	1992 (S-2)	1993 (S-2)	1993 (S-3)	1994 (S-3)
aluminum	NA	4000	12000	1500	4400	4000
arsenic	1.1	1.5	4.1	<0.55	0.71	<1.6
cadmium	<0.5	0.6	<1.4	<0.055	0.11	0.13
chromium	4.8	13.0	24.0	3.8	9.6	10.0
copper	2.6	7.2	24.0	2.1	6.7	7.1
iron	2200	16000	25000	3100	8200	7700
lead	<4.5	6.9	20.0	2.6	8.3	7.8
manganese	63	1600	570	610	830	860
mercury	<.01	0.1	<0.3	<0.06	<0.07	<0.03
nickel	NA	7.3	12.0	1.7	6.5	6.2
selenium	NA	0.4	<0.9	<0.3	<0.3	<1.6
silver	NA	<1.1	<2.6	0.09	0.58	<0.08
zinc	28.0	45.0	79.0	9.60	33.0	46.0
Other						
Total Solids (%)	69.0	76.8	35.0	32.0	56.0	NA
Total Volatile Solids (%)	NA	2.5	12.0	5.1	6.2	NA

NA = Not Analyzed
¹ Environmental Impact Report, March 3, 1989, p. 3.7-1.1

TABLE 4-2
FLAMBEAU RIVER SEDIMENT SAMPLING RESULTS
BLACKBERRY LANE
(S-1)

Metals (ppm)	1989	1991	1992	1993	1994
	Baseline ¹	1991	1992	1993	1994
aluminum	NA	3800	3300	4000	3900
arsenic	0.9	2.2	2.2	1.4	<4.2
cadmium	<0.5	<0.7	<0.6	<0.6	<0.42
chromium	5.5	11.0	10.0	11.0	10.0
copper	2.8	7.3	6.0	7.0	5.8
iron	3000	18000	16000	15000	11000
lead	<4.5	6.0	5.8	8.5	3.3
manganese	130	1900	1000	1300	1500
mercury	<.01	0.1	<0.1	<0.05	<0.04
nickel	NA	5.8	6.1	8.4	7.4
selenium	NA	0.4	<0.4	<0.3	4.2
silver	NA	<1.2	<1.1	0.06	<0.21
zinc	16	47.0	33.0	38.0	34.0
Other					
Total Solids (%)	85	73.0	78.6	79.2	NA
Total Volatile Solids (%)	NA	1.8	1.6	0.8	NA

NA = Not Analyzed
¹ Environmental Impact Report, March 3, 1989, p. 3.7-1.1

4.2.3 MACROINVERTEBRATES

Crayfish are collected at three sampling locations once per year for metal analyses. The sampling and analyses are conducted in accordance with the Updated Monitoring Plan and the Revised Mining Permit Quality Assurance/Quality Control Document (August 1991). Samples were collected on August 8, 1994. Whole bodies were used for analysis and the results represent a composite for all crayfish collected per site. The analytical data indicates that no relative difference in parameter concentrations when comparing upstream to downstream locations is evident.

Samples were collected on October 3 to identify macroinvertebrate fauna. The results show that the severe flooding of the Flambeau River during September and into October have likely had an impact upon the macroinvertebrate fauna. Macroinvertebrate samples collected above and below the mine site were significantly lower in diversity and abundance as compared to previous years. Macroinvertebrate sampling locations are shown on Figure 4-2.

Results for macroinvertebrate sampling are included in Appendix F.

4.2.4 SURFACE WATER QUALITY

Water samples are taken once per quarter from the Flambeau River at two monitoring locations. Samples are collected in accordance with procedures described in the Updated Monitoring Plan (July 1991) and the Revised Mine Permit Quality Assurance/Quality Control Document (August 1991). The sample identified as SW-1 is upstream of the mine site; SW-2 is downstream of the mine. Figure 4-2 shows the locations of the surface water sampling. Results of quarterly sampling have been submitted to WDNR on March 9, June 23, September 9 and December 21, 1994. Those submittals are incorporated by reference.

A summary of the 1994 surface water quality results are included on Table 4-3. The results from 1994 are consistent with data collected from the same locations in 1992-1993 and 1991 during baseline data collections. No significant difference in parameter concentrations is evident when comparing downstream water quality to upstream water quality, nor is there any statistically significant increasing or decreasing trend for any parameter. Trends of surface water quality results and statistical trend analysis are contained in Appendix C.

4.2.5 HABITAT CHARACTERISTICS

The annual habitat characterization along the eastern bank of the Flambeau River was conducted on August 8, 1994. The characterization followed procedures described in the Updated Monitoring Plan (July 1991) and the Revised Mining Quality Assurance/Quality Control Document (August 1991).

The Flambeau River substrate conditions were consistent with 1992 conditions. There was no sign of sedimentation or erosion associated with discharge from Outfall 001. Water-borne

TABLE 4-3
1994 QUARTERLY SURFACE WATER
QUALITY DATA SUMMARY

	SW-1				SW-2			
	1/94	4/94	7/94	10/94	1/94	4/94	7/94	10/94
aluminum (ug/l)	120	290	70	200	36	310	140	220
arsenic (ug/l)	<2	<2	<2	<2	<2	<2	<2	<2
beryllium (ug/l)	<1	<1	<1	<1	<1	<1	1.2	1.2
cadmium (ug/l)	<0.2	0.38	<0.2	<0.8	<0.2	<0.2	0.22	<0.08
chromium VI (ug/l)	<5	<5	<5	<1.5	<5	<5	<5	<1.5
chromium (ug/l)	<1	1.8	1.8	2.5	<1	1.9	2.3	3.7
copper (ug/l)	4.4	<2	2.7	2	<2	5.1	3.6	5.7
conductivity (field)	203	118	117	78	151	124	119	82
DO (mg/l)	11.9	5.8	8.5	10.1	11.6	6.6	8.8	9.3
hardness (mg/l)	64	43	48	36	60	40	48	38
lead (ug/l)	<1	10	2.5	1.1	<1	<1	1.4	1.5
mercury (ug/l)	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2	<0.2
nickel (ug/l)	<16	<16	<16	<16	<16	<16	<16	<16
pH (lab)	7.2	7.4	7.6	6.8	7.2	7.4	7.8	6.9
pH (field)	7.8	8.0	7.4	7.2	8.1	8.0	7.6	7.1
selenium (ug/l)	<2	<2	<2	<2	<2	<2	<2	<2
silver (ug/l)	<0.5	<0.5	<0.5	<2.5	<0.5	<0.5	<0.5	<2.5
sulfide (mg/l)			<2	<2			<2	<2
TDS (mg/l)	93	84	96	100	83	82	100	92
TSS (mg/l)	1.0	3.0	<1	8.0	<1	13	10	8
zinc (ug/l)	7.0	9.0	11	17	50	7.0	9.0	23.0

sediment had in the past been deposited on Outfall 001 as the river carried sediment up and onto the Outfall's riprap. Again during 1994, the only sediment noted at Outfall 001 was that which was due to river action.

Significant beaver activity was noted upstream from Outfall 002. Clusters of logs were located along the east bank which enhanced sedimentation. Sediment in excess of one foot had accumulated at each log cluster. The bank in this area is erodible and this characteristic continues past Outfall 001.

Immediately above Meadowbrook Creek, dozens of middens (shells of mussels) were observed in the shallow water. The area below Meadowbrook Creek where previously Elodea had been located, remained, though the area covered by Elodea seemed to be expanding downstream.

Additional detail including photographs is provided in Appendix G of this report.

4.2.6 WETLAND SURFACE FLOWS

Water levels in wetlands 1, 5C, 6C, 7 and 10A are measured monthly between March and December. Staff gauges designated WT 1 (Wetland 5C), WT 2 (Wetland 7), WT 3 (Wetland 6C), WT 4 (Wetland 10A) and WT 5 (Wetland 1) are measured. Figure 4-1 and Figure 4-2 show the staff gauge locations.

Measurements were provided to WDNR Mine Reclamation Unit on March 9, June 23, September 9 and December 21, 1994; those reports are incorporated by reference. Tables 4-4 through 4-8 summarize the wetland elevations for the five wetlands. Wetlands 5C, 6C, 7 and 10A showed similar readings to previous years. Wetland 1 experienced limited periods of standing water during 1994. During previous years fluctuating levels were experienced and had been predicted in the Wetland Inventory and Assessment (March 1989). Wetland 1 is supported chiefly by spring flow along its eastern edge. It had been previously predicted that dewatering the open pit would decrease or eliminate the groundwater discharge into this wetland. Upon realizing the pit drawdown had decreased the spring flow into Wetland 1, routine observations were made to assess any impacts upon Wetland 1.

Wetland 1 assessments were performed during May, July and early September 1994. Soil conditions and general state of existing vegetation indicated that there were no adverse effects to Wetland 1. These observations indicate that Wetland 1 is "perched" and not directly connected to the underlying groundwater table. The addition of mitigation water to Wetland 1 was not necessary during 1994. Wetland 1 will continue to be routinely monitored during 1995 with appropriate action taken if conditions warrant. Results of wetland monitoring efforts for 1994 are included in Appendix H.

TABLE 4-4

MONTHLY WETLAND STAFF GAUGE READING SUMMARY

	Staff Gauge Location/ Water Level (MSL)			
	WETLAND 5C (WT-1)			
	1991	1992	1993	1994
MAR	--	1140.62	NRT	NRT
APR	--	1140.47	1140.60	1140.73
MAY	1140.84	1140.21	1140.47	1140.22
JUN	1140.78	NSW	1140.34	1140.06
JUL	1140.05	NSW	NSW	NSW
AUG	NSW	NSW	1140.48	NSW
SEP	1140.21	1140.09	1140.51	1140.34
OCT	NSW	1140.68	1140.46	1140.28
NOV	NRT	NRT	NRT	NRT
DEC	NRT	NRT	NRT	NRT

NRT = No reading taken due to frozen conditions

NSW = No standing water

TABLE 4-5

MONTHLY WETLAND STAFF GAUGE READING SUMMARY

	Staff Gauge Location/ Water Level (MSL)			
	WETLAND 6C (WT-3)			
	1991	1992	1993	1994
MAR	--	1146.90	NRT	NRT
APR	--	1146.72	NRT	1146.89
MAY	1147.05	NSW	1146.78	NSW
JUN	NSW	NSW	1146.66	NSW
JUL	NSW	NSW	NSW	NSW
AUG	NSW	NSW	NSW	NSW
SEP	NSW	NSW	NSW	NSW
OCT	NSW	NSW	NSW	NSW
NOV	NRT	NRT	NRT	NRT
DEC	NRT	NRT	NRT	NRT

NRT = No reading taken due to frozen conditions
 NSW = No standing water

TABLE 4-6

MONTHLY WETLAND STAFF GAUGE READING SUMMARY

	Staff Gauge Location/ Water Level (MSL)			
	WETLAND 7 (WT-2)			
	1991	1992	1993	1994
MAR	--	1153.85	NRT	NRT
APR	--	1153.74	1153.82	1153.89
MAY	1154.00	1153.62	1153.57	1153.49
JUN	1153.58	1153.37	1153.64	1153.37
JUL	1153.51	1153.16	1153.46	1153.13
AUG	1153.15	1153.15	1153.56	NSW
SEP	1153.52	1153.06	1153.57	1153.48
OCT	1153.44	1153.16	1153.51	1153.49
NOV	NRT	NRT	NRT	NRT
DEC	NRT	NRT	NRT	NRT

NRT = No reading taken due to frozen conditions
 NSW = No standing water

TABLE 4-7

MONTHLY WETLAND STAFF GAUGE READING SUMMARY

	Staff Gauge Location/ Water Level (MSL)			
	WETLAND 10A			
	(WT-4)			
	1991	1992	1993	1994
MAR	--	1146.76	NRT	NRT
APR	--	1146.58	1146.74	1146.86
MAY	1146.81	1146.46	1146.57	1146.48
JUN	NSW	1146.16	1146.55	1146.39
JUL	1146.11	1145.91	1146.41	1146.18
AUG	NSW	1146.00	1146.55	1145.80
SEP	1146.26	1146.12	1146.57	1146.45
OCT	1146.10	1146.34	1146.53	1146.43
NOV	NRT	NRT	NRT	NRT
DEC	NRT	NRT	NRT	NRT

NRT = No reading taken due to frozen conditions
 NSW = No standing water

TABLE 4-8

MONTHLY WETLAND STAFF GAUGE READING SUMMARY

	Staff Gauge Location/ Water Level (MSL)			
	WETLAND 1 (WT-5)			
	1991	1992	1993	1994
MAR	--	1102.32	NRT	NRT
APR	--	1102.29	1102.49	1102.18
MAY	1102.35	1102.25	1102.03	NSW
JUN	1102.28	1102.26	NSW	NSW
JUL	1102.23	1101.90	NSW	NSW
AUG	NSW	1102.21	NSW	NSW
SEP	1102.33	1102.46	1101.92	NSW
OCT	1102.32	1102.37	NSW	NSW
NOV	NRT	NRT	NRT	NRT
DEC	NRT	NRT	NRT	NRT

NRT = No reading taken due to frozen conditions

NSW = No standing water

4.3 METEOROLOGY

As required in the Air Pollution Control Permit No. 89-DLJ-033, Condition 10, meteorological data is continuously collected from a meteorological station. Operation of the station is in accordance with the Updated Monitoring Plan (July 1991) and the Revised Quality Assurance/Quality Control Document (August 1991). On August 25, 1994 WDNR performed an audit upon the meteorological station. Wind speed and wind direction sensors were found to be operating within an acceptable range. Records of data at the meteorological station are maintained at the Flambeau Mine site and are available to WDNR as required by the Air Permit.

4.4 TOTAL SUSPENDED PARTICULATES (TSP)

Ambient air quality was monitored as required in the Mine Permit Condition 4-4. As described in the Updated Monitoring Plan (July 1991), TSP was measured every second day upon initiation of the operation phase of the Flambeau Mine during 1993. Flambeau's Mine Permit, Part 3, Condition 4(b) allows for the TSP sampling schedule to be reduced to no less than once every six days if after one year of operation there has been no exceedance of a TSP standard. Upon completion of one year of mine operation without a TSP exceedance, Flambeau requested from the WDNR a reduction of the TSP sampling frequency from every second day to every sixth day. In a letter dated August 11, 1994 the WDNR granted approval for the reduced schedule. Flambeau initiated the every sixth day TSP schedule on August 18, 1994.

There were no TSP measurements during 1994 which were greater than the ambient air quality standard for particulate matter which is 150 ug/m^3 . The highest reading of the four monitoring sites was attributed to construction involving reroofing the hospital at the North site. The second highest result at the North site was 72 ug/m^3 which is well below the ambient air quality standard for particulate matter. The highest result from the remaining three monitoring stations was 96 ug/m^3 which is also well below the required standard. The annual geometric mean of TSP measurements for air monitoring stations ranged from 16 ug/m^3 to 24 ug/m^3 .

TSP monitoring results were submitted to the WDNR Air Monitoring Section each month during 1994 as required in the Mine Permit Condition 4-9. The reports were submitted on the following dates: February 11, March 14, May 2, May 18, June 23, July 23, August 17, September 12, October 13, November 23 and December 24, 1994 and January 12, 1995. Copies of the reports are incorporated by reference.

Table 4-9 is a summary of the TSP monitoring results for 1994. Figures 4-3 to 4-6 present 1994 trends for TSP at the Flambeau air monitoring stations. Air monitoring station locations are shown on Figure 4-7.

TABLE 4-9

**FLAMBEAU MINING COMPANY
TSP DATA SUMMARY (ug/m3)**

Date	0001 North Site	0003 Southeast Site	0004 Northeast Site	0005 Northwest Site
1/2/94	10	1	10	9
1/4/94	11	15	20	8
1/6/94	7	7	8	8
1/8/94	14	9	7	6
1/10/94	18	23	22	22
1/12/94	21	31	32	29
1/14/94	9	16	11	5
1/16/94	11	13	11	11
1/18/94	8	13	7	8
1/20/94	29	23	24	22
1/22/94	17	19	19	15
1/24/94	15	19	17	10
1/26/94	9	13	12	18
1/28/94	12	13	11	8
1/30/94	11	10	8	3
2/1/94	28	NS	28	21
2/3/94	10	13	11	11
2/5/94	13	18	13	11
2/7/94	14	14	10	9
2/9/94	28	20	23	11
2/11/94	31	35	32	33
2/13/94	26	27	26	21
2/15/94	12	47	13	10
2/17/94	56	62	64	48
2/19/94	30	31	29	29
2/21/94	14	96	12	10
2/23/94	13	28	9	13
2/25/94	8	12	6	8
2/27/94	16	17	15	15
3/1/94	39	NS	42	37
3/3/94	44	47	44	44

TABLE 4-9 (CONT.)

Date	0001 North Site	0003 Southeast Site	0004 Northeast Site	0005 Northwest Site
3/5/94	27	29	30	23
3/7/94	21	58	47	15
3/9/94	18	NS	20	14
3/11/94	28	NS	40	36
3/13/94	18	NS	18	17
3/15/94	21	20	12	11
3/17/94	23	33	23	66
3/19/94	23	24	22	19
3/21/94	8	21	8	8
3/23/94	9	15	11	9
3/25/94	16	24	12	8
3/27/94	11	12	11	12
3/29/94	8	8	9	5
3/31/94	21	29	31	20
4/2/94	10	16	8	8
4/4/94	12	12	16	9
4/6/94	22	39	18	12
4/8/94	34	35	34	47
4/10/94	17	14	NS	11
4/12/94	24	21	24	25
4/14/94	25	26	27	21
4/16/94	12	22	13	11
4/18/94	35	NS	45	NS
4/20/94	19	35	18	16
4/22/94	26	37	36	25
4/24/94	45	44	51	42
4/26/94	22	26	21	21
4/28/94	10	12	7	3
4/30/94	14	12	13	10
5/2/94	24	27	27	18
5/4/94	42	42	58	33

TABLE 4-9 (CONT.)

Date	0001 North Site	0003 Southeast Site	0004 Northeast Site	0005 Northwest Site
5/6/94	13	13	15	10
5/8/94	34	39	44	34
5/10/94	37	36	37	31
5/12/94	22	35	24	16
5/14/94	39	38	36	35
5/16/94	11	19	16	14
5/18/94	40	47	50	36
5/20/94	62	63	75	64
5/22/94	29	30	30	27
5/24/94	33	50	36	29
5/26/94	22	23	23	18
5/28/94	51	51	56	52
5/30/94	42	NS	41	13
6/1/94	17	22	21	13
6/3/94	30	32	44	25
6/5/94	22	21	21	21
6/7/94	20	19	23	18
6/9/94	30	27	42	28
6/11/94	21	27	28	22
6/13/94	16	19	15	19
6/15/94	71	66	80	57
6/17/94	50	94	52	35
6/19/94	31	30	30	NS
6/21/94	20	34	30	17
6/23/94	37	41	40	NS
6/25/94	23	34	24	NS
6/27/94	27	31	26	NS
6/29/94	18	NS	18	17
7/1/94	20	44	20	NS
7/3/94	24	26	24	25
7/5/94	17	19	20	16

TABLE 4-9 (CONT.)

Date	0001 North Site	0003 Southeast Site	0004 Northeast Site	0005 Northwest Site
7/7/94	18	22	19	19
7/9/94	10	14	22	9
7/11/94	31	31	44	27
7/13/94	17	19	19	21
7/15/94	22	21	28	15
7/17/94	14	16	15	13
7/19/94	26	28	25	25
7/21/94	16	16	14	13
7/23/94	17	24	19	16
7/25/94	14	46	14	13
7/27/94	16	59	26	13
7/29/94	58	55	71	47
7/31/94	37	NS	36	34
8/2/94	41	42	48	35
8/4/94	16	30	20	13
8/6/94	24	23	22	18
8/8/94	8	24	9	5
8/10/94	16	17	18	20
8/12/94	30	23	49	18
8/18/94	33	36	53	NS
8/24/94	39	47	57	30
8/30/94	15	NS	18	16
9/5/94	12	17	13	11
9/11/94	41	43	44	41
9/17/94	16	18	15	13
9/23/94	26	31	29	23
9/29/94	18	19	21	12
10/5/94	143	27	32	20
10/11/94	NS	29	31	20
10/17/94	22	NS	23	22
10/23/94	7	12	7	6

TABLE 4-9 (CONT.)

Date	0001 North Site	0003 Southeast Site	0004 Northeast Site	0005 Northwest Site
10/29/94	20	24	21	18
11/4/94	11	12	13	8
11/10/94	31	35	33	22
11/16/94	19	21	21	17
11/22/94	NS	30	90	10
11/28/94	8	11	5	7
12/4/94	72	21	22	20
12/10/94	21	50	26	19
12/16/94	37	23	25	23
12/22/94	12	16	16	11
12/28/94	8	69	7	5

NS: No Sample

Figure 4-3

Flambeau Mining Co. TSP Data
Site 0001 - North Site




Figure 4-4

Flambeau Mining Co. TSP Data
Site 0003 - Southeast Site




Figure 4-5

Flambeau Mining Co. TSP Data
Site 0004 - Northeast Site






Figure 4-6

Flambeau Mining Co. TSP Data
Site 0005 - Northwest Site





NOTE: BASE MAP PREPARED FROM U.S.G.S. MAPS 7.5 MINUTE SERIES, LADYSMITH AND THORNAPPLE WISCONSIN QUADRANGLES

FOTH & VAN DYKE
 GEOSCIENCES & ENVIRONMENTAL MANAGEMENT DIVISION
 CREEK EAT, WISCONSIN

FLAMBEAU PROJECT
 LADYSMITH, WISCONSIN
 KENNECOTT MINERALS COMPANY
 Figure 4-7
 TSP AND METEOROLOGICAL SITES

WORKED	JOB
DRAWING NO.	REV.
DWYSON DRAWING NO.	

NO.	DATE	BY	DATE
1	12/12/89		

In addition to monitoring total suspended particulates, ambient air quality is monitored with respect to arsenic, beryllium, cadmium, chromium, mercury and nickel. Composites of the TSP filters collected over three month periods have been submitted for analyses as specified in Condition 4-4 of the Mine Permit.

Reports of the quarterly composites which were submitted to the WDNR Air Monitoring Section during 1994 are incorporated by reference and are summarized in Table 4-10. Analyses resulted in very low or non-detectable concentrations of these metals.

The Air Pollution Control Permit, Condition B.3. requires that source performance tests be conducted upon initiation of mine operation to document compliance with the visible emission limitations. Source performance tests which were conducted August 12-13, 1993 showed site operation to be well below the visual opacity limits of 10% and 20%. In a letter dated January 12, 1994 the WDNR granted a Release for Permanent Operation of the Flambeau Mine.

4.5 ASBESTIFORM FIBERS

The Mine Permit, in Condition 4-5, requires ambient air quality monitoring for asbestiform fibers. The asbestiform monitoring for the mining operations during 1994 was initiated on May 20. Sampling and analysis was conducted in accordance with the Revised Mining Permit Quality Assurance/Quality Control Document for Asbestiform Sampling (February 1993). Samples were collected one eight-hour day per month during the period May through September.

Results of sampling and analyses were submitted to WDNR Air Monitoring Section on June 21, July 7, August 9, September 19 and October 17, 1994. These reports are incorporated into this annual report by reference. No fibers were detected in any samples collected downwind from the Flambeau site.

Condition 4-5 of the Mine Permit allows for the cessation of asbestiform monitoring if during the first three years of active mining asbestiform fibers are not detected from the mining operations. Upon completion of the 1995 asbestiform monitoring schedule without detects for asbestiform fibers, Flambeau will provide notice to the WDNR that the requirement for asbestiform monitoring has been met and no further asbestiform monitoring will be performed.

4.6 OPERATIONAL MONITORING

The Mine Permit and Updated Monitoring Plan call for monitoring of operational activities. These include exfiltrate from the Type I stockpile, pit inflows, Type II stockpile leachate, equipment inspection and hydric soils monitoring. All samples were collected and analyzed in accordance with procedures in the Updated Monitoring Plan (July 1991) and Revised Mining Permit Quality Assurance/Quality Control Document (August 1991). Results of exfiltrate and leachate analyses have been submitted to the WDNR Mine Reclamation Unit on March 9, June 23, September 9, and December 21, 1994. These reports are incorporated by reference.

TABLE 4-10

QUARTERLY TSP FILTER METAL RESULTS SUMMARY (ug/m3)

	Arsenic	Beryllium	Cadmium	Chromium	Mercury	Nickel
<u>North Site</u>						
5/1/93-8/6/93	0.000471	<0.0000129	<0.0000774	<0.00888 ¹	<0.0000129	0.00108
8/7/93-11/3/93	0.000422	<0.0000113	<0.0000905	<0.00888 ¹	<0.0000188	0.00121
11/5/93-2/1/94	0.000641	<0.0000114	0.000211	<0.0126 ¹	0.0000151	0.00165
2/3/94-5/2/94	0.000538	<0.000011	0.000258	<0.0072 ¹	<0.0000101	0.000912
5/4/94-7/31/94	0.000521	<0.0000115	0.000157	<0.0486 ¹	<0.0000115	<0.0327 ¹
8/2/94-11/10/94	0.000335	0.000180	0.000232	<0.00625 ¹	<0.0000122	0.00149
<u>Southeast Site</u>						
5/1/93-8/6/93	0.000540	<0.0000141	<0.0000985	<0.00888 ¹	<0.0000141	0.00148
8/7/93-11/3/93	0.000491	<0.0000188	<0.0000707	<0.00888 ¹	0.0000180	0.000933
11/5/93-2/1/94	0.000489	<0.0000111	0.000223	<0.0126 ¹	0.0000285	0.00163
2/3/94-5/2/94	0.000713	<0.0000123	0.000241	0.00160	<0.0000123	0.00619
5/4/94-7/31/94	0.000567	<0.0000126	0.000123	<0.0486 ¹	<0.0000126	<0.0327 ¹
8/2/94-11/10/94	0.000429	<0.00000751	0.000161	<0.00625 ¹	0.0000168	0.00113

TABLE 4-10
(CONT'D)

	Arsenic	Beryllium	Cadmium	Chromium	Mercury	Nickel
<u>Northwest Site</u>						
5/1/93-8/6/93	0.000914	<0.0000127	<0.0000761	<0.00888 ¹	<0.0000127	0.00115
8/7/93-11/3/93	0.000433	<0.0000109	0.0000652	<0.00888 ¹	<0.0000109	0.00102
11/5/93-2/1/94	0.000569	<0.0000111	0.000172	<0.0126 ¹	0.0000147	0.00955
2/3/94-5/2/94	0.000465	<0.0000111	0.000246	<0.0072 ¹	<0.0000111	0.00110
5/4/94-7/31/94	0.00044	<0.0000119	0.000148	<0.0486 ¹	<0.0000119	<0.0327 ¹
8/2/94-11/10/94	0.000388	0.0000291	0.000218	<0.00625 ¹	0.0000224	0.000995
<u>Northeast Site</u>						
5/1/93-8/6/93	0.000402	<0.0000125	<0.0000751	<0.00888 ¹	<0.0000125	0.00100
8/7/93-11/3/93	0.000383	<0.0000108	0.0000759	<0.00888 ¹	0.0000132	0.000748
11/5/93-2/1/94	0.000553	<0.0000103	0.000188	<0.0126 ¹	0.0000164	0.00852
2/3/94-5/2/94	0.000548	<0.0000112	0.000264	<0.0072 ¹	<0.0000112	0.000974
5/4/94-7/31/94	0.00049	0.0000208	0.000148	<0.0486 ¹	0.0000131	0.0327
8/2/94-11/10/94	0.000328	<0.00000655	0.000164	<0.00625 ¹	<0.0000111	0.000866

¹ Chromium and nickel were detected in blank unexposed filters which resulted in an elevated detection limit

Monitoring of the Type I collection lysimeter was performed on a quarterly basis throughout 1994. The analysis of the exfiltrate is to characterize the liquid. The four samples collected during 1994 had pH values which were comparable to shallow groundwater samples. Sample comparison shows that chromium, copper and iron values remain within the range anticipated by Prediction of Chromium, Copper and Iron Concentration in Vadose Zone Water Reaching the Water Table Beneath the Unlined Type I Stockpile for the Kennecott Flambeau Project (July 1989). Manganese concentrations have shown a significant decrease since sampling was initiated in 1993. Flow rates remained relatively constant through 1994. Data is summarized in Table 4-11.

Condition 4 of the Groundwater Withdrawal Permit requires tabulation of monthly totals for precipitation, surface water run-on, groundwater inflow and dewatering pumping to allow an evaluation of the water handling balance within the pit. Estimates of groundwater inflow into the open pit are made by calculating flow based on the pumping rate from the pit. Adjustments to the flow rate have been made for precipitation, evaporation and surface flow into the pit. The flow rates are summarized in Table 4-12. Pit development is summarized in Table 4-13. For the period April to December, the estimated groundwater inflow was 78.8 MG in 1993, and 96.8 MG for all of 1994. The 1994 monthly average inflow of 8.1 MG was slightly lower than the 1993 monthly average of 8.8 MG.

Coupled with groundwater level monitoring as the pit has deepened, exposed rock has been periodically mapped to better define groundwater inflow occurrences and assess slope stability issues. In 1994, this wall mapping showed the presence of small rock parting related seeps at varying elevations on the west wall. Additional investigation and monitoring wells were installed to verify that pore pressures were within the design criteria defined to ensure wall stability. The investigations verified that wall pore pressures continue to remain within the defined criteria. Construction logs for those wells installed during 1994 are included in Appendix I.

The new west wall monitoring wells were in place prior to the extraordinary flood of September 1994. As a consequence of this additional monitoring being available, a very detailed and valuable record of major flood impacts upon the groundwater systems was obtained. The monitoring showed that the pressure increases that occurred during the flooding at no time threatened pit wall stability. The WWTP has sufficient capacity that it was able to treat, to required standards, in a short space of time, all of the flood induced increase in groundwater inflow and precipitation to the pit area.

Throughout 1995 additional information will continue to be gathered by pit mapping of inflows, the implementation of additional monitoring, and a continuing record of groundwater response through a full range of seasons.

Leachate from the Type II stockpile is treated within Flambeau's WWTP prior to discharge to the Flambeau River. The Type II leachate is collected on a quarterly basis and analyzed for quality. The 1994 fourth quarter sample shows an increase for all parameters including pH.

TABLE 4-11
TYPE I COLLECTION LYSIMETER MONITORING DATA
1994

PARAMETERS	UNIT	1Q JAN	2Q APR	3Q JUL	4Q OCT
Alkalinity	mg/l	94	80	92	150
Chromium (Dissolved)	ug/l	<1	<1	<1	1.2
Copper (Dissolved)	ug/l	<12	<12	<12	23
Flow Rate	gpd	307	339	256	280
Hardness	mg/l	150	120	120	150
Iron (Dissolved)	mg/l	0.110	0.017	0.052	0.240
Manganese (Dissolved)	mg/l	2200	920	73	340
pH, Field	s.u.	6.7	6.8	6.0	6.4
pH, Laboratory	s.u.	6.4	6.3	6.1	6.0
Solids (Dissolved)	mg/l	200	170	170	220
Specific Conductance	umho	311	288	302	351
Sulfate	mg/l	48.0	27.0	22	18

TABLE 4-12
PIT INFLOW SUMMARY
1994
(Million Gallons)

	1993	1994			
	Groundwater Inflow	Groundwater Inflow	Precipitation	Surface Water Run-on	Dewatering Pumping
January		7.71	1.06	0.00	7.71
February		6.23	0.54	1.33	7.56
March		7.41	0.71	1.24	8.66
April	15.7	5.39	4.19	1.62	7.01
May	8.7	6.58	1.73	0.62	7.20
June	7.9	6.92	5.30	1.71	8.63
July	7.2	7.95	6.77	2.68	10.63
August	10.0	9.54	3.42	1.12	10.65
September	6.7	11.32	10.68	4.77	16.09
October	7.2	10.39	3.57	1.26	11.65
November	8.4	8.45	3.62	0.75	9.20
December	7.0	8.89	0.75	0.76	9.65
Estimated Yearly Groundwater Inflow:	78.8	96.8			

**TABLE 4-13
PIT DEVELOPMENT SUMMARY**

Approximate Status of Pit Development During 1994														
Bench	Depth (ft)	Mined Area (acres)												
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	
1140	-40	4.5	4.5	4.5	4.5	5.0	5.0	5.0	5.0	5.1	5.4	5.4	5.4	5.4
1130	-30	10.2	10.2	10.2	10.2	12.6	13.7	13.7	13.7	14.8	16.3	16.3	16.4	17.0
1120	-20	15.5	15.5	15.5	15.5	16.3	18.5	19.4	19.4	21.1	22.1	22.1	22.4	23.7
1110	-10	18.3	18.3	18.3	18.3	18.3	19.8	21.4	21.4	22.5	22.5	22.5	22.6	25.8
1100	0	18.1	18.1	18.1	18.1	18.1	18.7	19.7	19.7	22.5	22.9	22.9	22.9	26.5
1090	10	15.9	15.9	15.9	15.9	15.9	16.1	16.1	16.1	18.3	18.8	18.8	18.8	22.9
1080	20	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	16.7	16.9	16.9	16.9	20.9
1070	30	11.0	11.1	11.3	11.3	11.4	11.4	11.4	11.4	11.4	11.4	11.4	11.4	12.1
1060	40	7.7	9.2	9.8	9.8	9.8	9.8	9.9	9.9	9.9	9.9	9.9	9.9	9.9
1050	50	1.7	1.9	5.2	8.0	9.0	9.0	9.1	9.1	9.1	9.1	9.1	9.1	9.1
1040	60	0.1	0.2	1.4	4.5	5.5	6.4	7.3	7.7	7.7	7.8	7.8	7.8	7.8
1030	70	0.0	0.0	0.2	0.2	2.0	3.0	3.8	5.2	5.8	6.6	6.6	6.6	6.6
1020	80	0.0	0.0	0.0	0.0	0.0	0.0	0.5	1.4	1.4	3.9	3.9	5.1	5.1
1010	90	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.1	0.1	1.0	1.0	1.0	2.5
1000	100	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.1	0.1	0.1	0.1
990	110	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.1	0.1	0.1	0.1
980	120	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
970	130	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
960	140	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
950	150	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
940	160	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
930	170	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
920	180	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
910	190	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
900	200	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

In spite of this increase, all four samples collected in 1994 show the leachate characteristics to remain below the values predicted for leachate from rock chips (4.8% sulfur) during the Wet/Dry Leaching Study (Kennecott Environmental Report, April 1989) with the exception of manganese and sulfate which are within the predicted range. The pH of the leachate remained relatively neutral during 1994. Data is summarized in Table 4-14.

An annual camera inspection of outfall pipes between the Type II stockpile and the surge pond is required by Condition 2-14 of the Mine Permit. The 1994 inspection was performed on August 22 and September 10. The pipe integrity was verified. A report of the inspection was submitted to the WDNR Mine Reclamation Unit on September 16, 1994 and is incorporated by reference.

While performing the camera inspection on August 22, the entrance manholes, access manholes, outlet, and the geomembrane-covered seam in the pipe junction prior to the outlet were also inspected to verify integrity. All were found to require no maintenance.

Annual inspection of the Type II leachate collection system was conducted October 13. The leachate lines were flushed by draining approximately 3500 gallons of treated water into each cleanout riser along with a buoyant indicator object. The water flow along with the buoyant object were observed in the collection manhole (MH-1) to verify that the leachate lines were free of obstruction and pipe integrity was maintained. The assessment verified that cleaning of the pipes was not necessary.

Routine maintenance inspections of the HDPE lined areas were conducted periodically during 1994. Repairs were made in the surge pond and runoff pond liner and Type II/Phase I stockpile liner as follow up to inspections. The WDNR was notified of the minor liner damage upon discovery and informed of the planned repairs. Reports of the repairs were prepared by STS Consultants Ltd. and Cooper Engineering; these reports are included in Appendix J.

Inspections of the sideslopes of the surge pond and runoff pond and the scuff strip below the outlet of the 36" pipe outlet in the surge pond were conducted by STS on June 23, 1994. No additional sloughing or deformation of the side slopes has occurred in the surge pond or runoff pond with the exception of a limited area under the 32-inch pipe on the west side of the runoff pond. However, there was no visible stress on the liner which would warrant action. Monitoring of pond sideslopes including the area under the runoff pond 32-inch pipe continues on a routine basis. The scuff strip within the surge pond shows no signs of movement or displacement from its original installed location. A small tear in the scuff strip was repaired. Preventive maintenance included placement of scuff strips below the corrugated HDPE pipes within the surge pond and runoff pond. Liner repairs and placement of additional scuff strips are documented in Appendix I. Reports of the STS inspection are included in Appendix B.

Hydric soils were maintained in a wet condition, as specified in the Vegetative Aquascape Plan (May 1991) and the Topsoil and Hydric Soils Management Plan (May 1991). A moisture measurement taken during 1994 showed that the hydric soils moisture content is 27%.

TABLE 4-14
 TYPE II LEACHATE MONITORING DATA
 1994

PARAMETERS	UNIT	1Q JAN	2Q APR	3Q JUL	4Q OCT
Alkalinity	mg/l	28	16	21	19
Conductivity	umho	134	124	304	539
Copper (Dissolved)	ug/l	14	22	32	2100
Hardness	mg/l	51	40	120	270
Iron (Dissolved)	mg/l	<0.015	<0.015	0.074	<0.015
Manganese (Dissolved)	mg/l	10	130	450	770
pH, Field	s.u.	7.2	8.0	5.9	6.9
pH, Laboratory	s.u.	6.8	7.0	6.4	8.7
Solids (Dissolved)	mg/l	88	62	190	490
Sulfate	mg/l	16	20	88	220

REFERENCES

1994 Annual Reclamation Report	November 1994
Air Pollution Control Permit	January 1991
Construction Documentation Report Type II Stockpile Phase 2 Construction	October 1994
Environmental Impact Report for Kennecott Flambeau Project	March 1989
Groundwater Model for the Kennecott Flambeau Project	July 1989
Groundwater Withdrawal Permit	January 1991
Local Agreement	August 1988
Mining Permit	January 1991
Operational Phase and Long Term Care Quality Assurance Plan	November 1993
Prediction of Chromium, Copper and Iron Concentration in Vadose Zone Water Reaching the Water Table Beneath the Unlined Type I Stockpile for the Kennecott Flambeau Project	July 1989
Revised Mining Permit Quality Assurance/Quality Control Plan	August 1991
Revised Mining Permit Quality Assurance/Quality Control Document for Asbestiform Sampling	February 1993
Topsoil and Hydric Soils Management Plan	May 1991
Updated Monitoring Plan	July 1991
Vegetative Aquascape Plan	May 1991
Wetland Inventory and Assessment	March 1989

SUBMITTALS

**WDNR
SUBMITTEE**

DATE

DOCUMENT

Section 2.0 Operating Activities

Construction Documentation Report Type II Site Phase 2 Construction	October 1994	Larry Lynch ¹
Preconstruction Report Type II Stockpile, Phase 2	May 1994	Larry Lynch ¹
Phase 2, Type II Stockpile Construction Status Report	July-September 1994	Larry Lynch ¹
Toxicity Reduction Evaluation Reports	Jan, Mar, Jun, Aug, Sept & Dec 1994	Tom Bauman ²
Mining Permit Modification Request-Production Increase	January 1994	Larry Lynch ¹
Flambeau Project-Modification to the Mining Permit	August 1994	Larry Lynch ¹
Toxic & Hazardous Spill Report	Jun & Dec 1994	Jerry Carow ³
Drillhole Abandonment Reports	Throughout 1994	Ken Markart ¹
Notice of Intent to Drill	Jan & Oct 1994	Larry Lynch ¹
Section 3.0 Reclamation Activities		
1994 Reclamation Annual Report	November 1994	Larry Lynch ¹
List of 1994 Reclamation Activities	January 1994	Larry Lynch ¹
Environmental Monitoring Ground Water Quality Results	Quarterly 1994	Larry Lynch ¹
Air Monitoring Results (TSP)	Monthly 1994	Steve Schuenemann ⁴

SUBMITTALS (CONT'D)

				WDNR SUBMITTEE
DOCUMENT	DATE		DATE	
Air Monitoring Project-STP Filer Metal Analytical Results	Apr, May, Jul, Sept 1994			Steve Schuenemann ⁴
Asbestiform Air Monitoring Results	Jan 1995			
1994 Camera Inspection	May-Sept 1994			Steve Schuenemann ⁴
1994 Leachate Line Assessment	September 1994			Larry Lynch ¹
	October 1994			Larry Lynch ¹
1 Mine Reclamation Unit Larry Lynch Ken Markart				
2 Bureau of Wastewater Management Tom Bauman				
3 WDNR Ladysmith Ranger Station Jerry Carow				
4 Air Monitoring Section Steve Schuenemann				

Appendix A

List of Deviations

**LIST OF MODIFICATIONS & DEVIATIONS
FROM APPROVED MINING PERMIT PLAN
(PER CONDITION 2-4)**

Permit/Application	Section	Modification or Deviation	Method	Authorization	
				Person	Date
Mine Permit	2-2	Modification to increase production to 450,000 tons ore per year.	Approval letter	Paul Didier	8/17/94
002 Outfall Plans & Specifications	2.2.5	Buried 12 inch diameter HDPE pipe replaces open 002 discharge channel.	Planned changes submitted in 1994 Annual Reclamation Report		
Mining Permit Application	4.7.4.5	Move security fence on west wall west approximately 10 feet.	Verbal	Larry Lynch	Fall 94
Flambeau Project Drawings	210-C-002 210-C-004	Ditch cut between haul road and topsoil stockpile to divert uncontaminated/off site water to Stream A.	Verbal	Larry Lynch	Spring 94
Final Engineering Report for Wastewater Treatment Facilities	6.2.3.2	Sulfide precipitation process altered to include citric acid for pH adjustment.	Conditional Approval Letter	Tom Bauman	Sept 94

Appendix B

Surge Pond/Runoff Pond Side Slope Evaluation



July 13, 1994

Ms. Jana E. Murphy
Supervisor of Environmental Affairs
Flambeau Mining Company
N4100 Highway 27
Ladysmith, Wisconsin 54848

Re: Surge and Runoff Ponds Observations, Type II Stockpile (Phase 1), Flambeau Mine,
Ladysmith, Wisconsin -- STS Project No. 20961XF

Dear Ms. Murphy:

As you requested, STS Consultants, Ltd., (STS) was at the above referenced site on June 23, 1994, to document the following as required by the Wisconsin Department of Natural Resources conditional approval of the lined facilities:

- observation of the surge pond and runoff pond sideslopes for sign of washout or deformation;
- observation of the 36-inch diameter drain from the Type II stockpile, the entrance manhole, access manholes, outlet, and the geomembrane-covered seam in the pipe junction prior to the outlet. We understand that Flambeau Mining personnel will perform the visual review of the entrance manhole and the access manholes;
- observation of the scuff strip below the outlet of the 36-inch diameter pipe outlet in the surge pond;

The sideslopes of the surge pond and runoff pond did not show any sign of washout or deformation with the exception of the soils under the 32-inch diameter pipe on the west side of the runoff pond which have sloughed down slope and created a void in the area immediately below the pipe. However, at low water level, no visible stress on the geomembrane liner was observed at this time. STS recommends continued monitoring of this area to observe if any changes of stress on the liner occur.

The weld collar for the 36-inch diameter discharge line in the surge pond was observed to have curled and induced tension on the overlying geomembrane liner. Additionally, the liner had broken away from the weld collar for a length of approximately 9 inches. Refer to STS' July 12, 1994, report regarding repairs performed in this area.

STS Consultants Ltd.
Consulting Engineers

1035 Kepler Drive
Green Bay, Wisconsin 54311
414.468.1978/Fax 414.468.3312



Flambeau Mining Company
STS Project No. 20961XF
July 13, 1994
Page 2

The geomembrane patch in the pipe junction prior to the outlet appeared to be in good condition.

The scuff sheet below the 36-inch diameter pipe outlet in the surge pond appeared to be in good condition with the exception of a small tear in the sheet near the high water mark. The underlying geomembrane liner did not appear to have been damaged. The tear may have been caused by ice formation inducing stress on the scuff sheet at the heat bond. STS recommends continuous extrusion welding of the scuff sheet to the liner to eliminate the effect of ice formation.

Additionally, STS recommends placement of scuff sheets beneath the corrugated pipes in the surge pond to minimize potential damage to the geomembrane liner.

Attached to this correspondence are copies of the STS technician's field reports. If you have any questions or comment, please contact us.

Sincerely,

STS CONSULTANTS LTD.

A handwritten signature in black ink, appearing to read 'Michael J. Pretti'.

Michael J. Pretti, P.E.

Project Engineer

A handwritten signature in black ink, appearing to read 'Dean A. Sylla'.

Dean A. Sylla, P.E.

Principal

MJP/lmh

Enclosure:

June 23, 1994, Field Technician Report

STS Construction Technology Group Field Report

~~Page~~ 1 of 3



The responsibilities and authority of STS and STS' Field Personnel include neither the responsibilities nor the authority of the "Competent Person" for the Project Site as defined by OSHA Regulations: 29 CFR 1926 Subpart P.

Project FLAMBEAU MINING COMPANY - SURGE POND. Project No. _____
 Location LADYSMITH, WI Day/Date Tuesday, June 23, 1994
 Contractor GSI Weather/Temp. Cloudy, 74°
 Client FMC
(1 of 3 reports for 6.23)

Project Competent Person per 29 CFR Part 1926 (Subpart P)

NAME: _____

FIRM: _____

FIRM ADDRESS: _____

PHONE: _____

Present on Site YES NO

Equipment Rental	-	Arrive Job	11:00 12:30	TOTAL CHARGEABLE HOURS 4 HOUR MINIMUM 9.0
Tolls \$		Depart Job	12:00 3:30	
Parking \$		Total Hours on Job	9.0	
Mileage	210	Travel Time	4.5	
Project Preparation Time			.5	

Summary of Technical and/or Engineering Services Performed, including Field Test Data. Locations, Elevations and Depth are Estimated.

I met with JANA MURPHY & VON SHANKS OF FMC UPON ARRIVAL. WE WENT TO THE SURGE POND FACILITY TO OBSERVE THE EXTENT OF THE LINER DAMAGE. COOPER ENGINEERING & FMC EMPLOYEES WERE REPAIRING THE UNSUPPORTED AREAS AROUND THE PIPE TO SUPPORT THE LINER FOR REPAIR. THE LOCATION IS THE NORTH SLOPE, WEST PORTION, IN PANEL 4B, 19' SOUTH OF THE ANCHOR TRENCH. THE LINER HAS BROKEN AWAY FROM THE WELD ON THE PIPE COLLAR. COOPER ENG. CUT A HOLE BELOW THE PIPE OUTLET TO FACILITATE BACKFILLING THE UNSUPPORTED AREA. COOPER ENG. USED A ^{DRY} SAND-BENTONITE MIXTURE FOR BACKFILLING THE UNSUPPORTED AREA. SEE COOPER REPORT FOR SOILS DETAILS. ALSO, AT THE 36" OUTLET, A HARD SPOT IN THE LINER WAS OBSERVED BY COOPER & CUT OPEN BY COOPER TO FIND THE WELD COLLAR UNDER THE LINER HAD CURLED & TENSIONED THE LINER. ALSO, THE LINER HAD BROKEN AWAY (LENGTH 9") FROM THE WELD COLLAR. (CONT. PAGE 2)

Field Test Data is Estimated Pending Final Laboratory Test Results. Site Sketch: Indicate North

Representative Jana E. Murphy
 Position Env. Supervisor
 Company Flambeau Mining Co.

By MJ Moroni
 Title Sr. ENGR. TECH.
 STS Consultants, Ltd.

STS Construction Technology Group Field Report

PAGE 2 of 2



The responsibilities and authority of STS and STS' Field Personnel include neither the responsibilities nor the authority of the "Competent Person" for the Project Site as defined by OSHA Regulations: 29 CFR 1926 Subpart P.

Project Flambeau Mining Co. Project No. _____
 Day/Date Tuesday, June 23, 1994
 Location _____ Weather/Temp. _____
 Contractor _____ Client _____

Project Competent Person per 29 CFR Part 1926 (Subpart P)

NAME: _____
 FIRM: _____
 FIRM ADDRESS: _____
 PHONE: _____
 Present on Site YES NO

Equipment Rental _____	Arrive Job _____	TOTAL CHARGEABLE HOURS 4 HOUR MINIMUM SEE PAGE 1
Tolls \$ _____	Depart Job _____	
Parking \$ _____	Total Hours on Job _____	
Mileage _____	Travel Time _____	
Project Preparation Time _____		

Summary of Technical and/or Engineering Services Performed, including Field Test Data. Locations, Elevations and Depth are Estimated.

A DEEP SLEATCH WAS ALSO OBSERVED IN PANEL 49, 3' SOUTH OF THE ANCHOR TRENCH | 5' EAST OF SEAM 45. OTHER MINOR SURFACE SCRATCHES ARE NOTED IN THIS AREA, WHICH ADJACENT TO THE ACCESS GATE FOR THE POND. THE SLEATCH WAS REPAIRED BY GSI BY WELDING A PATCH OVER THE AREA.

GSI ALSO REPAIR THE EARLIER MENTIONED DAMAGE AREAS BY WELDING PATCHES OVER THE CUTS AND GRINDING & REWELDING THE LINERS TO THE PIPE COLLARS. SEE TRIAL WELD FORM & REPAIR DATA FORM FOR SPECIFIC INFORMATION ON THE REPAIRS. GSI & VACUUM TESTED THE PATCHES | SPARK TESTED THE PIPE CONNECTIONS | FOUND NO LEAKS.

I ALSO OBSERVED THE PATCH IN THE 36" PIPE | IT APPEARED TO BE IN GOOD CONDITION.

THE SOLE CONDITION BENEATH THE PIPES DOES NOT SHOW ANY SLOUGHING OF SOILS, EXCEPT AT THE PIPE OUTFLOW AREA & REPAIRED TODAY.

Field Test Data is Estimated
 Pending Final Laboratory Test Results.

Site Sketch: Indicate North (CONT. PAGE 3).

Representative _____
 Position _____
 Company _____

By MJ Maroni
 Title Sr. Eng. Tech.
 STS Consultants, Ltd.

STS Construction Technology Group Field Report

PAGE 3 of 3



The responsibilities and authority of STS and STS' Field Personnel include neither the responsibilities nor the authority of the "Competent Person" for the Project Site as defined by OSHA Regulations: 29 CFR 1926 Subpart P.

Project FLAMBEAU MINING CO - SURGE POND. Project No. _____
 Location _____ Day/Date THURSDAY, JUNE 23, 1994.
 Contractor _____ Weather/Temp. _____
 Client _____

Project Competent Person per 29 CFR Part 1926 (Subpart P)

NAME: _____
 FIRM: _____
 FIRM ADDRESS: _____
 PHONE: _____
 Present on Site YES NO

Equipment Rental _____	Arrive Job _____	TOTAL CHARGEABLE HOURS 4 HOUR MINIMUM
Tolls \$ _____	Depart Job _____	
Parking \$ _____	Total Hours on Job _____	
Mileage _____	Travel Time _____	
Project Preparation Time _____		SEE PAGE 1

Summary of Technical and/or Engineering Services Performed, including Field Test Data. Locations, Elevations and Depth are Estimated.

THE SCUFF SHEET BELOW THE 36" PIPE IS IN GOOD CONDITION. HOWEVER, I DID NOTICE A SMALL TEAR IN THE SCUFF SHEET NEAR THE HIGH WATER MARK. THE LINER ITSELF IS NOT DAMAGED. THE TEAR QUITE POSSIBLY COULD HAVE BEEN CAUSED BY ICE ACTION ONE THE WINTER. IT WOULD BE A GOOD IDEA TO PLACE SCUFF STRIPS UNDER THE CORRUGATED PIPES THAT ARE LAYING ON THE LINER. SOME MINOR SCRATCH WAS OBSERVED IN THESE AREAS, AND A SCUFF STRIP WOULD PREVENT ANY SCRATCHING DAMAGE TO THE LINER.

THE 60 mil HDPE MATERIAL & EXTRUSION ROD WAS SUPPLIED BY FLAMBEAU MINING FOR REPAIRS MADE. MATERIAL CERTS. AVAILABLE FROM FMC. MATERIAL WAS CLEAN & DRY. ITS IS MATERIAL LEFT OVER FROM PREVIOUS LINER CONSTRUCTION.

Field Test Data is Estimated Pending Final Laboratory Test Results.

Site Sketch: Indicate North

Representative _____
 Position _____
 Company _____

By [Signature]
 Title SR. ENGR. TECH.
 STS Consultants, Ltd.

STS Construction Technology Group Field Report



NOTE: The responsibilities and authority of STS and STS' Field Personnel include neither the responsibilities nor the authority of the "Competent Person" for the Project Site as defined by OSHA Regulations: 29 CFR 1926 Subpart P.

Project Flambeau Mining Company - Runoff Pond. Project No. _____
 Location Ladysmith, WI Day/Date Thursday, June 23, 1994
 Contractor GSI Weather/Temp. Cloudy, 74°
 Client FMC.

Project Competent Person per 29 CFR Part 1926 (Subpart P)
NAME: _____
FIRM: _____
FIRM ADDRESS: _____
PHONE: _____
Present on Site <input type="checkbox"/> YES <input type="checkbox"/> NO

Equipment Rental _____	Arrive Job <u>12:00</u> <u>4:00</u>	TOTAL CHARGEABLE HOURS 4 HOUR MINIMUM <u>1.5</u>
Tolls \$ _____	Depart Job <u>12:30</u> <u>5:00</u>	
Parking \$ _____	Total Hours on Job <u>1.5</u>	
Mileage _____	Travel Time _____	
Project Preparation Time _____	_____	

Summary of Technical and/or Engineering Services Performed, including Field Test Data. Locations, Elevations and Depth are Estimated.

I MADE AN OBSERVATION TOUR OF THE RUN OFF POND TO OBSERVE THE PERFORMANCE OF THE LINER.

I FOUND A PUNCTURE IN THE LINER & A ^{SMALL} CREASE IN THE LINER IN THE SOUTH WEST CORNER. (P. 339)
 GSI PATCHED BOTH OF THESE LOCATIONS WITH 60 mil HDPE & EXTRUSION ROD SUPPLIED BY FLAMBEAU MINING. SER TRIAL WELD LOG & REPAIR SUMMARY FOR SPECIFIC WELDING DATA. GSI VACUUM-TESTED THE REPAIRS & FOUND NO LEAKS.

I NOTICED THAT THE SOILS UNDER THE 32" PIPE ON THE WEST SIDE OF THE POND HAVE SLOUGHED DOWN & CREATED A VOID IN THE AREA IMMEDIATELY BELOW THE PIPE. HOWEVER, AT LOW WATER, THERE WAS NO VISIBLE STRESS ON THE LINER AT THIS TIME.

ALSO, SCUFF STRIPS ARE RECOMMENDED UNDER EACH OF THE CORRUGATED PIPES TO PREVENT SCRATCHING THE LINER. SOME MINOR SCRATCHING IS EVIDENT AT EACH PIPE LOCATION.

Field Test Data is Estimated
 Pending Final Laboratory Test Results.

Site Sketch: Indicate North

Representative Jana E. Murphy
 Position Env. Supervisor
 Company Flambeau Mining Co.

By M. J. Moran
 Title Sr. Engr. Tech.
 STS Consultants, Ltd.

Appendix C

Groundwater Quality & Elevation

Surface Water Quality

Trends

Foth & Van Dyke Memorandum

January 16, 1995

TO: Jana Murphy, Flambeau Mining Company

CC: Jim Hutchison, Foth & Van Dyke
Jerry Sevick, Foth & Van Dyke

FR: Steve Lehrke, Foth & Van Dyke SL

RE: Flambeau Mining Company - 1994 Annual Report

Groundwater quality results associated with samples collected between July of 1991 and October of 1994 are listed in Table 1. Surface water quality results collected between July of 1991 and October of 1994 are listed in Table 2. The trends of the groundwater and surface water quality results are illustrated graphically in Attachments 1 and 2, respectively.

The groundwater concentration graphs (Attachment 1) indicate that, in general, very few overall trends are occurring in the groundwater quality. However, several isolated trends in the data can be seen. Alkalinity in MW-1000P has been following a decreasing trend. The October 1994 result of copper in MW-1000P was somewhat higher than past results. Iron in MW-1000P and MW-1005P dropped appreciably from 1991 to 1993, and has been holding steady since. Iron in MW-1004P had a significant reduction in concentrations between January and April of 1993. Iron in MW-1005 has been following a generally increasing trend.

Similar to iron in MW-1004P, manganese also had a significant reduction in concentrations between January and April of 1993. Somewhat higher than normal levels of manganese were observed in MW-1005P during January and October 1994. Manganese in MW-1010P has had a generally decreasing trend since 1991. Sulfate in MW-1010P had a decreasing trend from January of 1993 to January of 1994, but has been holding steady since.

In addition to presenting the trends graphically, a statistical trend test was performed on the results for each compound within each well. The nonparametric Mann-Kendall test for trend was used. This test, applied to the data, indicates whether a general overall increasing or decreasing trend between July of 1991 and October of 1994 is present. Since many tests were performed (one for each compound and well) the type I error rate, or false positive rate, was set to 0.01. The procedure for the Mann-Kendall test for trend is given in Gilbert (1987).

Summary statistics for each compound and well, along with the trend analysis results for groundwater are given in Table 1. The tests confirmed the above mentioned decreasing trends of alkalinity and iron in MW-1000P and manganese in MW-1010P, and the above mentioned increasing trends of copper in MW-1000P and iron in MW-1005. No other groundwater trends were found to be statistically significant.

Historical trend plots of groundwater elevations are also presented in Attachment 1. The groundwater elevation in many of the monitoring wells began to decline in late 1992, and continued to decline through 1993. These wells include MW-1000P, MW-1001, MW-1001G, MW-1001P, MW-1003, MW-1003P, MW-1004P, MW-1004S, MW-1010P, OW-7, OW-39, OW-42, PZ-R1, PZ-S3 and ST-9-23. During 1994, however, the declining trend of groundwater elevations in most of these wells began to slow, and elevations remained somewhat consistent. The only well which continues to show the same rate of decrease is PZ-R1.

The trend graphs of the surface water quality results (Attachment 2) indicate no general increasing or decreasing trends between July of 1991 and October of 1994. A statistical trend analysis using the Mann-Kendall test was also performed for surface water, and the results are shown in Table 2. No compounds measured at either of the two surface water sampling locations were determined to have a statistically increasing or decreasing trend.

In summary, both the trend graphs and the statistical trend analysis indicate no overall trends between July 1991 and October 1994 for surface water, and only isolated occurrences of trends over this time period for groundwater. Of the trends present in the groundwater data, both increasing and decreasing trends are represented.

Reference

Gilbert, Richard O. (1987) *Statistical Methods for Environmental Pollution Monitoring*. Van Nostrand Reinhold. New York, NY.

SGL:lmc

Groundwater Quality Results, Summary Statistics and Trend Analysis
July 1991 Through October 1994

Table 1

Well	Parameter	Units	Jul-91	Oct-91	Jan-92	Apr-92	Jul-92	Oct-92	Jan-93	Apr-93	Jul-93	Oct-93	Jan-94	Apr-94	Jul-94	Oct-94
MW-1000P	Alkalinity	mg/l	65	90	88	84	81	95	84	82	82	62	43	44	39	34
MW-1000P	Copper	mg/l	< 0.014	< 0.014	< 0.014	< 0.014	0.014	< 0.014	< 0.014	0.02	0.016	0.013	0.022	0.023	0.017	0.058
MW-1000P	Hardness	mg/l	84	110	110	88	120	100	88	90	86	120	54	54	49	36
MW-1000P	Iron	mg/l	0.65	0.84	1.7	1.3	0.47	0.8	0.15	0.27	0.061	0.032	< 0.015	0.021	0.026	0.047
MW-1000P	Manganese	mg/l	0.85	0.88	0.82	0.83	0.73	0.78	0.71	0.94	0.73	0.91	0.34	0.5	0.42	0.36
MW-1000P	Sulfate	mg/l	< 10	< 10	11	14	12	12	< 10	12	15	12	12	12	11	17
MW-1000P	TDS	mg/l	190	160	120	120	140	160	100	130	140	110	70	95	90	120
MW-1000P	pH(Field)	S.U.	8.39	7.41	5.75	6.91	6.84	6.9	6.22	6.24	6.6	7.03	6.9	7.7	7.5	7.2
MW-1002	Alkalinity	mg/l	50	49	47	49	41	53	53	66	42	42	39	35	31	38
MW-1002	Copper	mg/l	< 0.014	< 0.014	< 0.014	< 0.014	0.014	< 0.014	< 0.014	< 0.01	< 0.012	< 0.012	< 0.012	< 0.012	< 0.012	< 0.0016
MW-1002	Hardness	mg/l	60	60	67	48	120	82	66	90	52	52	50	45	44	46
MW-1002	Iron	mg/l	0.99	< 0.055	< 0.055	< 0.055	< 0.055	< 0.055	0.059	< 0.01	0.034	< 0.015	< 0.015	< 0.015	< 0.015	0.0056
MW-1002	Manganese	mg/l	0.0051	< 0.004	< 0.004	< 0.004	0.004	0.015	0.0047	< 0.004	< 0.004	< 0.004	< 0.004	< 0.004	< 0.004	< 0.00047
MW-1002	Sulfate	mg/l	< 10	< 10	11	11	10	11	< 10	9	10	6	7	7	6.6	6.1
MW-1002	TDS	mg/l	160	170	100	85	87	130	90	120	100	78	82	86	94	87
MW-1002	pH(Field)	S.U.	8.33	6.78	6.88	6.05	5.61	6.94	6.96	6.33	6.8	7.52	7.5	7.5	7	7
MW-1002G	Alkalinity	mg/l	86	88	80	84	79	85	75	44	64	82	94	92	92	88
MW-1002G	Copper	mg/l	< 0.014	< 0.014	< 0.014	< 0.014	0.014	< 0.014	< 0.014	< 0.01	< 0.012	< 0.012	< 0.012	< 0.012	< 0.012	< 0.0016
MW-1002G	Hardness	mg/l	100	120	110	110	160	130	94	76	80	110	120	120	120	110
MW-1002G	Iron	mg/l	< 0.055	< 0.055	< 0.055	< 0.055	< 0.055	< 0.055	< 0.055	< 0.01	< 0.015	< 0.015	< 0.015	< 0.015	< 0.015	0.0054
MW-1002G	Manganese	mg/l	0.0054	< 0.004	< 0.004	< 0.004	0.004	< 0.004	0.004	< 0.004	< 0.004	< 0.004	< 0.004	< 0.004	< 0.004	< 0.00047
MW-1002G	Sulfate	mg/l	< 10	10	11	14	11	11	12	8	11	11	14	12	12	14
MW-1002G	TDS	mg/l	240	280	140	150	150	180	98	74	140	190	82	170	170	200
MW-1002G	pH(Field)	S.U.	7.56	6.98	6.93	6.25	6.02	6.94	7.14	6.13	6.7	7.38	7	7.4	6.7	6.8
MW-1004P	Alkalinity	mg/l	160	170	160	170	160	190	170	170	170	170	140	160	160	170
MW-1004P	Copper	mg/l	< 0.014	< 0.014	< 0.014	< 0.014	0.014	< 0.014	< 0.014	< 0.01	< 0.012	< 0.012	< 0.012	< 0.012	< 0.012	< 0.0016
MW-1004P	Hardness	mg/l	150	170	150	160	170	180	160	160	150	160	150	150	150	160
MW-1004P	Iron	mg/l	0.33	0.22	0.32	0.37	0.38	0.32	0.39	< 0.01	0.042	0.048	< 0.015	0.033	0.024	0.035
MW-1004P	Manganese	mg/l	0.13	0.13	0.12	0.14	0.13	0.13	0.14	< 0.004	0.022	0.04	0.02	0.045	0.028	0.029
MW-1004P	Sulfate	mg/l	< 10	< 10	< 10	< 10	< 10	< 10	< 10	3	5	3	2	3	2.5	3.9
MW-1004P	TDS	mg/l	210	310	160	180	180	260	160	160	180	230	160	180	190	200
MW-1004P	pH(Field)	S.U.	8.15	7.15	6.8	6.88	6.74	7.46	6.24	7.74	7.4	7.61	7.3	7.4	7.1	7.1
MW-1004S	Alkalinity	mg/l	50	49	27	60	74	100	73	51	24	32	42	38	140	44
MW-1004S	Copper	mg/l	< 0.014	< 0.014	< 0.014	< 0.014	0.014	< 0.014	< 0.014	< 0.01	< 0.012	< 0.012	0.016	< 0.012	< 0.012	< 0.0016
MW-1004S	Hardness	mg/l	60	60	62	72	150	110	92	70	56	46	44	51	52	54
MW-1004S	Iron	mg/l	< 0.055	< 0.055	< 0.055	< 0.055	< 0.055	< 0.055	< 0.055	< 0.01	< 0.015	< 0.015	< 0.015	< 0.015	< 0.015	0.0064
MW-1004S	Manganese	mg/l	< 0.004	< 0.004	< 0.004	< 0.004	0.004	< 0.004	< 0.004	< 0.004	< 0.004	< 0.004	< 0.004	< 0.004	< 0.004	< 0.00047
MW-1004S	Sulfate	mg/l	< 10	10	11	12	< 10	< 10	< 10	11	11	9	10	8	8	8.6
MW-1004S	TDS	mg/l	160	170	95	100	110	220	95	120	110	98	74	100	100	150
MW-1004S	pH(Field)	S.U.	8.64	7.25	7.03	6.7	6.5	6.96	6.37	7.77	7	7.41	7	7.8	6.8	6.7

Table 1, continued

Well	Parameter	Units	Jul-91	Oct-91	Jan-92	Apr-92	Jul-92	Oct-92	Jan-93	Apr-93	Jul-93	Oct-93	Jan-94	Apr-94	Jul-94	Oct-94
MW-1005	Alkalinity	mg/l	84	92	86	90	90	110	94	78	74	84	81	88	75	78
MW-1005	Copper	mg/l	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.01	< 0.012	< 0.012	< 0.012	< 0.012	< 0.012	< 0.0016
MW-1005	Hardness	mg/l	380	360	1000	520	420	400	400	500	410	390	440	450	450	420
MW-1005	Iron	mg/l	17	20	18	17	22	24	24	24	18	25	24	24	31	28
MW-1005	Manganese	mg/l	0.51	0.49	0.46	0.38	0.44	0.47	0.52	0.54	0.42	0.61	0.53	0.54	0.69	0.63
MW-1005	Sulfate	mg/l	15	12	14	16	15	15	23	15	18	17	18	13	14	20
MW-1005	TDS	mg/l	570	770	530	680	640	600	140	630	590	680	580	620	600	820
MW-1005	pH(Field)	S.U.	7.73	7.34	6.12	6.32	6.01	6.13	6.21	6.11	6.1	6.68	6.3	7.6	6.2	6.1
MW-1005P	Alkalinity	mg/l	260	260	260	260	270	270	260	250	250	250	250	250	240	250
MW-1005P	Copper	mg/l	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.01	< 0.012	< 0.012	< 0.012	< 0.012	< 0.012	< 0.0016
MW-1005P	Hardness	mg/l	280	230	240	240	260	260	240	250	230	220	230	230	230	250
MW-1005P	Iron	mg/l	1.2	1	0.75	1	1.2	1.1	1.1	0.46	0.61	0.17	0.19	0.2	0.22	0.24
MW-1005P	Manganese	mg/l	0.22	0.15	0.16	0.13	0.1	0.11	0.11	0.15	0.14	0.069	0.35	0.16	0.1	0.62
MW-1005P	Sulfate	mg/l	< 10	< 10	< 10	< 10	< 10	< 10	< 10	2	3	< 2	< 2	< 2	< 2	2.5
MW-1005P	TDS	mg/l	290	440	280	350	270	320	220	240	260	300	260	270	270	280
MW-1005P	pH(Field)	S.U.	8.49	7.66	6.85	6.37	6.81	7.26	6.39	6.52	7.6	7.53	7.3	7.2	6.9	7.2
MW-1005S	Alkalinity	mg/l	170	170	170	180	190	190	180	81	170	170	160	160	160	160
MW-1005S	Copper	mg/l	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.01	< 0.012	< 0.012	< 0.012	< 0.012	< 0.012	< 0.0016
MW-1005S	Hardness	mg/l	170	170	250	290	270	270	180	210	160	160	160	160	160	160
MW-1005S	Iron	mg/l	3	3.8	3.6	3.7	3.9	4.1	4.1	4.4	4.2	4.2	4	4.1	4.1	3.7
MW-1005S	Manganese	mg/l	0.21	0.22	0.21	0.2	0.2	0.21	0.21	0.23	0.22	0.24	0.2	0.2	0.2	0.19
MW-1005S	Sulfate	mg/l	< 10	< 10	< 10	< 10	< 10	< 10	< 10	8	9	6	9	8	7.2	13
MW-1005S	TDS	mg/l	220	370	20	210	220	260	160	200	200	220	190	200	210	240
MW-1005S	pH(Field)	S.U.	7.68	7.37	6.88	7.48	7.38	6.88	6.09	6.38	7.3	7.28	7.2	7.5	6.9	7.3
MW-1010P	Alkalinity	mg/l	140	160	150	160	180	180	190	170	150	160	160	160	160	160
MW-1010P	Copper	mg/l	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.014	< 0.012	< 0.012	< 0.012	< 0.012	< 0.012	0.0032
MW-1010P	Hardness	mg/l	140	130	130	140	160	160	180	130	130	130	150	150	150	150
MW-1010P	Iron	mg/l	< 0.055	< 0.055	0.15	< 0.055	< 0.055	< 0.055	< 0.055	0.055	< 0.015	< 0.015	< 0.015	< 0.015	< 0.015	0.0046
MW-1010P	Manganese	mg/l	0.26	0.28	0.25	0.2	0.14	0.14	0.031	0.14	0.035	0.081	0.17	0.014	0.01	0.014
MW-1010P	Sulfate	mg/l	< 10	10	16	14	< 10	< 10	32	28	11	5	3	3	3.4	4.5
MW-1010P	TDS	mg/l	180	250	200	340	180	280	210	270	180	230	170	180	190	200
MW-1010P	pH(Field)	S.U.	8.47	8.26	6.87	7.62	6.86	7.49	7.21	6.62	7.2	7.51	7.3	7.4	7.2	7.5

Table 1, continued

Well	Parameter	Units	Sample Size	Total Detections	Percent Detected	Mann-Kendall		p-Level
						S	S	
MW-1000P	Alkalinity	mg/l	14	14	100%	-57	0.002	*
MW-1000P	Copper	mg/l	14	8	57%	58	0.001	*
MW-1000P	Hardness	mg/l	14	14	100%	-43	0.02	
MW-1000P	Iron	mg/l	14	13	93%	-61	0	*
MW-1000P	Manganese	mg/l	14	14	100%	-46	0.012	
MW-1000P	Sulfate	mg/l	14	11	79%	30	0.113	
MW-1000P	TDS	mg/l	14	14	100%	-46	0.012	
MW-1000P	pH(Field)	S.U.	14	14	100%	12	0.554	
MW-1002	Alkalinity	mg/l	14	14	100%	-44	0.017	
MW-1002	Copper	mg/l	14	0	0%	0	1	
MW-1002	Hardness	mg/l	14	14	100%	-41	0.026	
MW-1002	Iron	mg/l	14	4	29%	-4	0.872	
MW-1002	Manganese	mg/l	14	3	21%	-18	0.359	
MW-1002	Sulfate	mg/l	14	9	64%	15	0.45	
MW-1002	TDS	mg/l	14	14	100%	-33	0.08	
MW-1002	pH(Field)	S.U.	14	14	100%	23	0.234	
MW-1002G	Alkalinity	mg/l	14	14	100%	11	0.59	
MW-1002G	Copper	mg/l	14	0	0%	0	1	
MW-1002G	Hardness	mg/l	14	14	100%	3	0.914	
MW-1002G	Iron	mg/l	14	1	7%	13	0.518	
MW-1002G	Manganese	mg/l	14	1	7%	-13	0.518	
MW-1002G	Sulfate	mg/l	14	13	93%	41	0.026	
MW-1002G	TDS	mg/l	14	14	100%	1	1	
MW-1002G	pH(Field)	S.U.	14	14	100%	0	1	
MW-1004P	Alkalinity	mg/l	14	14	100%	-4	0.872	
MW-1004P	Copper	mg/l	14	1	7%	9	0.668	
MW-1004P	Hardness	mg/l	14	14	100%	-17	0.388	
MW-1004P	Iron	mg/l	14	12	86%	-37	0.048	
MW-1004P	Manganese	mg/l	14	13	93%	-34	0.071	
MW-1004P	Sulfate	mg/l	14	7	50%	47	0.01	
MW-1004P	TDS	mg/l	14	14	100%	-3	0.914	
MW-1004P	pH(Field)	S.U.	14	14	100%	-5	0.83	
MW-1004S	Alkalinity	mg/l	14	14	100%	-3	0.914	
MW-1004S	Copper	mg/l	14	1	7%	7	0.748	
MW-1004S	Hardness	mg/l	14	14	100%	-32	0.09	
MW-1004S	Iron	mg/l	14	1	7%	13	0.518	
MW-1004S	Manganese	mg/l	14	0	0%	0	1	
MW-1004S	Sulfate	mg/l	14	10	71%	-2	0.957	
MW-1004S	TDS	mg/l	14	14	100%	-14	0.484	
MW-1004S	pH(Field)	S.U.	14	14	100%	-13	0.518	

* Indicates Statistically Significant Trend

Table 1, continued

Well	Parameter	Units	Sample Size	Total Detections	Percent Detected	Mann-Kendall S	P-Level
MW-1005	Alkalinity	mg/l	14	14	100%	-30	0.113
MW-1005	Copper	mg/l	14	0	0%	0	1
MW-1005	Hardness	mg/l	14	14	100%	6	0.789
MW-1005	Iron	mg/l	14	14	100%	59	0 *
MW-1005	Manganese	mg/l	14	14	100%	48	0.012
MW-1005	Sulfate	mg/l	14	14	100%	23	0.234
MW-1005	TDS	mg/l	14	14	100%	5	0.83
MW-1005	pH(Field)	S.U.	14	14	100%	-16	0.419
MW-1005P	Alkalinity	mg/l	14	14	100%	-47	0.01
MW-1005P	Copper	mg/l	14	0	0%	0	1
MW-1005P	Hardness	mg/l	14	14	100%	-7	0.748
MW-1005P	Iron	mg/l	14	14	100%	-47	0.01
MW-1005P	Manganese	mg/l	14	14	100%	-4	0.872
MW-1005P	Sulfate	mg/l	14	3	21%	18	0.359
MW-1005P	TDS	mg/l	14	14	100%	-22	0.257
MW-1005P	pH(Field)	S.U.	14	14	100%	-14	0.484
MW-1005S	Alkalinity	mg/l	14	14	100%	-33	0.08
MW-1005S	Copper	mg/l	14	0	0%	0	1
MW-1005S	Hardness	mg/l	14	14	100%	-43	0.02
MW-1005S	Iron	mg/l	14	14	100%	31	0.1
MW-1005S	Manganese	mg/l	14	14	100%	-22	0.257
MW-1005S	Sulfate	mg/l	14	8	57%	46	0.012
MW-1005S	TDS	mg/l	14	13	93%	-4	0.872
MW-1005S	pH(Field)	S.U.	14	14	100%	-12	0.554
MW-1010P	Alkalinity	mg/l	14	14	100%	14	0.484
MW-1010P	Copper	mg/l	14	1	7%	13	0.518
MW-1010P	Hardness	mg/l	14	14	100%	15	0.45
MW-1010P	Iron	mg/l	14	3	21%	2	0.957
MW-1010P	Manganese	mg/l	14	14	100%	-61	0 *
MW-1010P	Sulfate	mg/l	14	11	79%	-5	0.83
MW-1010P	TDS	mg/l	14	14	100%	-16	0.419
MW-1010P	pH(Field)	S.U.	14	14	100%	-16	0.419

* Indicates Statistically Significant Trend



Table 2

Surface Water Quality Results, Summary Statistics and Trend Analysis
July 1991 Through October 1994

Station	Parameter	Units	Jul-91	Oct-91	Jan-92	Apr-92	Jul-92	Oct-92	Jan-93	Apr-93	Jul-93	Nov-93	Jan-94	Apr-94	Jul-94	Oct-94
SW-1	Aluminum	mg/l	<	0.08	0.7	0.75	0.14	0.42	0.11	0.13	0.18	0.047	0.12	0.29	0.07	0.2
SW-1	Arsenic	mg/l	<	0.002	<	0.002	<	0.002	<	0.002	0.0028	<	<	<	<	<
SW-1	Beryllium	mg/l	<	0.2	<	0.001	<	0.001	<	0.001	<	<	<	<	<	<
SW-1	Cadmium	mg/l	<	0.001	<	0.0002	0.0006	0.0002	0.0007	0.0002	0.0008	<	0.0002	0.00038	<	0.0008
SW-1	Chromium	mg/l	0.0027	<	0.002	<	0.001	<	<	<	<	0.004	<	0.0018	0.0018	0.0025
SW-1	Chromium VI	mg/l	0.01	<	0.009	<	0.018	<	<	0.005	0.005	<	<	<	<	0.0015
SW-1	Chromium VI	mg/l	<	0.003	0.003	0.005	0.002	0.004	<	0.002	0.012	<	0.0044	<	0.0027	0.002
SW-1	Copper	mg/l	6.2	11	12	11.2	7.4	9.9	11	10	10	9	11.9	5.8	8.5	10.1
SW-1	Diss O2	mg/l	100	46	50	34	23	52	52	40	44	56	64	43	48	36
SW-1	Hardness	mg/l	0.0012	<	0.001	<	0.001	<	<	0.001	<	<	0.001	0.01	0.0025	0.0011
SW-1	Lead	mg/l	<	0.0002	<	0.0002	<	0.0002	<	0.0002	<	<	<	<	<	<
SW-1	Mercury	mg/l	<	0.05	0.05	<	0.018	0.02	0.02	0.02	0.016	0.016	0.016	0.016	0.016	0.016
SW-1	Nickel	mg/l	<	0.002	<	0.002	<	0.002	<	0.002	<	<	<	<	<	<
SW-1	Selenium	mg/l	<	0.0005	<	0.0005	<	0.0005	<	0.0005	<	<	<	<	<	<
SW-1	Silver	mg/l	140	98	90	86	90	90	100	66	66	91	93	84	96	100
SW-1	Sulfide	mg/l	<	1	4	<	9	4	<	2	5	<	1	3	1	8
SW-1	TDS	mg/l	0.02	24	0.008	0.011	0.006	<	0.003	<	0.003	<	0.007	0.009	0.011	0.017
SW-1	TSS	mg/l	7.43	7.92	6.95	6.71	6.75	7.23	6.71	7.07	7.3	8.59	7.8	8	7.4	7.2
SW-1	Zinc	S.U.	<	0.4	0.42	0.72	0.14	0.54	0.07	0.11	0.36	0.072	0.036	0.31	0.14	0.22
SW-2	Aluminum	mg/l	<	0.001	<	0.002	<	0.002	<	0.002	0.0027	<	<	<	<	<
SW-2	Arsenic	mg/l	<	0.2	<	0.001	<	0.001	<	0.001	<	<	<	<	<	<
SW-2	Beryllium	mg/l	<	0.0002	<	0.0002	<	0.0002	<	0.0002	<	<	<	<	<	<
SW-2	Cadmium	mg/l	<	0.0012	0.002	0.001	0.001	0.001	0.001	0.001	0.0021	0.004	0.001	0.0019	0.0023	0.0037
SW-2	Chromium	mg/l	0.009	<	0.007	<	0.013	0.02	<	0.005	0.005	<	<	<	<	0.0015
SW-2	Chromium VI	mg/l	0.0042	<	0.004	<	0.002	0.004	0.004	0.002	0.012	0.0032	0.002	0.0051	0.0036	0.0057
SW-2	Copper	mg/l	6.5	10	12	11.5	7.6	10	12	11	9.7	8.5	11.6	6.6	8.8	9.3
SW-2	Diss O2	mg/l	48	47	50	34	28	68	52	40	76	60	60	40	48	38
SW-2	Hardness	mg/l	0.0012	<	0.001	<	0.003	<	<	0.001	<	<	0.001	0.001	0.0014	0.0015
SW-2	Lead	mg/l	<	0.0002	<	0.0002	<	0.0002	<	0.0002	<	<	<	<	<	<
SW-2	Mercury	mg/l	<	0.05	0.05	<	0.018	0.02	0.02	0.02	0.016	0.016	0.016	0.016	0.016	0.016
SW-2	Nickel	mg/l	<	0.002	<	0.002	<	0.002	<	0.002	<	<	<	<	<	<
SW-2	Selenium	mg/l	<	0.0005	<	0.0005	<	0.0005	<	0.0005	<	<	<	<	<	<
SW-2	Silver	mg/l	140	85	87	120	120	96	110	74	100	88	88	82	100	92
SW-2	Sulfide	mg/l	<	1	4	<	7	5	<	1	11	<	1	13	10	8
SW-2	TDS	mg/l	0.02	3	0.004	0.009	0.008	<	0.008	<	0.009	0.004	0.05	0.007	0.009	0.023
SW-2	TSS	mg/l	7.92	8.01	7.09	6.19	7.1	7.11	7.05	7.25	7.1	7.93	8.1	8	7.6	7.1
SW-2	Zinc	S.U.	<	0.4	0.42	0.72	0.14	0.54	0.07	0.11	0.36	0.072	0.036	0.31	0.14	0.22
SW-2	pH(Field)	S.U.	<	0.001	<	0.002	<	0.002	<	0.002	0.0027	<	<	<	<	<


Table 2, continued

Station	Parameter	Units	Sample Size	Total Detections	Percent Detected	Mann-Kendall S	P-Level
SW-1	Aluminum	mg/l	14	13	93%	-1	1
SW-1	Arsenic	mg/l	14	1	7%	3	0.914
SW-1	Beryllium	mg/l	14	0	0%	0	1
SW-1	Cadmium	mg/l	14	4	29%	-12	0.554
SW-1	Chromium	mg/l	14	6	43%	12	0.554
SW-1	Chromium VI	mg/l	13	2	15%	-21	0.228
SW-1	Copper	mg/l	14	8	57%	-12	0.554
SW-1	Diss O2	mg/l	14	14	100%	-11	0.59
SW-1	Hardness	mg/l	14	14	100%	-6	0.789
SW-1	Lead	mg/l	14	5	36%	21	0.28
SW-1	Mercury	mg/l	14	0	0%	0	1
SW-1	Nickel	mg/l	14	0	0%	0	1
SW-1	Selenium	mg/l	14	0	0%	0	1
SW-1	Silver	mg/l	14	0	0%	0	1
SW-1	Sulfide	mg/l	3	0	0%	0	1
SW-1	TDS	mg/l	14	14	100%	-2	0.987
SW-1	TSS	mg/l	14	9	64%	-6	0.789
SW-1	Zinc	mg/l	14	10	71%	-9	0.668
SW-1	pH(Field)	S.U.	14	14	100%	18	0.359
SW-2	Aluminum	mg/l	14	13	93%	4	0.872
SW-2	Arsenic	mg/l	14	1	7%	3	0.914
SW-2	Beryllium	mg/l	14	2	14%	24	0.213
SW-2	Cadmium	mg/l	14	2	14%	-1	1
SW-2	Chromium	mg/l	14	8	57%	28	0.142
SW-2	Chromium VI	mg/l	13	2	15%	-21	0.228
SW-2	Copper	mg/l	14	9	64%	14	0.484
SW-2	Diss O2	mg/l	14	14	100%	-11	0.59
SW-2	Hardness	mg/l	14	14	100%	2	0.357
SW-2	Lead	mg/l	14	5	36%	1	1
SW-2	Mercury	mg/l	14	0	0%	0	1
SW-2	Nickel	mg/l	14	0	0%	0	1
SW-2	Selenium	mg/l	14	0	0%	0	1
SW-2	Silver	mg/l	14	0	0%	0	1
SW-2	Sulfide	mg/l	3	0	0%	0	1
SW-2	TDS	mg/l	14	14	100%	-25	0.192
SW-2	TSS	mg/l	14	8	57%	28	0.142
SW-2	Zinc	mg/l	14	11	79%	21	0.28
SW-2	pH(Field)	S.U.	14	14	100%	16	0.419


Attachment 1

Flambeau Mining Company Groundwater Quality Results


MW-1000P




* Compound Not Detected, Value = Detection Limit



* Compound Not Detected, Value = Detection Limit







* Compound Not Detected, Value = Detection Limit



* Compound Not Detected, Value = Detection Limit


Flambeau Mining Company Groundwater Quality Results

MW-1000P




Flambeau Mining Company Groundwater Quality Results


MW-1002




* Compound Not Detected, Value = Detection Limit



* Compound Not Detected, Value = Detection Limit







* Compound Not Detected, Value = Detection Limit



* Compound Not Detected, Value = Detection Limit





Flambeau Mining Company Groundwater Quality Results

MW-1002







Flambeau Mining Company Groundwater Quality Results

MW-1002G







Flambeau Mining Company
Groundwater Quality Results

MW-1002G







Flambeau Mining Company Groundwater Quality Results

MW-1004P







Flambeau Mining Company Groundwater Quality Results

MW-1004P



Flambeau Mining Company Groundwater Quality Results





MW-1004S



Prepared By: SGL Checked By: JBH1





Flambeau Mining Company
Groundwater Quality Results

MW-1004S







Flambeau Mining Company Groundwater Quality Results

MW-1005







Flambeau Mining Company Groundwater Quality Results

MW-1005



Flambeau Mining Company Groundwater Quality Results





MW-1005P



Prepared By: SGL Checked By: JBH1

Flambeau Mining Company Groundwater Quality Results





MW-1005P



Prepared By: SGL Checked By: JBH1





Flambeau Mining Company Groundwater Quality Results

MW-1005S



Flambeau Mining Company
Groundwater Quality Results





MW-1005S



Prepared By: SGL Checked By: JBH1

Flambeau Mining Company
Groundwater Quality Results





MW-1010P



Prepared By: SGL Checked By: JBH1





Flambeau Mining Company
Groundwater Quality Results

MW-1010P







Prepared By: SGL Checked By: JBH1

Flambeau Mining Company
Groundwater Elevation Results







Prepared By: SGL Checked By: JBH1

Flambeau Mining Company
Groundwater Elevation Results







Flambeau Mining Company




Groundwater Elevation Results




Flambeau Mining Company
Groundwater Elevation Results







Flambeau Mining Company
Groundwater Elevation Results







January 1992 reading erratic. Validity disputable.







Flambeau Mining Company
Groundwater Elevation Results



Flambeau Mining Company
Groundwater Elevation Results





Flambeau Mining Company
Groundwater Elevation Results







Prepared By: SGL Checked By: JBH1



Flambeau Mining Company
Groundwater Elevation Results



Flambeau Mining Company
Groundwater Elevation Results







Flambeau Mining Company
Groundwater Elevation Results



Attachment 2





Flambeau Mining Company Surface Water Quality Results

SW-1







Flambeau Mining Company
Surface Water Quality Results

SW-1







Flambeau Mining Company Surface Water Quality Results

SW-1






Flambeau Mining Company Surface Water Quality Results

SW-1







Flambeau Mining Company Surface Water Quality Results

SW-1







Flambeau Mining Company
Surface Water Quality Results

SW-2







Flambeau Mining Company
Surface Water Quality Results

SW-2



Flambeau Mining Company
Surface Water Quality Results


SW-2




Flambeau Mining Company
Surface Water Quality Results

SW-2


Nickel




Selenium



Silver






Sulfide



Flambeau Mining Company Surface Water Quality Results

SW-2



Appendix D

Sediment Sampling

Foth & Van Dyke Memorandum

January 9, 1995

TO: Jana Murphy, Flambeau Mining Company

CC: Tom Myatt, Flambeau Mining Company
Jim Hutchison, Foth & Van Dyke
Jerry Sevick, Foth & Van Dyke

FR: Bill West, Foth & Van Dyke ^{wmw}

RE: Report on Activities Associated with 1994 Sediment Sampling
Flambeau River, Ladysmith, Wisconsin

Introduction

On July 11, 1994, Bill West of Foth & Van Dyke was accompanied by Jack Christman of Flambeau Mining Company (Flambeau) for the purpose of installing sediment traps in the Flambeau River. This activity is part of routine site monitoring required of the Flambeau Mining Permit.

Triplicate sediment collection containers were positioned in two locations in the Flambeau River. One location was above the Flambeau discharge Outfall 001 at the Blackberry Lane access. The second location was downstream of mining site Outfall 001 near the Sister's farm. The sampling locations were the same locations sampled in 1993. Sample containers were removed from the river after an exposure period of four weeks.

Methodology

Sediment traps were installed upstream and downstream of the Flambeau discharge locations as illustrated in Figure 1. Sample containers consisted of one-quart wide mouth mason jars which were acid washed prior to installation.

At each sampling location, a set of three sample jars were placed in the river, each secured by rebar and surrounded by a concrete half block. Rebar was driven into the substrate to the point of being flush with the top of the block. Sinking the rebar flush with the block discourages the collection of debris which may cover the jar opening.

Quart jars inserted into the submerged half block opening were positioned so that the top of the jar was either flush with the top of the block or slightly below the top of the block. This positioning was designed to reduce the potential for breakage due to an encounter with water-borne debris.

With every three jar set, the outer most jar (most distal to the shore) was positioned approximately 45 degrees upstream of the second jar. The proximal jar was 45 degrees downstream of the middle jar. The jars were separated in the stream by a minimum of three feet. When placing jars, the upstream jar was positioned first followed by the middle jar then finally the downstream jar. In this manner, the chance of impacting downstream jars while placing the upstream jars was eliminated.

Based on observations noted from 1993 sediment collection activities, minor method modifications were added to the 1994 protocol. First, only one rebar was used to secure the half block. This could be accomplished by rotating each block so that a corner faced upstream. This practice reduces the side pressure on the block allowing use of a single rebar section to secure the block. Second, it was noted that crayfish and small fish were able to take up residence in the jars over the exposure period. It was observed in 1993 that jars which contained crayfish also contained significant amount of gravel and pebbles. Also, the movements of crayfish and fish actually stirred up the collected sediment resulting in loss of the very sediment which was to be collected. Therefore, in 1994, ½-inch mesh nitex screening was placed over each of the jars. The screening was secured on the rim of the jar using plastic ties. The screen was of sufficient mesh size to discourage colonization by fish and crayfish and large enough to allow sediment to pass. Initial concerns over the possibility of algal growth covering the mesh and preventing the transfer of sediment to the jar were unfounded as little algal growth was observed in the one month exposure period.

Sample containers were retrieved on August 9, 1994. At each site, the container furthest downstream of the three sample set was removed first followed by the middle jar and finally the furthest upstream jar. In this manner contamination of downstream jars was avoided.

To secure the sample, the plastic tie and mesh were first removed. A sheet of parafilm was stretched over the jar opening to seal the sediments and water. This seal was followed by lid and ring. Samples were iced and taken directly to Northern Lake Service in Crandon, Wisconsin for analysis. At the laboratory the sediment in the three jars at each sampling location were combined into samples S-1 (upstream) and S-3 (downstream).

Observations

Sample consistency from the upstream site (S-1) and downstream site (S-3) were very uniform, *i.e.*, soft sediment with no gravel. It was noted that no fish or crayfish were captured in the sample containers. It was also observed that little if any gravel or pebbles were contained in the sample containers and that contrary to previous years, all collected material appeared to be made up of soft water-borne sediment. Some macroinvertebrates were successful in colonizing the sample containers. Caddisfly casings can be seen attached to the jar walls in Figures 2 and 3. Also, it was noted that containers from Site S-3 had nearly twice the amount of collected sediment as did jars from Site S-1. This might be expected since Blackberry Lane (Site S-1) is characterized by low relief, shallow water where samplers could be located 30 to 50 feet off shore while the Sister's Farm location is of steep gradient with samplers located 10 to 20 feet off shore. There is a higher degree of probability that near shore sediments or on shore sediments at S-3 could become disturbed and available for capture in the S-3 containers.


Results

A summary of results of the laboratory analysis of the sediment samples from the two sampling sites is shown in Table 1. Individual sample analysis reports are attached.

Discussion

Data from the first four years of sediment analysis indicates that, in general, no increase or decrease in parameter concentration in sediments is occurring. Moreover, downstream samples continue to compare favorably with upstream sediment samples indicating no impacts due to mine activities.

Because Foth & Van Dyke was successful in eliminating biota (crayfish and fish) from the jars during the collection period, sediment quantities collected were reduced. This aspect resulted in having insufficient samples to conduct total solids and total volatile solids analyses. To alleviate this problem, Foth & Van Dyke will add additional sediment traps in 1995.



SEDIMENT SAMPLE LOCATION
 FIGURE I
 FLAMBEAU MINING COMPANY
 LADYSMITH, WISCONSIN
 Scale: 1" = 2000'
 Date: 8-31-93
 By: G



Figure 2 Triplicate Sediment Samples from Site S-1



Figure 3 Triplicate Sediment Samples from Site S-3

Flambeau River Sediment Sampling Results 1991 - 1994

Parameter (mg/L)	Sample Location/Number								
	Blackberry Lane (S-1)				Port Arthur Dam (S-2 & S-3)				
	S-1-01 (1991)	S-1-02 (1992)	S-1-03 (1993)	S-1-04 (1994)	S-2-01 (1991)	S-2-02 (1992)	S-2-03 (1993)	S-3-03 (1993)	S-3-04 (1994)
Silver	<1.2	<1.1	0.057	<0.21	<1.1	<2.6	0.086	0.58	<0.08
Aluminum	3800.0	3300.0	4000.0	3900	4000.0	12000.0	1500	4400	4000
Arsenic	2.2	2.2	1.4	<4.2	1.5	4.1	<0.55	0.71	<1.6
Cadmium	<0.7	<0.6	<0.06	<0.42	0.6	<1.4	<0.055	0.11	0.13
Chromium	11.0	10.0	11	10	13.0	24.0	23.8	9.6	10
Copper	7.3	6.0	7.0	5.8	7.2	24.0	2.1	6.7	7.1
Iron	18000.0	16000.0	15000	11000	16000	25000	3100	8200	7700
Mercury	0.1	<0.1	<0.045	<0.04	0.1	<0.3	<0.057	<0.07	<0.03
Manganese	1900.0	1000.0	1300	1500	1600.0	570.0	610	830	860
Nickel	5.8	6.1	8.4	7.4	7.3	12.0	1.7	6.5	6.2
Lead	6.0	5.8	8.5	3.3	6.9	20.0	2.6	8.3	7.8
Selenium	0.4	<0.4	<0.32	4.2	0.4	<0.9	<0.28	<0.26	<1.6
Zinc	47.0	33.0	38	34	45.0	79.0	9.6	33	46
Total Solids %	73.0	78.6	79.2	NA*	76.8	35.0	32	56	NA*
Total Volatile Solids %	1.80	1.60	0.77	NA*	2.5	12.0	5.8	6.24	NA*
Field Temp. C	25.0	16.2	15.0	NA	25.0	15.8	15.5	15.5	NA

*Solids data not available due to insufficient sample.

Appendix E

Fish Sampling

Foth & Van Dyke Memorandum

January 9, 1995

TO: Jana Murphy, Flambeau Mining Company

CC: Tom Myatt, Flambeau Mining Company
Jim Hutchison, Foth & Van Dyke
Jerry Sevick, Foth & Van Dyke

FR: Bill West, Foth & Van Dyke *lms*

RE: Report on Activities, 1994 Fish Collection and Analysis, Flambeau River, Ladysmith, Wisconsin

Introduction

On October 16 and 17, 1994, representatives of EA Associates, Deerfield, Illinois and Foth & Van Dyke, electroshocked two impoundments on the Flambeau River located above and below the Flambeau Mine Site. These impoundments included the flowage above the Ladysmith Dam, Ladysmith, Wisconsin (upstream sample), and the flowage above the Thornapple Dam (downstream sample). The purpose of the sampling event was to collect walleye and submit walleye fillets for tissue (metals) analysis.

The sampling event took place approximately one month after severe flooding was experienced on the Flambeau River. Flooding was so severe that a breach of the sidewall of the dam in Ladysmith occurred. This led to the release of the majority of the water in the impoundment at Ladysmith. Data from 1994 should be viewed in light of the fact that formerly impounded walleye at the Ladysmith Dam could very well make up some of the fish shocked at the Thornapple Dam.

Fish Sampling

Acceptable sampling methods include hook and line, electroshocking, and fyke netting. As in previous years, electroshocking was used for the collection of walleye. The objective of the electroshocking effort is to collect walleye in the following size ranges:

- 10 to 12 inches - one fish
- 12 to 15 inches - two fish
- 15 to 18 inches - three fish
- 18 to 22 inches - two fish
- greater than 22 inches - one fish

Electrofishing was conducted on the Thornapple Flowage on October 16 and 17, and on the Ladysmith Flowage on October 17, using a pulsed DC electrofishing boat.

Fillets of walleye were tested for total mercury. The livers of the fish collected at each of the two sampling stations were composited into one upstream and one downstream sample. Each was analyzed for metal parameters. Each walleye was measured for total length, sexed, and the stomach contents noted. The age of each walleye was determined. Physical characteristics of each walleye are found in Table 1. The stomach analyses of the walleye are found in Table 2. Tables 3 and 4 show the results of the liver and tissue analyses.

In previous years, Foth & Van Dyke had included a table which listed species of fish, other than walleye, which were encountered during the walleye collection activities. Because of the severe flooding during the proposed collection period, the walleye collection effort had to be postponed several times. When the collections were conducted, the necessary identification specialists were not available. Therefore, the fish species list does not appear in this report.

Species observed during the collection event were consistent with those collected in previous collection efforts. As was the case in previous years, there was some difficulty collecting all of the walleye for each of the larger size classes.

Interpretation of Results of Fish Data

Since shocking activities were targeting walleye, no attempt was made to use the shocking procedure as a quantitative or qualitative measure of fish species.

Tissue analysis of walleye from the Ladysmith Flowage indicated an increase in mercury from 1991 to 1992 but decreases thereafter. The Thornapple Flowage also shows decreases in mercury over the four years monitored. Average concentrations of mercury in 1994 in fish tissue are nearly identical in both upstream and downstream samples.

No increasing or decreasing chemical concentration trends can be observed for upstream and downstream samples of walleye liver.

Table 1

Physical Data of Walleye
Flambeau River, Ladysmith, Wisconsin
October 1994

ID No.	Length (mm)	Weight (g)	Sex	Age
Thornapple Flowage				
WE-TA-01	297	215	M	2+
WE-TA-02	373	530	F	3+
WE-TA-03	374	490	M	3+
WE-TA-04	382	575	F	3+
WE-TA-05	427	755	M	5+
WE-TA-06	435	790	M	5+
WE-TA-07	462	985	M	6+
WE-TA-08	394	620	F	4+
WE-TA-09	408	640	F	4+
Ladysmith Flowage				
WE-LS-01	296	240	M	3+
WE-LS-02	311	290	F	3+
WE-LS-03	334	320	F	4+
WE-LS-04	344	375	F	3+
WE-LS-05	373	520	F	4+
WE-LS-06	376	565	F	4+
WE-LS-07	383	540	F	4+
WE-LS-08	392	495	F	4+
WE-LS-09	516	1440	F	7+

Table 2

Stomach Analysis of Walleye
Flambeau River, Ladysmith, Wisconsin
October 1994

Sample ID	Percent Full	Type of Content	General Comments
Thornapple Flowage			
WE-TA-01	0	Empty	None
WE-TA-02	20	Some vegetation	Nearly all digested
WE-TA-03	0	Empty	None
WE-TA-04	95	1 Fish 60mm	Mostly digested
WE-TA-05	0	Empty	None
WE-TA-06	0	Empty	1 Tapeworm noted
WE-TA-07	0	Empty	None
WE-TA-08	85	1 Fish 80mm	Mostly digested, unidentifiable
WE-TA-09	0	Empty	None
Ladysmith Flowage			
WE-LS-01	10	Fish parts	Nearly all digested
WE-LS-02	100	1 Fish 60mm	Partly digested
WE-LS-03	50	1 Fish	Nearly all digested
WE-LS-04	0	Empty	None
WE-LS-05	0	Empty	None
WE-LS-06	0	Empty	None
WE-LS-07	55	1 Fish 45mm	Smallmouth bass Slightly digested
WE-LS-08	0	Empty	None
WE-LS-09	0	Empty	None

Table 3

**Fish Tissue Analysis
Mercury 1991 - 1994
Results in mg/kg**

Fish ID No.	Year			
	1991	1992	1993	1994
Thornapple Flowage				
WE-TA-01	0.09	0.78	0.40	0.10
WE-TA-02	1.00	0.55	0.40	0.18
WE-TA-03	0.60	0.59	0.20	0.19
WE-TA-04	0.80	0.52	0.48	0.21
WE-TA-05	0.40	0.68	0.39	0.37
WE-TA-06	0.70	0.76	0.33	0.88
WE-TA-07	0.60	0.44	1.10	0.59
WE-TA-08	0.80	0.47	0.63	0.29
WE-TA-09	0.60	0.38	0.91	0.32
Average Concentration	0.71	0.57	0.54	0.35
Ladysmith Flowage				
WE-LS-01	0.90	0.99	0.68	0.35
WE-LS-02	0.80	0.94	0.67	0.45
WE-LS-03	0.80	0.79	0.55	0.31
WE-LS-04	0.70	0.85	0.44	0.25
WE-LS-05	0.90	0.81	0.81	0.53
WE-LS-06	0.60	0.91	0.66	0.35
WE-LS-07	0.80	0.82	0.71	0.25
WE-LS-08	0.60	0.96	0.76	0.18
WE-LS-09	0.60	0.55	0.77	0.31
Average Concentration	0.67	0.84	0.67	0.33

Table 4

Metals Analysis of Walleye
Flambeau River, Ladysmith, WI
Results in mg/kg
1991-1994

Sample ID	Cd	Cr	Cu	Ni	Pb	Zn	Al	Hg	As	Se	Ag	Fe	Mn
Fish Liver													
WE-TA-1-9 1991	0.1	0.2	1.5	0.4	1.3	17	1.1	0.3	0.02	0.51	0.2	73	1.5
WE-TA-1-9 1992	<0.1	<0.1	1.6	<0.2	<0.1	33	15	0.2	<0.04	0.6	<0.1	96	1.6
WE-TA-1-9-1993	0.10	<0.10	4.3	<0.2	<0.05	21	1.6	0.45	<0.09	0.70	0.03	110	1.6
WE-TA-1-9-1994	<0.27	<0.63	1.2	<0.72	<3.9	16	7.9	0.12	<1.3	<1.3	<0.45	140	1.4
WE-LS-1-9 1991	0.1	0.3	6.0	0.5	1.2	18	2.9	0.3	0.02	0.48	0.2	67	1.4
WE-LS-1-9 1992	0.2	0.2	9.6	<0.2	<0.1	37	14	0.4	<0.05	0.6	<0.1	59	2.0
WE-LS-1-9-1993	0.19	<0.08	17	0.17	<0.04	22	1.6	0.28	<0.09	0.64	0.07	63	1.3
WE-LS-1-9-1994	0.32	<0.58	3.1	<0.67	<3.7	19	4.0	0.19	<1.4	<1.4	<0.42	76	1.6

Appendix F

Macroinvertebrate Sampling

Foth & Van Dyke Memorandum

January 9, 1995

TO: Jana Murphy, Flambeau Mining Company

CC: Tom Myatt, Flambeau Mining Company
Jim Hutchison, Foth & Van Dyke
Jerry Sevick, Foth & Van Dyke

FR: Bill West, Foth & Van Dyke *WMMW*

RE: Summary of Activities, 1994, Macroinvertebrate Collection
Flambeau River, Ladysmith, Wisconsin

Introduction

On October 3, 1994, Bill West of Foth & Van Dyke completed the 1994 macroinvertebrate collection activities for the Flambeau Mine project. These activities are a requirement of the project's Mining Permit. Three locations, one upstream of the mine discharge locations and two downstream of the discharges, are required to be sampled annually. Sampling locations include the end of Blackberry Lane (upstream), the Flambeau River at the confluence with Meadowbrook Creek and at the site of the former Port Arthur Dam—the latter two sites being downstream sites. This report describes the collection activities and records observations noted on the day of collection.

Site Conditions

Water stage at all three sites was high—one to two feet above bank stage. This condition was noted to persist throughout the entire day and was apparently caused by major flooding from a storm occurring in the middle of September. The storm water caused a breach in the earthen portion of the dam in the city of Ladysmith located upstream of the project. Based on noted debris in the vegetation along shore, water stage appeared to have been eight to ten feet above bank stage during flooding. A coffer dam built to temporarily correct the problem allowed the Ladysmith pool to raise to near normal stage. However, because of the excess water in the Flambeau River system following the storm, all water discharged through the Dairyland Dam was passed directly through the Ladysmith Dam, hence, the consistently high water flow throughout the day of field collection.

Methodology

Macroinvertebrate samples were collected using a net with an 8 by 18-inch opening and a mesh size of 800 to 900 micron mesh size. In-stream sampling methods consisted of kick seining supplemented by sweep netting along the shore. These two techniques are appropriate for obtaining the necessary macroinvertebrate samples for this project.

At each of the three sites, in-stream sampling was conducted for a minimum of one hour. The kick seining effort included a period of kicking, which lasted about five minutes per kick (longer if few organisms were observed to be collected), followed by sample washing, sorting (removal of debris), and containerization of specimens. Specimens were preserved in alcohol as they were collected.

About ten minutes were required for each kick seine effort. At least one ten-minute effort was devoted to sweep netting along the near shore vegetation at each site with the exception of Meadowbrook Creek which lacks such vegetation.

When collected and preserved, samples were sent to EA Engineering, Deerbrook, Illinois, for identification and enumeration.

Site-Specific Observations and Conditions

Blackberry Lane

Sampling was initiated at the end of Blackberry Lane at 12:30 p.m. and was terminated at 2:00 p.m. Water temperature was 58°F. Water stage was one to two feet above bank stage. Substrate at Blackberry lane is characterized as predominantly cobble and smaller (typically less than four inches in diameter).

Bank vegetation immediately downstream of the Blackberry lane access is predominantly grass/sedge with a significant amount of overhang at the water edge. This sedge/grass complex was common to only this site of the three sampled. The bank vegetation was mostly submerged and, depending on the extent and severity of the recent flooding, may have lost a significant amount of the local fauna. Sweep netting in this area normally would pick up water strider, whirligig, water scorpion, water beetle and late instar Odonata, which may not be as common in downstream sampling sites.

Meadowbrook Creek

Sampling at Meadowbrook Creek was conducted from 10:30 a.m. to noon. Water temperature was 56°F. Water stage was about one foot over bank stage and covered the gravel bars along the bank immediately upstream of Meadowbrook Creek. Stream C which is upstream of Meadowbrook Creek was not flowing, however, river water was backed up into Stream C a distance of about 30 feet.

The substrate of the Meadowbrook Creek sampling site is characterized as rock/cobble with some boulder. Collections were concentrated in a portion of the Flambeau River immediately above the confluence of the Flambeau River with Meadowbrook Creek.

Port Arthur Dam

Sampling at Port Arthur Dam was conducted from 8:45 to 9:45 a.m. Water temperature was 56°F. Water stage was one to one and one half feet above bank stage.

The substrate of the Flambeau River at this site is characterized as rock in the four to twelve inch size category. It was noted that many of the rocks were very loose, possibly recently rolled by the flooding. As a note, it is probable that habitat in the vicinity may have moved around in the recent past with a resultant shift in local faunal populations.

Data Evaluation

Samples were sent to EA Engineering for enumeration and identification. Table 1 is a list of organisms collected during the 1994 sampling event.

Total taxa collected and reported in 1994 were significantly lower in diversity and abundance as compared to previous years. This condition holds true for samples collected both above and below the Flambeau Mining outfall. Lower numbers of organisms collected are likely attributed to the severe flooding which occurred in the middle of September and continued into October.

Table 1

**Macroinvertebrates Collected From Three
Locations Near the Flambeau Mine Site
October 1994**

Taxa	Blackberry Lane	Meadowbrook Creek	Port Arthur Dam
Decapoda			
<u>Orconectes sp.</u>	5	4	4
Isopoda			
<u>Caecidotea sp.(1)</u>	-	1	1
Amphipoda			
<u>Hyaloleia azteca</u>	-	1	4
Ephemeroptera			
<u>Caenis sp.</u>	-	1	-
<u>Ephemera simulans</u>	-	15	41
<u>Ephemerella sp.</u>	-	1	1
<u>Isonychia (Isonychia) sp.</u>	16	17	28
<u>Anthopotamus verticis(2)</u>	13	98	53
<u>Stenacron sp.</u>	-	-	5
<u>Stenonema mediopunctatum</u>	-	10	19
<u>Stenonema vicarium</u>	-	9	20
<u>Stenonema sp.</u>	1	1	21
Odonata			
<u>Calopteryx sp.</u>	-	-	5
<u>Ophiogomphus rupinsulensis</u>	12	3	3
<u>Ophiogomphus howei</u>	-	-	1
<u>Hylogomphus sp.</u>	1	1	4
Plecoptera			
<u>Acroneuria abnormis</u>	1	1	12
<u>Neoperla clymene</u>	1	2	9
<u>Agneta capitata(3)</u>	35	126	64
<u>Pteronarcys sp.</u>	1	-	-
Hemiptera			
<u>Hesperocorixa sp.</u>	-	-	2
Megaloptera			
<u>Nigronia serricornis</u>	2	1	7

Taxa	Blackberry Lane	Meadowbrook Creek	Port Arthur Dam
<u>Sialis sp.</u>	-	1	1
Tricoptera			
<u>Cheumatopsyche sp.</u>	6	19	21
<u>Chimarra obscura</u>	-	-	1
<u>Hydropsyche phalerata</u>	2	3	3
<u>Hydropsyche sp.</u>	37	27	25
<u>Macrostemum zebratum</u> (4)	1	-	4
<u>Polycentropus senu lato</u>	-	-	2
<u>Setodes sp.</u>	1	-	-
Coleoptera			
<u>Dineutus sp.</u>	1	-	1
<u>Dubiraphia sp.</u>	-	-	2
<u>Ectopria nervosa</u>	1	2	2
<u>Gyrinus sp.</u>	-	-	1
<u>Stenelmis sp.</u>	7	1	1
Diptera			
<u>Atherix sp.</u>	1	1	1
<u>Hexatoma sp.</u>	1	-	-
<u>Tabanus sp.</u>	2	-	-
Chironomidae			
<u>Cryptochironomus sp.</u>	1	-	-
<u>Epoicladius sp.</u>	-	-	8
<u>Microtendipes sp.</u>	-	7	-
<u>Nanocladius sp.</u>	-	-	2
<u>Stictochironomus sp.</u>	4	-	-
<u>Thienemannimyia sp. group</u>	-	1	-
<u>Chironomini</u>	-	1	-
Total Taxa	24	27	35

- (1) Caecodotea sp. formerly reported as Acellus sp.
- (2) Anthopotamus verticis formerly reported as Potamanthus verticis.
- (3) Agnetina capitata formerly reported as Phasganophora capitata.
- (4) Macrostemum zebratum formerly reported as Macronema zebratum.

Foth & Van Dyke Memorandum

January 9, 1995

TO: Jana Murphy, Flambeau Mining Company

CC: Tom Myatt, Flambeau Mining Company
Jim Hutchison, Foth & Van Dyke
Jerry Sevick, Foth & Van Dyke

FR: Bill West, Foth & Van Dyke *Wm*

RE: Report on Activities, 1994 Crayfish Collection for Tissue Analysis
Flambeau River, Ladysmith, Wisconsin

Introduction

On August 8, 1994, Bill West of Foth & Van Dyke completed crayfish collection activities at three sites on the Flambeau River downstream of Ladysmith, Wisconsin. The purpose of this activity was to fulfill requirements of the Flambeau Mining Permit which requires Flambeau Mining Company (Flambeau) to conduct metals analysis of crayfish at selected sites upstream and downstream of the mining discharge point (Outfall 001). A minimum of 25 crayfish are to be collected at the following sites:

1. The Flambeau River at the access point off Blackberry Lane (upstream site).
2. The Flambeau River at Meadowbrook Creek (downstream site).
3. The Flambeau River at the site of the former Port Arthur Dam (downstream site).

The time of year of collection is not defined, however, from past experience, the best time to collect appears to be mid to late summer when crayfish are active and easily obtained. This is also the time to obtain larger size crayfish which would provide better information on metals uptake in macroinvertebrates over time.

Methodology

All samples were collected using a 8 by 18-inch rectangular net with 800 to 900 micron mesh size. Crayfish were collected by using a kick seine method or by locating feeding crayfish and literally spooking them backwards into the net. The former method was used at the Port Arthur Dam and Meadowbrook Creek sites because water is deeper. At Blackberry Lane the latter method works well because the shallow water allows for easy observation of feeding crayfish.

Crayfish were collected during the following time windows:

Site Location	Time of Collection	Number of Crayfish
Port Arthur Dam	9:20 a.m. - 10:50 a.m.	26
Meadowbrook Creek	11:35 A.m. - 1:05 p.m.	25
Blackberry Lane	2:35 p.m. - 4:30 p.m.	28

Specimens were composited for each site in a Ziploc® bag and placed on ice. Specimens were transported to Northern Lake Service, Crandon, Wisconsin for metals analysis.

Results and Discussion

The results of the analysis of the crayfish appear in Table 1. The results represent a composite for all crayfish collected per site. Whole bodies were used for analysis. A review of the data indicates that no relative difference in parameter concentrations from upstream locations to downstream locations is evident.

Table 1

**Metals Analysis of Crayfish
Flambeau River, Ladysmith, WI
Results in mg/kg
1991 - 1994**

Sample ID	Cd	Cr	Cu	Ni	Pb	Zn	Al	Hg	As	Se	Ag
Blackberry 1991	0.1	1.0	17	0.4	1.2	23	36	0.1	0.24	0.14	0.2
Blackberry 1992	<0.1	0.4	16	<0.2	0.1	43	46	0.1	0.30	0.13	<0.1
Blackberry 1993	0.03	<0.09	15	0.2	<0.05	16	28	<0.2	<0.09	<0.19	0.06
Blackberry 1994	0.02	0.92	9.9	<0.22	<0.05	12	17	<0.02	<0.75	<1.93	<0.09
Meadowbrook 1991	0.1	1.6	20	0.5	1.3	27	36	0.1	0.29	0.15	0.2
Meadowbrook 1992	<0.1	0.5	19	<0.2	0.2	39	82	0.11	0.4	0.12	<0.1
Meadowbrook 1993	0.04	<0.09	15	0.2	<0.04	15	18	<0.20	<0.08	<0.35	0.08
Meadowbrook 1994	0.02	0.74	22	<0.29	<0.09	17	31	<0.03	<0.66	<1.64	<0.08
Port Arthur 1991	0.1	1.6	20	0.5	1.2	21	27	0.3	0.28	0.15	0.2
Port Arthur 1992	<0.1	0.4	14	1.5	0.2	33	430	0.1	0.34	0.14	<0.1
Port Arthur 1993	0.03	<0.09	12	<0.15	<0.04	11	22	<0.2	<0.1	<0.36	0.09
Port Arthur 1994	0.04	0.92	18	<1.4	<0.10	15	28	<0.02	<0.76	<1.88	<0.09

Appendix G

Habitat Characterization

Foth & Van Dyke Memorandum

January 9, 1995

TO: Jana Murphy, Flambeau Mining Company

CC: Tom Myatt, Flambeau Mining Company
Jim Hutchison, Foth & Van Dyke
Jerry Sevick, Foth & Van Dyke

FR: Bill West, Foth & Van Dyke *W/MW*

RE: Report on 1994 Habitat Characterization, Flambeau River, Ladysmith, Wisconsin

Introduction

On August 8, 1994, Bill West of Foth & Van Dyke conducted a habitat characterization of the Flambeau River in an area adjacent to the Flambeau Mine site. The purpose of the characterization was to provide an assessment of habitat in the Flambeau River above and below the mining site and to compare conditions in the river to those documented prior to the initiation of discharges. Habitat characterization study requirements are described in the mining application (December 1989) and approved pursuant to Docket No. IH-89-14. This report describes the habitat/substrate along the east bank of the Flambeau River from a point 100 yards above Outfall 002 to a point 1000 yards downstream of discharge Outfall 001.

Methodology

On August 8, 1994, substrates along the east bank of the Flambeau River were noted and characterized. The area of study is identified in Figure 1.

The study was initiated at 4:30 p.m. above the mining site. River stage was about four inches below bank stage and had been dropping since mid-day. Water depth and clarity were suitable to accommodate the substrate evaluation.

Stream assessment required that the stream segment between the pipeline crossing and a point 100 yards upstream of Outfall 002 be waded to physically determine condition of the substrate, amount of deposition, if any, and type of deposition, e.g., silt or larger.

Summary of Findings

Substrate descriptions were previously documented in a report submitted in January 1993 titled *Flambeau Mining Company 1992 Annual Report* (Appendix K). Conditions observed in 1994 were consistent with those documented in 1992 (Figure 2).


During 1994 field observations, it was noted that a significant amount of beaver activity had occurred above Outfall 002. The remnants of a beaver hut was located along the bank about 60 to 80 yards upstream of Outfall 002. At this same point a cluster of logs was noted in the water along the bank. Another series of logs were located about 20 yards upstream of Outfall 002. At each log cluster sediment in excess of one foot had accumulated. Photograph 1 shows the remnant of the beaver hut with cluster of logs from the hut downstream (foreground). Note also the erodible bank in this area. This bank type is continuous throughout the distance from above the beaver hut past Outfall 001. Also note that at the time of the picture, the stage had fallen about a foot and a half from levels earlier in the day.

Photograph 2 shows Outfall 002. There is no sediment on rocks throughout the entire length of the outfall. Some algae has colonized in the riprap in the wetted area of the outfall. Algal growth is consistent on rocks which are near shore as shown in Photograph 3 (near Meadowbrook Creek) and Photograph 4 (just upstream of Meadowbrook Creek). Photograph 4 is a closeup of the rock/cobble substrate showing the sand and gravel mix in the interstices.



As in previous years, the area above Outfall 002 downstream to about 150 yards below Outfall 001 is highly erodible. Soft sediments exist along shore from the bank outward from three to five feet.

The only sediment noted at Outfall 001 was that which was due to river action. Water-borne sediment had in the past been deposited on Outfall 001 as the river carried sediment up and onto the Outfall's riprap.

No sediment differences were observed from 1992 through this observation period in the area from Outfall 001 to the pipeline crossing. Stream C at Meadowbrook Creek was observed to be dry. Immediately above Meadowbrook Creek, dozens of middens (shells of mussels) were observed in the shallow water. The area below Meadowbrook Creek where previously Elodea had been located, remained, though the area covered by Elodea seemed to be expanding downstream.



FLAMBEAU MINING COMPANY	
FIGURE I	
HABITAT CHARACTERIZATION STUDY AREA	
FLAMBEAU RIVER, LADYSMITH, WI.	
Scale: 1" = 1550'	Date: JANUARY, 1993
Prepared by: Foth & Van Dyke	By: GJB



Legend

- 1 = *Vallisneria* sp. =
- 2 = *Potamogeton* sp. =
- 3 = *Elodea* sp. =
- 4 = Rock/Cobble Complex
- 5 = Rock/Cobble/Gravel Complex
- 6 = Cobble/Gravel Complex
- 7 = Gravel/Silt Complex
- 8 = Silt/Organic Matter Complex

Distance = 500 Feet

FLAMBEAU MINING COMPANY	
FIGURE 2 HABITAT CHARACTERIZATION STUDY AREA FLAMBEAU RIVER, LADYSMITH, WI	
Scale: AS SHOWN	Date: JANUARY, 1993
Prepared By: [illegible]	Date: [illegible]



Photograph 1 August 1994
Flambeau River upstream of Flambeau Mining Company Outfall 001. Note erodible bank and remnants of beaver hut with debris and sediment trailing downstream.



Photograph 2 August 1994
Flambeau River at Flambeau Mining Company outfall 002. Note no sediment from outfall but some deposition from action of river washing sediment across the mouth of outfall.



Photograph 3 August 1994
Flambeau River downstream of Flambeau Mining Company
Outfall 001, looking downstream toward confluence with
Meadowbrook Creek.



Photograph 4 August 1994
Typical Flambeau River substrate - rock/cobble/gravel substrate with
washed sediment filling interstices.

Appendix H

Results of Wetland Monitoring Efforts

Foth & Van Dyke

September 12, 1994

2737 S. Ridge Road
P. O. Box 19012
Green Bay, WI 54307-9012
414/497-2500
FAX: 414/497-8516

Ms. Jana Murphy
Flambeau Mining Company
N4100 Highway 27
Ladysmith, WI 54848

Dear Jana:

RE: Results of Wetland Monitoring Efforts for 1994


During 1994 I visited the mine site on three separate occasions to monitor the conditions of Wetland No. 1 and to assess the need for special mitigation measures at Wetland No. 1 located to the north and northwest of the open pit. These visits were made during the months of May, July, and early September. During all three visits soil conditions and general state of existing vegetation indicated that there were no adverse affects of the groundwater drawdown at Wetland No. 1 and other wetlands in the immediate vicinity of the mine site. The only exception was the lack of flow in a spring located close to the eastern border of Wetland No. 1 that had continuous flow during prior years. These observations strongly indicate that Wetland No. 1 is "perched" and vertical permeability of wetland soils is very low.

As a result of these observations it is my opinion that there is no immediate need to implement any mitigation efforts that would provide additional surface water flow to Wetland No. 1. This opinion is based upon conditions observed throughout the year at Wetland No. 1 and surrounding wetlands that are not within the area affected by the groundwater drawdown associated with the open pit. Wetlands throughout the region that previously (1987 and 1988) had some standing water interspersed throughout their area were virtually devoid of standing water at the times during 1994 when site visits were made. Staff gauge readings during 1994 indicate that conditions observed during this year were within the natural variation of conditions observed at other wetlands in the region.

Therefore the addition of mitigation water to Wetland No. 1 is not being recommended at this time. However, we believe that conditions need to be continuously monitored. A site visit in early 1995 when snow melt and spring runoff are at their peak is recommended. At that time the Flambeau Mining Company should be prepared to provide supplemental flow to the eastern side of Wetland No. 1 should conditions at that time warrant the additional water.

Sincerely,

Foth & Van Dyke


Tim J. Weyenberg
Vice President
Client Services

TJW:jap

(a3s12)91F6.flwp


Appendix I

Monitoring Well/Piezometer Construction Logs

Project Name Imbean Mine	Local Grid Location of Well 40744.2 ft. <input checked="" type="checkbox"/> N. 39,353.9 ft. <input checked="" type="checkbox"/> E <input type="checkbox"/> S. <input type="checkbox"/> W.	Well Name WW-1
License, Permit or Monitoring Number 03180	Grid Origin Location Lat. _____ Long. _____ or St. Plane _____ ft. N. _____ ft. E.	Wis. Unique Well Number _____ DNR Well Number _____
Type of Well Water Table Observation Well <input checked="" type="checkbox"/> 11 Piezometer <input type="checkbox"/> 12	Section Location of Waste/Source NW 1/4 of SE 1/4 of Sec. 9, T. 34N, R. 6 <input checked="" type="checkbox"/> E. <input type="checkbox"/> W.	Date Well Installed 05/05/94 m m d d y y
Distance Well Is From Waste/Source Boundary _____ ft.	Location of Well Relative to Waste/Source u <input type="checkbox"/> Upgradient s <input type="checkbox"/> Sidegradient d <input type="checkbox"/> Downgradient n <input type="checkbox"/> Not Known	Well Installed By: (Person's Name and Firm) Richard Kastner Kramer Well Drilling, Inc
Is this a Point of Enforcement Std. Application? <input type="checkbox"/> Yes <input type="checkbox"/> No		

Protective pipe, top elevation **1112.48** ft. MSL
Well casing, top elevation _____ ft. MSL
Ground surface elevation **1110.5** ft. MSL
Surface seal, bottom **1108.6** ft. MSL or **2.0** ft.

USCS classification of soil near screen:
GP GM GC GW SW SP
SM SC ML MH CL CH
Bedrock **Cambrian sandstone**
Sieve analysis attached? Yes No
Drilling method used: Rotary 50
Hollow Stem Auger 41
Air Hammer Other _____
Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99
Sealing additives used? Yes No
Describe _____ **NA**
Source of water (attach analysis):
NA



1. Cap and lock? Yes No
2. Protective cover pipe:
a. Inside diameter: **6.0** in.
b. Length: **17.0** ft.
c. Material: Steel 04
Other _____
d. Additional protection? Yes No
If yes, describe: _____
3. Surface seal:
Bentonite 30
Concrete 01
Other _____
4. Material between well casing and protective pipe:
Bentonite 30
Annular space seal _____
Other _____
5. Annular space seal:
a. Granular Bentonite 33
b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
c. _____ Lbs/gal mud weight . . . Bentonite slurry 31
d. _____ % Bentonite Bentonite-cement grout 50
e. _____ Ft³ volume added for any of the above
f. How installed: Tremie 01
Tremie pumped 02
Gravity 08
6. Bentonite seal:
a. Bentonite granules 33
b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
c. _____ Other _____
7. Fine sand material: Manufacturer, product name & mesh size
a. _____
b. Volume added _____ ft³
8. Filter pack material: Manufacturer, product name and mesh size
a. _____
b. Volume added _____ ft³
9. Well casing: Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other _____
10. Screen material:
a. Screen type: Factory cut 11
Continuous slot 01
Other _____
b. Manufacturer _____
c. Slot size: **0** _____
d. Slotted length: _____
11. Backfill material (below filter pack): None 14
Other _____

Bentonite seal, top _____ ft. MSL or _____ ft.
Fine sand, top _____ ft. MSL or _____ ft.
Filter pack, top _____ ft. MSL or _____ ft.
Screen joint, top _____ ft. MSL or _____ ft.
Well bottom _____ ft. MSL or _____ ft.
Filter pack, bottom _____ ft. MSL or _____ ft.
Borehole, bottom **1076.5** ft. MSL or **36.0** ft.
Borehole, diameter **7.0** in.
I.D. well casing **6.23** in.
O.D. well casing **6.00** in.

I hereby certify that the information on this form is true and correct to the best of my knowledge.
Signature **Shirley R. May** Firm **Consulting Mining Geologist**

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$500 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. This form should be kept.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flambeau Mine</u>	County Name <u>Rusk</u>	Well Name <u>WW-1</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number _____
		DNR Well Number _____

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other _____ _____
3. Time spent developing well 60 min.
4. Depth of well (from top of well casing) 36.0 ft.
5. Inside diameter of well _____ in.
6. Volume of water in filter pack and well casing _____ gal.
7. Volume of water removed from well _____ gal.
8. Volume of water added (if any) _____ gal.
9. Source of water added _____
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>16.00</u> ft.	<u>18.92</u> ft.
Date	b. <u>05/05/94</u> m m d d y y	<u>05/05/94</u> m m d d y y
Time	c. <u>4:00</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.	<u>5:00</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.
12. Sediment in well bottom	<u>/</u> inches	<u>/</u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>muddy</u>	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe) <u>almost clear.</u>
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<u>/</u> mg/l	<u>/</u> mg/l
15. COD	<u>/</u> mg/l	<u>/</u> mg/l

16. Additional comments on development:

Hole not completed with installation of screen due to lack of H₂O production.

Well developed for: Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: <u>Richard Kastner</u>	Signature: <u>Erwin R. May</u>
Firm: <u>Kramer Well Drilling, Inc</u>	Print Initials: <u>ERM</u>
	Firm: <u>Consulting Mining Geologist</u>

Well Name: WW-2

Wis. Unique Well Number: _____ DNR Well Number: _____

Date Well Installed: 05/05/94
m m d d y y


Well Installed By: (Person's Name and Firm)
Richard Kastner
Kramer Well Drilling, Inc

Local Grid Location of Well: 40671.4 ft. N. 39,253.2 ft. E.
Grid Origin Location: _____

St. Plane: _____ ft. N. _____ ft. E.

Section Location of Waste/Source: NW 1/4 of SE 1/4 of Sec. 9, T. 34N, R. 6

Location of Well Relative to Waste/Source:
u Upgradient s Sidegradient
d Downgradient n Not Known



I hereby certify that the information on this form is true and correct to the best of my knowledge.

Signature: Shirley R. May Firm: Consulting Mining Geologist.

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$100,000 for each violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each violation.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flambeau Mine</u>	County Name <u>Rusk</u>	Well Name <u>WW-2</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number _____
		DNR Well Number _____

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other _____
3. Time spent developing well 30 min.
4. Depth of well (from top of well casing) 47.4 ft.
5. Inside diameter of well 6.00 in.
6. Volume of water in filter pack and well casing 0.0 gal.
7. Volume of water removed from well 230.0 gal.
8. Volume of water added (if any) 0.0 gal.
9. Source of water added NA
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>25.5</u> ft.	<u>28.65</u> ft.
Date	b. <u>05/06/94</u> m m d d y y	<u>05/06/94</u> m m d d y y
Time	c. <u>11:30</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u>12:00</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<u>/</u> inches	<u>/</u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>muddy</u>	Clear <input type="checkbox"/> 20 Turbid <input checked="" type="checkbox"/> 25 (Describe) <u>muddy</u>
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<u>/</u> mg/l	<u>/</u> mg/l
15. COD	<u>/</u> mg/l	<u>/</u> mg/l

16. Additional comments on development:

Well developed by: Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: <u>Richard Kastner</u>	Signature: <u>Edward R. May</u>
Firm: <u>Kramer Well Drilling, Inc</u>	Print Initials: <u>ERM</u>
	Title: <u>Consulting Mining Geologist.</u>


NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

Project Name: Flambeau Mine
 License, Permit or Monitoring Number: 03180
 Type of Well: Water Table Observation Well 11
 Piezometer 12
 Distance Well Is From Waste/Source Boundary: _____ ft.
 Well A Point of Enforcement Std. Application? Yes No

Local Grid Location of Well: 39754.0 ft. N. S. 39018.4 ft. E. W
 Grid Origin Location: _____
 Lat. _____ Long. _____
 St. Plane _____ ft. N. _____ ft. E.
 Section Location of Waste/Source: SW 1/4 of SE 1/4 of Sec. 9, T. 34 N, R. 6 E. W
 Location of Well Relative to Waste/Source:
 u Upgradient s Sidegradient
 d Downgradient n Not Known

Well Name: 104-9
 Wis. Unique Well Number: _____ DNR Well Number: _____
 Date Well Installed: 08/22/94
 Well Installed By: (Person's Name and Firm)
Jim Hackney
Amas Construction Co

Protective pipe, top elevation: _____ ft. MSL
 Well casing, top elevation: 1045.73 ft. MSL
 Casing and surface elevation: 1042.0 ft. MSL
 Surface seal, bottom: _____ ft. MSL or 0.0 ft.
 USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock
 Sieve analysis attached? Yes No
 Drilling method used: Rotary 50
Perussion Hollow Stem Auger 41
 Other
 Drilling fluid used: Water 02 Air 01
 Drilling Mud 03 None 99
 Sealing additives used? Yes No
 Describe: NA
 Source of water (attach analysis): NA



1. Cap and lock? capped Yes No
 2. Protective cover pipe:
 a. Inside diameter: _____ in.
 b. Length: _____ ft.
 c. Material: Steel 04
None Other
 d. Additional protection? Yes No
 If yes, describe: _____
 3. Surface seal:
 Bentonite 30
 Concrete 01
 Other
 4. Material between well casing and protective pipe:
 Bentonite 30
entire hole Annular space seal
0.25" washed pea gravel Other
 5. Annular space seal:
 a. Granular Bentonite 33
 b. _____ Lbs/gal mud weight ... Bentonite-sand slurry 35
 c. _____ Lbs/gal mud weight ... Bentonite slurry 31
 d. _____ % Bentonite ... Bentonite-cement grout 50
 e. _____ Ft³ volume added for any of the above
 f. How installed: Tremie 01
 Tremie pumped 02
 Gravity 08
 6. Bentonite seal:
 a. Bentonite granules 33
 b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
 c. _____ Other
 7. Fine sand material: Manufacturer, product name & mesh size
 a. _____
 b. Volume added _____ ft³
 8. Filter pack material: Manufacturer, product name and mesh size
 a. _____
 b. Volume added _____ ft³
 9. Well casing: Flush threaded PVC schedule 40 23
 Flush threaded PVC schedule 80 24
 Other
 10. Screen material: PVC
 a. Screen type: Factory cut 11
 Continuous slot 01
0.25" hole drilled every 4" Other
 b. Manufacturer _____
 c. Slot size: _____ in.
 d. Slotted length: _____ ft.
 11. Backfill material (below filter pack): None 14
 Other

Bentonite seal, top: _____ ft. MSL or _____ ft.
 Fine sand, top: _____ ft. MSL or _____ ft.
 Filter pack, top: _____ ft. MSL or _____ ft.
 Screen joint, top: _____ ft. MSL or _____ ft.
 Well bottom: _____ ft. MSL or 460 ft.
 Filter pack, bottom: _____ ft. MSL or 460 ft.
 Borehole, bottom: _____ ft. MSL or 460 ft.
 Borehole, diameter: 3.5 in.
 I.D. well casing: 2.37 in.
 O.D. well casing: 2.02 in.

I hereby certify that the information on this form is true and correct to the best of my knowledge.
 Signature: Shirley R. May Firm: Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. See instructions for more information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <i>Flambeau Mine</i>	County Name <i>Rusk</i>	Well Name <i>104-9</i>
Facility License, Permit or Monitoring Number <i>03180</i>	County Code <i>55</i>	AVIS Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other
3. Time spent developing well 0 min.
4. Depth of well (from top of well casing) 46.0 ft.
5. Inside diameter of well 2.02 in.
6. Volume of water in filter pack and well casing _____ gal.
7. Volume of water removed from well _____ gal.
8. Volume of water added (if any) _____ gal.
9. Source of water added _____
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>10.00</u> ft.	<u>00.00</u> ft.
Date	b. <u>08/22/94</u> m m d d y y	<u> </u> / <u> </u> / <u> </u> m m d d y y
Time	c. <u> </u> : <u> </u> : <u> </u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u> </u> : <u> </u> : <u> </u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<u> </u> inches	<u> </u> inches
13. Water clarity	Clear <input checked="" type="checkbox"/> 10 Turbid <input type="checkbox"/> 15 (Describe)	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe)
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<u> </u> mg/l	<u> </u> mg/l
15. COD	<u> </u> mg/l	<u> </u> mg/l

16. Additional comments on development:
Drilled into footwall of "B" lens - close to (within 5') of "B"

Well developed by: Person's Name and Firm

Name: Jim Hadeney

Firm: Ames Construction Co

I hereby certify that the above information is true and correct to the best of my knowledge.


Signature: Shirley R. May

Print Initials: ERM

Firm: Consulting Mining Geologist

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

City/Project Name <u>Flambeau Mine</u>	Local Grid Location of Well 39757.1 ft. <input type="checkbox"/> N. <input type="checkbox"/> S. 39012.8 ft. <input type="checkbox"/> E. <input type="checkbox"/> W.	Well Name <u>104-10</u>
Permit or Monitoring Number <u>03180</u>	Grid Origin Location Lat. _____ Long. _____ or St. Plane _____ ft. N. _____ ft. E.	Wis. Unique Well Number _____ DNR Well Number _____
Type of Well Water Table Observation Well <input checked="" type="checkbox"/> 11 Piezometer <input type="checkbox"/> 12	Section Location of Waste/Source <u>SW 1/4 of SE 1/4 of Sec. 9, T. 34N, R. 6</u> <input type="checkbox"/> E. <input checked="" type="checkbox"/> W.	Date Well Installed <u>08/23/94</u> m m d d y y
Distance Well Is From Waste/Source Boundary _____ ft.	Location of Well Relative to Waste/Source u <input type="checkbox"/> Upgradient s <input type="checkbox"/> Sidegradient d <input type="checkbox"/> Downgradient n <input type="checkbox"/> Not Known	Well Installed By: (Person's Name and Firm) <u>Jim Hackney</u> <u>Ames Construction Co</u>
Well A Point of Enforcement Std. Application? <input type="checkbox"/> Yes <input type="checkbox"/> No		Capped <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No



Protective pipe, top elevation _____ ft. MSL

Well casing, top elevation 1044.08 ft. MSL

Ground surface elevation 1041.6 ft. MSL

Surface seal, bottom _____ ft. MSL or _____ ft.

USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock

Sieve analysis attached? Yes No

Drilling method used: Rotary 50
 Hollow Stem Auger 41
Asi Hammer Other

Drilling fluid used: Water 02 Air 01
 Drilling Mud 03 None 99

Sealing additives used? Yes No

Describe _____ NA

Source of water (attach analysis): _____ NA

Bentonite seal, top _____ ft. MSL or _____ ft.

Fine sand, top _____ ft. MSL or _____ ft.

Filter pack, top _____ ft. MSL or _____ ft.

Screen joint, top _____ ft. MSL or _____ ft.

Well bottom _____ ft. MSL or 42.0 ft.

Filter pack, bottom _____ ft. MSL or 47.0 ft.

Borehole, bottom _____ ft. MSL or 47.0 ft.

Borehole, diameter 3.5 in.

O.D. well casing 2.37 in.

Well casing 2.02 in.

1. Cap and lock? Capped Yes No

2. Protective cover pipe:
 a. Inside diameter: _____ in.
 b. Length: _____ ft.
 c. Material: _____ Steel 04
NONE Other
 d. Additional protection? Yes No
 If yes, describe: _____

3. Surface seal:
 Bentonite 30
 Concrete 01
 Other

4. Material between well casing and protective pipe:
 Bentonite 30
Entire Hole Annular space seal
0.25" Washed Pea Gravel Other

5. Annular space seal:
 a. Granular Bentonite 33
 _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
 _____ Lbs/gal mud weight . . . Bentonite slurry 31
 _____ % Bentonite Bentonite-cement grout 50
 e. _____ Ft³ volume added for any of the above
 f. How installed: Tremie 01
 Tremie pumped 02
 Gravity 08

6. Bentonite seal:
 a. Bentonite granules 33
 b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
 c. _____ Other

7. Fine sand material: Manufacturer, product name & mesh size
 a. _____
 b. Volume added _____ ft³

8. Filter pack material: Manufacturer, product name and mesh size
 a. _____
 b. Volume added _____ ft³

9. Well casing: Flush threaded PVC schedule 40 23
 Flush threaded PVC schedule 80 24
 Other

10. Screen material: PVC
 a. Screen type: Factory cut 11
 Continuous slot 01
0.25" hole drilled every 4" Other
 b. Manufacturer _____
 c. Slot size: _____ in.
 d. Slotted length: _____ ft.

11. Backfill material (below filter pack): None 14
 Other

I hereby certify that the information on this form is true and correct to the best of my knowledge.

Signature Arvade R. Army Firm Consulting mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. See instructions for more information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Hamblan Mine</u>	County Name <u>Rusk</u>	Well Name <u>104-10</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other
3. Time spent developing well 0 min.
4. Depth of well (from top of well casing) 47.0 ft.
5. Inside diameter of well 2.02 in.
6. Volume of water in filter pack and well casing 0 gal.
7. Volume of water removed from well 0 gal.
8. Volume of water added (if any) 0 gal.
9. Source of water added NA
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>18.00</u> ft.	<u>00.00</u> ft.
Date	b. <u>08/23/94</u> m m d d y y	<u> / / </u> m m d d y y
Time	c. <u> : </u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u> : </u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<u> </u> inches	<u> </u> inches
13. Water clarity	Clear <input checked="" type="checkbox"/> 10 Turbid <input type="checkbox"/> 15 (Describe)	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe)

Fill in if drilling fluids were used and well is at solid waste facility:

14. Total suspended solids	<u> </u> mg/l	<u> </u> mg/l
15. COD	<u> </u> mg/l	<u> </u> mg/l

16. Additional comments on development:
Artesian ≈ 0.2 gpm visual estimate. Drilled into "B"

Well developed by: Person's Name and Firm

Name: Jim Hackney

Firm: Ames Construction Co

I hereby certify that the above information is true and correct to the best of my knowledge.

Signature: Shirley R. May

Print Initials: ERM

Firm: Consulting ~~Co~~ Mine Geologist

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

City/Project Name: Flambeau Mine
 Well Name: 104-11
 Permit or Monitoring Number: 03180
 Local Grid Location of Well: 39761.6 ft. N. S. 39007.5 ft. E. W.
 Grid Origin Location: _____
 Lat. _____ Long. _____ or _____
 Date Well Installed: 08/23/94
 m m d d y y
 Well Installed By: (Person's Name and Firm) Jim Hackney
Ames Construction Co
 Type of Well: Water Table Observation Well 11
 Piezometer 12
 Distance Well Is From Waste/Source Boundary: _____ ft.
 Section Location of Waste/Source: SW 1/4 of SE 1/4 of Sec. 9, T. 34 N, R. 6 E. W.
 Location of Well Relative to Waste/Source:
 u Upgradient s Sidegradient
 d Downgradient n Not Known
 Well A Point of Enforcement Std. Application?
 Yes No

Protective pipe, top elevation _____ ft. MSL
 Well casing, top elevation 1095.29 ft. MSL
 and surface elevation 1091.2 ft. MSL
 Surface seal, bottom _____ ft. MSL or _____ ft.
 USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock
 Sieve analysis attached? Yes No
 Drilling method used: Rotary 50
Percussion Hollow Stem Auger 41
 Other
 Drilling fluid used: Water 02 Air 01
 Drilling Mud 03 None 99
 Additives used? Yes No
 Describe: NA
 Source of water (attach analysis): NA

1. Cap and lock? Capped Yes No
 2. Protective cover pipe:
 a. Inside diameter: _____ in.
 b. Length: _____ ft.
 c. Material: _____ Steel 04
 Other
NONE
 d. Additional protection? Yes No
 If yes, describe: _____
 3. Surface seal:
 Bentonite 30
 Concrete 01
 Other
 4. Material between well casing and protective pipe:
 Bentonite 30
Entire Hole Annular space seal
0.25" Washed Pea Gravel Other
 5. Annular space seal:
 a. Granular Bentonite 33
 b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
 c. _____ Lbs/gal mud weight . . . Bentonite slurry 31
 d. _____ % Bentonite Bentonite-cement grout 50
 e. _____ Ft³ volume added for any of the above
 f. How installed: Tremie 01
 Tremie pumped 02
 Gravity 08
 6. Bentonite seal:
 a. Bentonite granules 33
 b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
 c. _____ Other
 7. Fine sand material: Manufacturer, product name & mesh size
 a. _____
 b. Volume added _____ ft³
 8. Filter pack material: Manufacturer, product name and mesh size
 a. _____
 b. Volume added _____ ft³
 9. Well casing: Flush threaded PVC schedule 40 23
 Flush threaded PVC schedule 80 24
 Other
 10. Screen material: PVC
 a. Screen type: Factory cut 11
 Continuous slot 01
0.25" Hole Drilled every 4" Other
 b. Manufacturer _____
 c. Slot size: _____ in.
 d. Slotted length: _____ ft.
 11. Backfill material (below filter pack): None 14
 Other

Bentonite seal, top _____ ft. MSL or _____ ft.
 Fine sand, top _____ ft. MSL or _____ ft.
 Filter pack, top _____ ft. MSL or _____ ft.
 Screen joint, top _____ ft. MSL or _____ ft.
 Well bottom _____ ft. MSL or 36.0 ft.
 Filter pack, bottom _____ ft. MSL or 36.0 ft.
 Borehole, bottom _____ ft. MSL or 36.0 ft.
 Borehole, diameter 3.5 in.
 O.D. well casing 2.37 in.
 Well casing 2.02 in.

I hereby certify that the information on this form is true and correct to the best of my knowledge.
 Signature: Edward R. May Firm: Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. See instructions for more information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flambeau Mine</u>	County Name <u>Rusk</u>	Well Name <u>104-11</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No

2. Well development method

surged with bailer and bailed	<input type="checkbox"/>	41
surged with bailer and pumped	<input type="checkbox"/>	61
surged with block and bailed	<input type="checkbox"/>	42
surged with block and pumped	<input type="checkbox"/>	62
surged with block, bailed and pumped	<input type="checkbox"/>	70
compressed air	<input type="checkbox"/>	20
bailed only	<input type="checkbox"/>	10
pumped only	<input type="checkbox"/>	51
pumped slowly	<input type="checkbox"/>	50
Other	<input type="checkbox"/>	

3. Time spent developing well 0 min.

4. Depth of well (from top of well casing) 36.0 ft.

5. Inside diameter of well 2.02 in.

6. Volume of water in filter pack and well casing 0 gal.

7. Volume of water removed from well 0 gal.

8. Volume of water added (if any) 0 gal.

9. Source of water added NA

10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>12.00</u> ft.	<u>0.00</u> ft.
Date	b. <u>08/23/94</u> m m d d y y	<u>1/1</u> m m d d y y
Time	c. <u>/</u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u>/</u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<u>/</u> inches	<u>/</u> inches
13. Water clarity	Clear <input checked="" type="checkbox"/> 10 Turbid <input type="checkbox"/> 15 (Describe)	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe)
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<u>/</u> mg/l	<u>/</u> mg/l
15. COD	<u>/</u> mg/l	<u>/</u> mg/l

16. Additional comments on development:
Artesian ≈ 0.1 gpm visual estimate. Collared into "B" lens.
Hit "B" FW @ ≈ 12'

Well developed by: Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: <u>Jim Hackney</u>	Signature: <u>Shrode B. May</u>
Firm: <u>Ames Construction Co</u>	Print Initials: <u>ERM</u>
	Firm: <u>Consulting Mining Geologist</u>

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

City/Project Name
Ambean Mine

License, Permit or Monitoring Number
03180

Type of Well
Water Table Observation Well 11
Piezometer 12

Distance Well Is From Waste/Source Boundary
ft. _____

Well A Point of Enforcement Std. Application?
 Yes No

Local Grid Location of Well
39769.1 ft. N. S. 38997.4 ft. E. W.

Grid Origin Location
Lat. _____ Long. _____ or _____

St. Plane _____ ft. N. _____ ft. E.

Section Location of Waste/Source
SW 1/4 of SE 1/4 of Sec. 9, T. 34 N, R. 6 E. W.

Location of Well Relative to Waste/Source
u Upgradient s Sidegradient
d Downgradient n Not Known

Well Name
104-12

Wis. Unique Well Number _____ DNR Well Number _____

Date Well Installed
08/23/94
m m d d y y

Well Installed By: (Person's Name and Firm)
Jim Hackney
Ames Construction Co

Capped Yes No

Protective pipe, top elevation _____ ft. MSL

Well casing, top elevation 1045.27 ft. MSL

_____ and surface elevation 1041.3 ft. MSL

Surface seal, bottom _____ ft. MSL or _____ ft.

USCS classification of soil near screen:
GP GM GC GW SW SP
SM SC ML MH CL CH
Bedrock


Sieve analysis attached? Yes No

Drilling method used:
Rotary 50
Hollow Stem Auger 41
Per percussion Other

Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99

Sealing additives used? Yes No
Describe NA

Source of water (attach analysis):
NA



1. Cap and lock? Capped Yes No

2. Protective cover pipe:
a. Inside diameter: _____ in.
b. Length: _____ ft.
c. Material: _____ Steel 04
NONE Other
d. Additional protection? Yes No
If yes, describe: _____

3. Surface seal: _____
Bentonite 30
Concrete 01
Other

4. Material between well casing and protective pipe:
Entire Hole Bentonite 30
0.25" Washed Pea Gravel Annular space seal
Other

5. Annular space seal:
a. Granular Bentonite 33
b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
c. _____ Lbs/gal mud weight Bentonite slurry 31
d. _____ % Bentonite Bentonite-cement grout 50
e. _____ Ft³ volume added for any of the above
f. How installed: Tremie 01
Tremie pumped 02
Gravity 08

6. Bentonite seal:
a. Bentonite granules 33
b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
c. _____ Other

7. Fine sand material: Manufacturer, product name & mesh size
a. _____
b. Volume added _____ ft³

8. Filter pack material: Manufacturer, product name and mesh size
a. _____
b. Volume added _____ ft³

9. Well casing: Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other

10. Screen material: PVC
a. Screen type: Factory cut 11
Continuous slot 01
0.25" Hole Drilled every 4" Other
b. Manufacturer _____
c. Slot size: _____ in.
d. Slotted length: _____ ft.

11. Backfill material (below filter pack): None 14
Other

Bentonite seal, top _____ ft. MSL or _____ ft.

Fine sand, top _____ ft. MSL or _____ ft.

Filter pack, top _____ ft. MSL or _____ ft.

Screen joint, top _____ ft. MSL or _____ ft.

Well bottom _____ ft. MSL or 36.0 ft.

Filter pack, bottom _____ ft. MSL or 36.0 ft.

Borehole, bottom _____ ft. MSL or 36.0 ft.

Borehole, diameter 3.5 in.

O.D. well casing 2.37 in.

I.D. well casing 2.02 in.

I hereby certify that the information on this form is true and correct to the best of my knowledge.

Signature Edward R. May Firm Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. See instructions for more information including where the completed form should be sent.

Route 10: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <i>Flambeau Mine</i>	County Name <i>Rusk</i>	Well Name <i>104-12</i>	
Facility License, Permit or Monitoring Number <i>03180</i>	County Code <i>55</i>	Wis. Unique Well Number	DNR Well Number

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other
3. Time spent developing well *0* min.
4. Depth of well (from top of well casing) *36.0* ft.
5. Inside diameter of well *2.02* in.
6. Volume of water in filter pack and well casing *0* gal.
7. Volume of water removed from well *0* gal.
8. Volume of water added (if any) *0* gal.
9. Source of water added *NA*
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <i>0.0</i> ft.	<i>0.0</i> ft.
Date	b. <i>08/23/97</i> m m d d y y	<i>1/1/</i> m m d d y y
Time	c. <i>/</i> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<i>/</i> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<i>/</i> inches	<i>/</i> inches
13. Water clarity	Clear <input checked="" type="checkbox"/> 10 Turbid <input type="checkbox"/> 15 (Describe)	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe)
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<i>/</i> mg/l	<i>/</i> mg/l
15. COD	<i>/</i> mg/l	<i>/</i> mg/l

16. Additional comments on development:
Artesian ≈ 1.5 gpm. Collared in QSS; hit top of "B" lens at ≈ 2'.

Well developed by: Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: <i>Jim Hackney</i>	Signature: <i>Shirley R. May</i>
Firm: <i>Ames Construction Co</i>	Print Initials: <i>ERM</i>
	Firm: <i>Consulting Mining Geologist</i>


NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

State of Wisconsin
Department of Natural Resources

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

City/Project Name: Lambeau Mine
 License, Permit or Monitoring Number: 03180
 Type of Well: Water Table Observation Well 11
 Piezometer 12
 Distance Well Is From Waste/Source Boundary: _____ ft.
 Well A Point of Enforcement Std. Application? Yes No
 Local Grid Location of Well: 39780.4 ft. N, 38985.7 ft. E
 Grid Origin Location: _____
 Lat. _____ Long. _____
 St. Plane _____ ft. N, _____ ft. E
 Section Location of Waste/Source: SW 1/4 of SE 1/4 of Sec. 9, T. 34 N, R. 6
 Location of Well Relative to Waste/Source:
 u Upgradient s Sidegradient
 d Downgradient n Not Known
 Well Name: 104-13
 Wis. Unique Well Number: _____ DNR Well Number: _____
 Date Well Installed: 08/23/94
 Well Installed By: (Person's Name and Firm)
Jim Hackney
Ames Construction Co

Protective pipe, top elevation _____ ft. MSL
 Well casing, top elevation 1042.23 ft. MSL
 Land surface elevation 1041.2 ft. MSL
 Surface seal, bottom _____ ft. MSL or _____ ft.
 2. USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock
 3. Sieve analysis attached? Yes No
 4. Drilling method used: Rotary 50
 Hollow Stem Auger 41
Percussion Other
 5. Drilling fluid used: Water 02 Air 01
 Drilling Mud 03 None 99
 6. Sealing additives used? Yes No
 Describe: NA
 7. Source of water (attach analysis):
NA



1. Cap and lock? Capped Yes No
 2. Protective cover pipe:
 a. Inside diameter: _____ in.
 b. Length: _____ ft.
 c. Material: _____ Steel 04
 Other
NONE
 d. Additional protection? Yes No
 If yes, describe: _____
 3. Surface seal:
 Bentonite 30
 Concrete 01
 Other
 4. Material between well casing and protective pipe:
Entire Hole Bentonite 30
0.25" Washed Pea Gravel Annular space seal
 Other
 5. Annular space seal:
 a. Granular Bentonite 33
 b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
 c. _____ Lbs/gal mud weight Bentonite slurry 31
 d. _____ % Bentonite Bentonite-cement grout 50
 e. _____ Ft³ volume added for any of the above
 f. How installed:
 Tremie 01
 Tremie pumped 02
 Gravity 08
 6. Bentonite seal:
 a. Bentonite granules 33
 b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
 c. _____ Other
 7. Fine sand material: Manufacturer, product name & mesh size
 a. _____
 b. Volume added _____ ft³
 8. Filter pack material: Manufacturer, product name and mesh size
 a. _____
 b. Volume added _____ ft³
 9. Well casing:
 Flush threaded PVC schedule 40 23
 Flush threaded PVC schedule 80 24
 Other
 10. Screen material: PVC
 a. Screen type:
 Factory cut 11
 Continuous slot 01
0.25" Hole Drilled every 4" Other
 b. Manufacturer _____
 c. Slot size: _____ in.
 d. Slotted length: _____ ft.
 11. Backfill material (below filter pack):
 None 14
 Other

2. Bentonite seal, top _____ ft. MSL or _____ ft.
 3. Fine sand, top _____ ft. MSL or _____ ft.
 4. Filter pack, top _____ ft. MSL or _____ ft.
 5. Screen joint, top _____ ft. MSL or _____ ft.
 6. Well bottom _____ ft. MSL or 320 ft.
 7. Filter pack, bottom _____ ft. MSL or 320 ft.
 8. Borehole, bottom _____ ft. MSL or 320 ft.
 9. Borehole, diameter 3.5 in.
 10. O.D. well casing 8.37 in.
 11. I.D. well casing 2.02 in.

I, Shane R. May, hereby certify that the information on this form is true and correct to the best of my knowledge.
 Signature: _____ Firm: Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name Flambeau Mine	County Name Rusk	Well Name 104-13
Facility License, Permit or Monitoring Number 03180	County Code 55	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other
3. Time spent developing well 0 min.
4. Depth of well (from top of well casing) 32.0 ft.
5. Inside diameter of well 2.02 in.
6. Volume of water in filter pack and well casing 0 gal.
7. Volume of water removed from well 0 gal.
8. Volume of water added (if any) 0 gal.
9. Source of water added NA
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>32.0</u> ft.	_____ ft.
Date	b. <u> </u> / <u> </u> / <u> </u> m m d d y y	_____ / _____ / _____ m m d d y y
Time	c. <u> </u> : <u> </u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.	_____ : _____ <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	_____ inches	_____ inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input type="checkbox"/> 15 (Describe)	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe)
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	_____ mg/l	_____ mg/l
15. COD	_____ mg/l	_____ mg/l


16. Additional comments on development:
**Collared in QSS. Hit "B" Hanging wall at 22-28'
This zone contained chert, MS & water.**

Well developed by: Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: <u>Jim Hackney</u>	Signature: <u>[Signature]</u>
Firm: <u>Ames Construction Co</u>	Print Initials: <u>ERM</u>
	Firm: <u>Consulting Mining Geologist</u>

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

City/Project Name: Flambeau Mine
 License, Permit or Monitoring Number: 03180
 Type of Well: Water Table Observation Well 11
 Piezometer 12
 Distance Well Is From Waste/Source Boundary: _____ ft.
 Well A Point of Enforcement Std. Application? Yes No
 Local Grid Location of Well: 39,786.2 ft. N. S. 38,978.1 ft. E. W.
 Grid Origin Location: _____
 St. Plane: _____ ft. N. _____ ft. E.
 Section Location of Waste/Source: SW 1/4 of SE 1/4 of Sec. 9, T. 34 N. R. 6 E. W.
 Location of Well Relative to Waste/Source: Upgradient Sidegradient Downgradient Not Known
 Well Name: 104 - 14
 Wis. Unique Well Number: _____ DNR Well Number: _____
 Date Well Installed: 08/23/94
 Well Installed By: (Person's Name and Firm) Jim Hackney
Ames Construction Co

Protective pipe, top elevation _____ ft. MSL
 Well casing, top elevation 1044.63 ft. MSL
 Casing and surface elevation 1041.0 ft. MSL
 Surface seal, bottom _____ ft. MSL or _____ ft.
 USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock
 Sieve analysis attached? Yes No
 Drilling method used: Rotary 50
 Hollow Stem Auger 41
Perussion Other
 Drilling fluid used: Water 02 Air 01
 Drilling Mud 03 None 99
 Sealing additives used? Yes No
 Describe: NA
 Source of water (attach analysis): NA



1. Cap and lock? Capped Yes No
 2. Protective cover pipe:
 a. Inside diameter: _____ in.
 b. Length: _____ ft.
 c. Material: _____ Steel 0.4
 Other
NONE
 d. Additional protection? Yes No
 If yes, describe: _____
 3. Surface seal: Bentonite 3.0
 Concrete 0.1
 Other
 4. Material between well casing and protective pipe:
Entire Hole Bentonite 3.0
0.25" Washed Pea Gravel Annular space seal
 Other
 5. Annular space seal:
 a. Granular Bentonite 3.3
 b. _____ Lbs/gal mud weight ... Bentonite-sand slurry 3.5
 c. _____ Lbs/gal mud weight ... Bentonite slurry 3.1
 d. _____ % Bentonite ... Bentonite-cement grout 5.0
 e. _____ Ft³ volume added for any of the above
 f. How installed: Tremie 0.1
 Tremie pumped 0.2
 Gravity 0.8
 6. Bentonite seal:
 a. Bentonite granules 3.3
 b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 3.2
 c. _____ Other
 7. Fine sand material: Manufacturer, product name & mesh size
 a. _____
 b. Volume added _____ ft³
 8. Filter pack material: Manufacturer, product name and mesh size
 a. _____
 b. Volume added _____ ft³
 9. Well casing: Flush threaded PVC schedule 40 2.3
 Flush threaded PVC schedule 80 2.4
 Other
 10. Screen material: PVC
 a. Screen type: Factory cut 1.1
 Continuous slot 0.1
0.25" Hole drilled every 4" Other
 b. Manufacturer _____
 c. Slot size: _____ in.
 d. Slotted length: _____ ft.
 11. Backfill material (below filter pack): None 1.4
 Other

I hereby certify that the information on this form is true and correct to the best of my knowledge.
 Signature: Grande R. May Firm: Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flambean Mine</u>	County Name <u>Rusk</u>	Well Name <u>104-14</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other
3. Time spent developing well 0 min.
4. Depth of well (from top of well casing) 36.0 ft.
5. Inside diameter of well 2.02 in.
6. Volume of water in filter pack and well casing 0 gal.
7. Volume of water removed from well 0 gal.
8. Volume of water added (if any) 0 gal.
9. Source of water added NA
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>/</u> ft.	_____ ft.
Date	b. <u>/ /</u> m m d d y y	_____ / _____ / _____ m m d d y y
Time	c. <u>/</u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.	_____ : _____ <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	_____ inches	_____ inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe)	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe)
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<u>/</u> mg/l	_____ mg/l
15. COD	<u>/</u> mg/l	_____ mg/l

16. Additional comments on development:
Drilled into QSS

Well developed by: Person's Name and Firm

Name: Jim Hackney

Firm: Ames Construction CO

I hereby certify that the above information is true and correct to the best of my knowledge.

Signature: Shwade R. May


Print Initials: ERM

Firm: Consulting Mining Geologist.

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

Project Name: Lambeau Mine
License, Permit or Monitoring Number: 03180
Type of Well: Water Table Observation Well 11
Piezometer 12
Distance Well Is From Waste/Source Boundary: _____ ft.
Well A Point of Enforcement Std. Application? Yes No
Local Grid Location of Well: 39791.8 ft. N. S. 38972.8 ft. E. W.
Grid Origin Location: _____
Lat. _____ Long. _____ or
St. Plane _____ ft. N. _____ ft. E.
Section Location of Waste/Source: SW 1/4 of SE 1/4 of Sec. 9, T. 34N, R. 6 E. W.
Location of Well Relative to Waste/Source: u Upgradient s Sidegradient
d Downgradient n Not Known
Well Name: 104-15
Wis. Unique Well Number: _____ DNR Well Number: _____
Date Well Installed: 08/23/94
Well Installed By: (Person's Name and Firm) Jim Hackney
Ames Construction Co

Protective pipe, top elevation _____ ft. MSL
Well casing, top elevation 1043.48 ft. MSL
Ground surface elevation 1041.5 ft. MSL
Surface seal, bottom _____ ft. MSL or _____ ft.
USCS classification of soil near screen:
GP GM GC GW SW SP
SM SC ML MH CL CH
Bedrock
1. Sieve analysis attached? Yes No
2. Drilling method used: Rotary 50
Hollow Stem Auger 41
Percussion Other
3. Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99
4. Sealing additives used? Yes No
Describe: NA
7. Source of water (attach analysis): NA



1. Cap and lock? Cap Yes No
2. Protective cover pipe:
a. Inside diameter: _____ in.
b. Length: _____ ft.
c. Material: _____ Steel 04
NONE Other
d. Additional protection? Yes No
If yes, describe: _____
3. Surface seal: _____ Bentonite 30
Concrete 01
Other
4. Material between well casing and protective pipe:
Entire Hole Bentonite 30
Annular space seal
0.25" Washed Pea Gravel Other
5. Annular space seal:
a. Granular Bentonite 33
b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
c. _____ Lbs/gal mud weight Bentonite slurry 31
d. _____ % Bentonite Bentonite-cement grout 50
e. _____ Ft³ volume added for any of the above
f. How installed: Tremie 01
Tremie pumped 02
Gravity 08
6. Bentonite seal: a. Bentonite granules 33
b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
c. _____ Other
7. Fine sand material: Manufacturer, product name & mesh size
a. _____
b. Volume added _____ ft³
8. Filter pack material: Manufacturer, product name and mesh size
a. _____
b. Volume added _____ ft³
9. Well casing: Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other
10. Screen material: PVC
a. Screen type: Factory cut 11
Continuous slot 01
0.25" Hole Drilled every 4" Other
b. Manufacturer _____
c. Slot size: _____ in.
d. Slotted length: _____ ft.
11. Backfill material (below filter pack): None 14
Other

12. Bentonite seal, top _____ ft. MSL or _____ ft.
13. Fine sand, top _____ ft. MSL or _____ ft.
14. Filter pack, top _____ ft. MSL or _____ ft.
15. Screen joint, top _____ ft. MSL or _____ ft.
16. Well bottom _____ ft. MSL or 32.0 ft.
17. Filter pack, bottom _____ ft. MSL or 32.0 ft.
18. Borehole, bottom _____ ft. MSL or 32.0 ft.
19. Borehole, diameter 3.5 in.
20. O.D. well casing 2.37 in.
21. Well casing 2.02 in.

I, Shirley R. May, certify that the information on this form is true and correct to the best of my knowledge.
Signature: _____ Firm: Consulting Mining Geologist.

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. See instructions for more information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <i>Flambeau Mine</i>	County Name <i>Rusk</i>	Well Name <i>104-15</i>
Facility License, Permit or Monitoring Number <i>03180</i>	County Code <i>55</i>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other
3. Time spent developing well 0 min.
4. Depth of well (from top of well casing) 37.0 ft.
5. Inside diameter of well 2.02 in.
6. Volume of water in filter pack and well casing 0 gal.
7. Volume of water removed from well 0 gal.
8. Volume of water added (if any) 0 gal.
9. Source of water added NA
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u> </u> ft.	<u> </u> ft.
Date	b. <u> / / </u> m m d d y y	<u> / / </u> m m d d y y
Time	c. <u> : </u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u> : </u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<u> </u> inches	<u> </u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe)	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe)
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<u> </u> mg/l	<u> </u> mg/l
15. COD	<u> </u> mg/l	<u> </u> mg/l

16. Additional comments on development:
Collared into F.L. of the "A" lens.

Well developed by: Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: _____	Signature: <u><i>Shirley A. May</i></u>
Firm: _____	Print Initials: <u>ERM</u>
	Firm: <u>Consulting Mining Geologist</u>

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.


Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

City/Project Name
Flambeau Mine
Well Name
104-16
Well Permit or Monitoring Number
03180
Type of Well
Water Table Observation Well 11
Piezometer 12
Distance Well Is From Waste/Source Boundary
ft.
Well A Point of Enforcement Std. Application?
 Yes No

Local Grid Location of Well
39828.5 ft. N. S. 38,929.6 ft. E. W.
Grid Origin Location
Lat. _____ Long. _____ or
St. Plane _____ ft. N. _____ ft. E.
Section Location of Waste/Source
SW 1/4 of SE 1/4 of Sec. 9, T. 34 N., R. 6 E. W.
Location of Well Relative to Waste/Source
u Upgradient s Sidegradient
d Downgradient n Not Known

Well Name
104-16
Wis. Unique Well Number _____ DNR Well Number _____
Date Well Installed
08/23/97
m m d d y y
Well Installed By: (Person's Name and Firm)
Jim Hackney
Ames Construction Co

Protective pipe, top elevation _____ ft. MSL
Well casing, top elevation 1045.39 ft. MSL
Land surface elevation 1041.1 ft. MSL
Surface seal, bottom _____ ft. MSL or _____ ft.
USCS classification of soil near screen:
GP GM GC GW SW SP
SM SC ML MH CL CH
Bedrock
Sieve analysis attached? Yes No
Drilling method used: Rotary 50
Hollow Stem Auger 41
Percussion Other
Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99
Sealing additives used? Yes No
Describe _____ NA
1. Source of water (attach analysis):
NA



1. Cap and lock? Capped Yes No
2. Protective cover pipe:
a. Inside diameter: _____ in.
b. Length: _____ ft.
c. Material: _____ Steel 04
NONE Other
d. Additional protection? Yes No
If yes, describe: _____
3. Surface seal: Bentonite 30
Concrete 01
Other
4. Material between well casing and protective pipe:
Entire Hole Bentonite 30
Annular space seal
0.25" washed Pea Gravel Other
5. Annular space seal:
a. Granular Bentonite 33
b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
c. _____ Lbs/gal mud weight Bentonite slurry 31
d. _____ % Bentonite Bentonite-cement grout 50
e. _____ Ft³ volume added for any of the above
f. How installed: Tremie 01
Tremie pumped 02
Gravity 08
6. Bentonite seal: a. Bentonite granules 33
b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
c. _____ Other
7. Fine sand material: Manufacturer, product name & mesh size
a. _____
b. Volume added _____ ft³
8. Filter pack material: Manufacturer, product name and mesh size
a. _____
b. Volume added _____ ft³
9. Well casing: Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other
10. Screen material: PVC
a. Screen type: Factory cut 11
Continuous slot 01
0.25" Hole Drilled every 4" Other
b. Manufacturer _____
c. Slot size: _____ in.
d. Slotted length: _____ ft.
11. Backfill material (below filter pack): None 14
Other

Bentonite seal, top _____ ft. MSL or _____ ft.
Fine sand, top _____ ft. MSL or _____ ft.
Filter pack, top _____ ft. MSL or _____ ft.
Screen joint, top _____ ft. MSL or _____ ft.
Well bottom _____ ft. MSL or 36.0 ft.
Filter pack, bottom _____ ft. MSL or 36.0 ft.
Borehole, bottom _____ ft. MSL or 36.0 ft.
Borehole, diameter 3.5 in.
O.D. well casing 2.37 in.
Well casing 2.02 in.

I hereby certify that the information on this form is true and correct to the best of my knowledge.
Signature Shirley R. May Firm Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. See instructions for more information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name Flambeau Mine	County Name Rusk	Well Name 104-16	
Facility License, Permit or Monitoring Number 03180	County Code 55	Wis. Unique Well Number	DNR Well Number

1. Can this well be purged dry? Yes No

2. Well development method

surged with bailer and bailed	<input type="checkbox"/> 41
surged with bailer and pumped	<input type="checkbox"/> 61
surged with block and bailed	<input type="checkbox"/> 42
surged with block and pumped	<input type="checkbox"/> 62
surged with block, bailed and pumped	<input type="checkbox"/> 70
compressed air	<input type="checkbox"/> 20
bailed only	<input type="checkbox"/> 10
pumped only	<input type="checkbox"/> 51
pumped slowly	<input type="checkbox"/> 50
Other	<input type="checkbox"/>

3. Time spent developing well 0 min.

4. Depth of well (from top of well casing) 36.0 ft.

5. Inside diameter of well 2.02 in.

6. Volume of water in filter pack and well casing / gal.

7. Volume of water removed from well / gal.

8. Volume of water added (if any) / gal.

9. Source of water added NA

10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>/</u> ft.	<u>/</u> ft.
Date	b. <u>/ / /</u> m m d d y y	<u>/ / /</u> m m d d y y
Time	c. <u>/</u> : <u>/</u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u>/</u> : <u>/</u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<u>/</u> inches	<u>/</u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe)	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe)

Fill in if drilling fluids were used and well is at solid waste facility:

14. Total suspended solids	<u>/</u> mg/l	<u>/</u> mg/l
15. COD	<u>/</u> mg/l	<u>/</u> mg/l

16. Additional comments on development:
Collared into massive sulfate "A" lens

Well developed by: Person's Name and Firm Name: _____ Firm: _____	I hereby certify that the above information is true and correct to the best of my knowledge. Signature: <u>[Signature]</u> Print Initials: <u>ERM</u> Firm: <u>Consulting Mining Geologist</u>
---	---

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

City/Project Name
Lambert Mine

License, Permit or Monitoring Number
03180

Type of Well
Water Table Observation Well 11
Piezometer 12

Distance Well Is From Waste/Source Boundary
ft. _____

Well A Point of Enforcement Std. Application?
 Yes No

Local Grid Location of Well
39834.1 ft. N S 38923.1 ft. E W

Grid Origin Location
Lat. _____ Long. _____ or
St. Plane _____ ft. N. _____ ft. E.

Section Location of Waste/Source
_____ 1/4 of _____ 1/4 of Sec. _____ T. _____ N. R. _____ E W

Location of Well Relative to Waste/Source
u Upgradient s Sidegradient
d Downgradient n Not Known

Well Name
104-17

Wis. Unique Well Number _____ DNR Well Number _____

Date Well Installed
mm / dd / yy

Well Installed By: (Person's Name and Firm)

Protective pipe, top elevation _____ ft. MSL

Well casing, top elevation 1041.09 ft. MSL

Ground surface elevation 1040.5 ft. MSL

Surface seal, bottom _____ ft. MSL or _____ ft.

USCS classification of soil near screen:
GP GM GC GW SW SP
SM SC ML MH CL CH
Bedrock

Sieve analysis attached? Yes No


Drilling method used:
Rotary 50
Hollow Stem Auger 41
Percussion Other

Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99

Sealing additives used? Yes No

Describe _____ NA

7. Source of water (attach analysis):
NA



1. Cap and lock? Capped Yes No

2. Protective cover pipe:
a. Inside diameter: _____ in.
b. Length: _____ ft.
c. Material: _____ Steel 04
NONE Other
d. Additional protection? Yes No
If yes, describe: _____

3. Surface seal:
Bentonite 30
Concrete 01
Other

4. Material between well casing and protective pipe:
Entire Hole Bentonite 30
Annular space seal
0.25" Washed Pea Gravel Other

5. Annular space seal:
a. Granular Bentonite 33
b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
c. _____ Lbs/gal mud weight Bentonite slurry 31
d. _____ % Bentonite Bentonite-cement grout 50
e. _____ Ft³ volume added for any of the above
f. How installed: Tremie 01
Tremie pumped 02
Gravity 08

6. Bentonite seal:
a. Bentonite granules 33
b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
c. _____ Other

7. Fine sand material: Manufacturer, product name & mesh size
a. _____
b. Volume added _____ ft³

8. Filter pack material: Manufacturer, product name and mesh size
a. _____
b. Volume added _____ ft³

9. Well casing:
Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other

10. Screen material: PVC
a. Screen type: Factory cut 11
Continuous slot 01
0.25" Holes Drilled every 4" Other
b. Manufacturer _____
c. Slot size: _____ in.
d. Slotted length: _____ ft.

11. Backfill material (below filter pack):
None 14
Other

Bentonite seal, top _____ ft. MSL or _____ ft.

Fine sand, top _____ ft. MSL or _____ ft.

Filter pack, top _____ ft. MSL or _____ ft.

Screen joint, top _____ ft. MSL or _____ ft.

Well bottom _____ ft. MSL or 36.0 ft.

Filter pack, bottom _____ ft. MSL or 36.0 ft.

Borehole, bottom _____ ft. MSL or 36.0 ft.

Borehole, diameter 3.5 in.

O.D. well casing 2.37 in.

I.D. well casing 2.02 in.

I hereby certify that the information on this form is true and correct to the best of my knowledge.
Signature Shwade R. Man Firm Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. For more information including where the completed form should be sent.

Route 10: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <i>Flambeau Mine</i>	County Name <i>Rusk</i>	Well Name <i>104-17</i>	
Facility License, Permit or Monitoring Number <i>03180</i>	County Code <i>55</i>	Wis. Unique Well Number	DNR Well Number

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other
3. Time spent developing well _____ min.
4. Depth of well (from top of well casing) 36.0 ft.
5. Inside diameter of well _____ in.
6. Volume of water in filter pack and well casing _____ gal.
7. Volume of water removed from well _____ gal.
8. Volume of water added (if any) _____ gal.
9. Source of water added _____
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. _____ ft.	_____ ft.
Date	b. ____/____/____ m m d d y y	____/____/____ m m d d y y
Time	c. ____:____ <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.	____:____ <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	_____ inches	_____ inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input type="checkbox"/> 15 (Describe) _____	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe) _____

Fill in if drilling fluids were used and well is at solid waste facility:

14. Total suspended solids _____ mg/l

15. COD _____ mg/l

16. Additional comments on development:
Collared in cherty H.W. rock.

Well developed by: Person's Name and Firm Name _____ Firm _____	I hereby certify that the above information is true and correct to the best of my knowledge. Signature: <i>Shirley R. May</i> Print Initials: <i>ERM</i> Firm: <i>Consulting Mining Geologists</i>
---	---

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

Project Name
Urban Mine

License, Permit or Monitoring Number
03180

Type of Well
Water Table Observation Well 11
Piezometer 12

Distance Well Is From Waste/Source Boundary
ft. _____

Well A Point of Enforcement Std. Application?
 Yes No

Local Grid Location of Well
39717.5 ft. N. S. 38937.4 ft. E. W.

Grid Origin Location
Lat. _____ Long. _____ or
St. Plane _____ ft. N. _____ ft. E.

Section Location of Waste/Source
SW 1/4 of SE 1/4 of Sec. 9, T. 34 N, R. 6 E. W.

Location of Well Relative to Waste/Source
u Upgradient s Sidegradient
d Downgradient n Not Known

Well Name
WW-3

Wis. Unique Well Number _____ DNR Well Number _____

Date Well Installed
05/20/94
m m d d y y

Well Installed By: (Person's Name and Firm)
Richard Kastner
Kramer Well Drilling, Inc.

Protective pipe, top elevation 1102.54 ft. MSL

Well casing, top elevation 1102.78 ft. MSL

Land surface elevation 1100.1 ft. MSL

Surface seal, bottom 1098.0 ft. MSL or 2.1 ft.

USCS classification of soil near screen:
GP GM GC GW SW SP
SM SC ML MH CL CH
Bedrock


Sieve analysis attached? Yes No

Drilling method used:
Rotary 50
Hollow Stem Auger 41
Air Hammer Other

Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99

Sealing additives used? Yes No
Describe NA

Source of water (attach analysis):



1. Cap and lock? Yes No

2. Protective cover pipe:
a. Inside diameter: 6.0 in.
b. Length: 5.0 ft.
c. Material: Steel 04
Other

d. Additional protection? Yes No
If yes, describe: _____

3. Surface seal: Bentonite 30
Concrete 01
Other

4. Material between well casing and protective pipe:
Bentonite 30
Annular space seal

5. Annular space seal:
a. Granular Bentonite 33
b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
c. _____ Lbs/gal mud weight Bentonite slurry 31
d. _____ % Bentonite Bentonite-cement grout 50
e. _____ Ft³ volume added for any of the above
f. How installed: Tremie 01
Tremie pumped 02
Gravity 08

6. Bentonite seal:
a. Bentonite granules 33
b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
c. _____ Other

7. Fine sand material: Manufacturer, product name & mesh size
a. Badger Silica #20-#40
b. Volume added _____ ft³

8. Filter pack material: Manufacturer, product name and mesh size
a. 0.25" Washal Pan Gravel
b. Volume added _____ ft³

9. Well casing: Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other

10. Screen material: PVC
a. Screen type: Factory cut 11
Continuous slot (1)
Other

b. Manufacturer _____
c. Slot size: 0.010
d. Slot length: 5.0

11. Backfill material (below filter pack):
Name 14
Other

I hereby certify that the information on this form is true and correct to the best of my knowledge.

Signature Shirley R. May Firm Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flambeau Mine</u>	County Name <u>Rusk</u>	Well Name <u>WW-3</u>	
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number	DNR Well Number

1. Can this well be purged dry? Yes No

2. Well development method

surged with boiler and bailed	<input type="checkbox"/> 41
surged with bailer and pumped	<input type="checkbox"/> 61
surged with block and bailed	<input type="checkbox"/> 42
surged with block and pumped	<input type="checkbox"/> 62
surged with block, bailed and pumped	<input type="checkbox"/> 70
compressed air	<input checked="" type="checkbox"/> 20
bailed only	<input type="checkbox"/> 10
pumped only	<input type="checkbox"/> 51
pumped slowly	<input type="checkbox"/> 50
Other	<input type="checkbox"/>

3. Time spent developing well 30 min.

4. Depth of well (from top of well casing) 67.5 ft.

5. Inside diameter of well 2.02 in.

6. Volume of water in filter pack and well casing 0.0 gal.

7. Volume of water removed from well 225.0 gal.

8. Volume of water added (if any) 0.0 gal.

9. Source of water added NA

10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>28.00</u> ft.	<u>31.80</u> ft.
Date	b. <u>05/19/94</u> m m d d y y	<u>05/20/94</u> m m d d y y
Time	c. <u>3:30</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.	<u>9:00</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<u>—</u> inches	<u>—</u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>muddy</u>	Clear <input type="checkbox"/> 20 Turbid <input checked="" type="checkbox"/> 25 (Describe) <u>muddy</u>

Fill in if drilling fluids were used and well is at solid waste facility:

14. Total suspended solids	<u>—</u> mg/l	<u>—</u> mg/l
15. COD	<u>—</u> mg/l	<u>—</u> mg/l

16. Additional comments on development:

Well developed by: Person's Name and Firm

Name: Richard Kastner

Firm: Kramer Well Drilling, Inc

I hereby certify that the above information is true and correct to the best of my knowledge.

Signature: Shirley R. May

Print initials: ERM

Title: Consulting Mining Geologist

Project Name
Flambeau Mine

License, Permit or Monitoring Number
03180

Type of Well Water Table Observation Well 11
Piezometer 12

Distance Well Is From Waste/Source Boundary
ft. _____

Well A Point of Enforcement Std. Application?
 Yes No

Local Grid Location of Well
39,722.4 ft. N. S. 38,931.9 ft. E. W.

Grid Origin Location
Lat. _____ Long. _____ or
St. Plane _____ ft. N. _____ ft. E.

Section Location of Waste/Source
SW 1/4 of SE 1/4 of Sec. 9, T. 34 N, R. 6 E. W.

Location of Well Relative to Waste/Source
u Upgradient s Sidegradient
d Downgradient n Not Known

Well Name
WW-4

Wis. Unique Well Number DNR Well Number

Date Well Installed
05/20/94
m m d d y y

Well Installed By: (Person's Name and Firm)
Richard Kastner
Kramer Well Drilling, Inc

Protective pipe, top elevation 1102.55 ft. MSL

Well casing, top elevation 1102.41 ft. MSL

Wellhead and surface elevation 1100.1 ft. MSL

Surface seal, bottom 1098.1 ft. MSL or 2.0 ft.

USCS classification of soil near screen:
GP GM GC GW SW SP
SM SC ML MH CL CH
Bedrock

Sieve analysis attached? Yes No


Drilling method used: Rotary 50
Hollow Stem Auger 41
Air Hammer Other 1

Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99

Sealing additives used? Yes No

Describe _____

7. Source of water (attach analysis): _____



1. Cap and lock? Yes No

2. Protective cover pipe:
a. Inside diameter: 6.0 in.
b. Length: 5.0 ft.
c. Material: Steel 04
Other _____
d. Additional protection? Yes No
If yes, describe: _____

3. Surface seal: Bentonite 30
Concrete 01
Other _____

4. Material between well casing and protective pipe:
Bentonite 30
Annular space seal _____
Other _____

5. Annular space seal:
a. Granular Bentonite 33
b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
c. _____ Lbs/gal mud weight . . . Bentonite slurry 31
d. _____ % Bentonite Bentonite-cement grout 50
e. _____ Ft³ volume added for any of the above
f. How installed: Tremie 01
Tremie pumped 02
Gravity 08

6. Bentonite seal:
a. Bentonite granules 33
b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
c. _____ Other _____

7. Fine sand material: Manufacturer, product name & mesh size
a. Badger Silica #20-#40
b. Volume added _____ ft³

8. Filter pack material: Manufacturer, product name and mesh size
a. 0.25" Washed Pen Gravel
b. Volume added _____ ft³

9. Well casing: Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other _____

10. Screen material: PVC
a. Screen type: Factory cut 11
Continuous slot 01
Other _____
b. Manufacturer _____
c. Slot size: 0.010
d. Slotted length: 5.0

11. Backfill material (below filter pack): None 14
Other _____

Bentonite seal, top 1055.0 ft. MSL or _____ ft.

Fine sand, top 1053.0 ft. MSL or _____ ft.

Filter pack, top 1052.0 ft. MSL or _____ ft.

Screen joint, top 1050.0 ft. MSL or _____ ft.

Well bottom 1045.0 ft. MSL or _____ ft.

Filter pack, bottom _____ ft. MSL or _____ ft.

Borehole, bottom 1045.0 ft. MSL or _____ ft.

Borehole diameter 7.0 in.

O.D. well casing 2.37 in.

Well casing 2.02 in.

I hereby certify that the information on this form is true and correct to the best of my knowledge.

Signature Shirley R. May Firm Consulting Mining Geologist.

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flambeau mine</u>	County Name <u>Rusk</u>	Well Name <u>WW-4</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No

2. Well development method

surged with bailer and bailed	<input type="checkbox"/>	41
surged with bailer and pumped	<input type="checkbox"/>	61
surged with block and bailed	<input type="checkbox"/>	42
surged with block and pumped	<input type="checkbox"/>	62
surged with block, bailed and pumped	<input type="checkbox"/>	70
compressed air	<input checked="" type="checkbox"/>	20
bailed only	<input type="checkbox"/>	10
pumped only	<input type="checkbox"/>	51
pumped slowly	<input type="checkbox"/>	50
Other	<input type="checkbox"/>	

3. Time spent developing well 30 min.

4. Depth of well (from top of well casing) 57.4 ft.

5. Inside diameter of well 202 in.

6. Volume of water in filter pack and well casing 0.0 gal.

7. Volume of water removed from well 90.0 gal.

8. Volume of water added (if any) 0.0 gal.

9. Source of water added NA

10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>22.0</u> ft.	<u>30.4</u> ft.
Date	b. <u>05/20/94</u> m m d d y y	<u>05/20/94</u> m m d d y y
Time	c. <u>10:10³⁰</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u>1:00</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.
12. Sediment in well bottom	<u>/</u> inches	<u>/</u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>Muddy</u>	Clear <input type="checkbox"/> 20 Turbid <input checked="" type="checkbox"/> 25 (Describe) <u>Muddy</u>

Fill in if drilling fluids were used and well is at solid waste facility:

14. Total suspended solids	<u>/</u> mg/l	<u>/</u> mg/l
15. COD	<u>/</u> mg/l	<u>/</u> mg/l

16. Additional comments on development:

Well developer or Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: <u>Richard Kastner</u>	Signature: <u>[Signature]</u>
Firm: <u>Kramer Well Drilling, Inc</u>	Print Initials: <u>ERM</u>
	Title: <u>Consulting Mining Geologist</u>

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

City/Project Name
Flambeau Mine

License, Permit or Monitoring Number
03180

Type of Well Water Table Observation Well 11
 Piezometer 12

Distance Well Is From Waste/Source Boundary
 ft. _____

Well A Point of Enforcement Std. Application?
 Yes No

Local Grid Location of Well
39,721.6 ft. N. S. 38,932.0 ft. E. W

Grid Origin Location
 Lat. _____ Long. _____ or
 St. Plane _____ ft. N. _____ ft. E.

Section Location of Waste/Source
SW 1/4 of SE 1/4 of Sec. 9, T. 34 N., R. 6 E. W

Location of Well Relative to Waste/Source
 Upgradient Sidegradient
 Downgradient Not Known

Well Name
WW-5

Wis. Unique Well Number DNR Well Number

Date Well Installed
05/20/94
 m m d d y y

Well Installed By: (Person's Name and Firm)
Richard Kastner
Kramer Well Drilling, Inc

Protective pipe, top elevation 1102.86 ft. MSL

Well casing, top elevation 1102.52 ft. MSL

Land surface elevation 1100.1 ft. MSL

Surface seal, bottom 1098.1 ft. MSL or 2.0 ft.

1. USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock


2. Sieve analysis attached? Yes No

3. Drilling method used: Rotary 50
 Hollow Stem Auger 41
Air Hammer Other

4. Drilling fluid used: Water 02 Air 01
 Drilling Mud 03 None 99

5. Logging additives used? Yes No
 Describe NA

6. Source of water (attach analysis):
NA



1. Cap and lock? Yes No

2. Protective cover pipe:
 a. Inside diameter: 6.0 in.
 b. Length: 5.0 ft.
 c. Material: Steel 04
 Other
 d. Additional protection? Yes No
 If yes, describe: _____

3. Surface seal:
 Bentonite 30
 Concrete 01
 Other

4. Material between well casing and protective pipe:
 Bentonite 30
 Annular space seal
 Other

5. Annular space seal:
 a. Granular Bentonite 33
 b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
 c. _____ Lbs/gal mud weight Bentonite slurry 31
 d. _____ % Bentonite Bentonite-cement grout 50
 e. _____ Ft³ volume added for any of the above
 f. How installed: Tremie 01
 Tremie pumped 02
 Gravity 08

6. Bentonite seal:
 a. Bentonite granules 33
 b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
 c. _____ Other

7. Fine sand material: Manufacturer, product name & mesh size
 a. Badger Silica #20-#40
 b. Volume added _____ ft³

8. Filter pack material: Manufacturer, product name and mesh size
 a. 0.25" Washed Pea Gravel
 b. Volume added _____ ft³

9. Well casing: Flush threaded PVC schedule 40 23
 Flush threaded PVC schedule 80 24
 Other

10. Screen material: PVC
 a. Screen type: Factory cut 11
 Continuous slot 01
 Other
 b. Manufacturer: _____
 c. Slot size: 0.010
 d. Slotted length: 5.0

11. Backfill material (below filter pack):
 None 1-
 Other

I hereby certify that the information on this form is true and correct to the best of my knowledge.
 Signature Edward R. May Firm Consulting Mining Geologist.

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. Information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flambcan Mine</u>	County Name <u>Rusk</u>	Well Name <u>LOW-5</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No

2. Well development method

surged with bailer and bailed	<input type="checkbox"/>	41
surged with bailer and pumped	<input type="checkbox"/>	61
surged with block and bailed	<input type="checkbox"/>	42
surged with block and pumped	<input type="checkbox"/>	62
surged with block, bailed and pumped	<input type="checkbox"/>	70
compressed air	<input checked="" type="checkbox"/>	20
bailed only	<input type="checkbox"/>	10
pumped only	<input type="checkbox"/>	51
pumped slowly	<input type="checkbox"/>	50
Other	<input type="checkbox"/>	

3. Time spent developing well 30 min.

4. Depth of well (from top of well casing) 43.5 ft.

5. Inside diameter of well 2.02 in.

6. Volume of water in filter pack and well casing 0.0 gal.

7. Volume of water removed from well 180.0 gal.

8. Volume of water added (if any) 0.0 gal.

9. Source of water added NA

10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>22.00</u> ft.	<u>23.93</u> ft.
Date	b. <u>05/20/94</u> m m d d y y	<u>05/20/94</u> m m d d y y
Time	c. <u>4:30</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.	<u>5:30</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.
12. Sediment in well bottom	<u>/</u> inches	<u>/</u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>muddy</u>	Clear <input type="checkbox"/> 20 Turbid <input checked="" type="checkbox"/> 25 (Describe) <u>muddy</u>
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<u>/</u> mg/l	<u>/</u> mg/l
15. COD	<u>/</u> mg/l	<u>/</u> mg/l

16. Additional comments on development:

Well developer: Person's Name and Firm Name <u>Richard Kastner</u> Firm <u>Kramer Well Drilling, Inc</u>	I hereby certify that the above information is true and correct to the best of my knowledge. Signature <u>Shirley R. May</u> Print Initials: <u>ERM</u> Title <u>Consulting Mining Geologist</u>
--	---

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

Project Name
Flambeau Mine
License, Permit or Monitoring Number
03180

Local Grid Location of Well
39,755.0 ft. N. S. 38913.0 ft. E. W.
Grid Origin Location
Lat. _____ Long. _____ or
St. Plane _____ ft. N. _____ ft. E.

Well Name
WW-6
Wis. Unique Well Number _____ DNR Well Number _____
Date Well Installed
05/23/94
m m d d y y


Type of Well Water Table Observation Well 11
Piezometer 12
Is Well Is From Waste/Source Boundary _____ ft.
Well A Point of Enforcement Std. Application?
 Yes No

Section Location of Waste/Source
SW 1/4 of SE 1/4 of Sec. 9, T. 34 N, R. 6 E. W.
Location of Well Relative to Waste/Source
u Upgradient s Sidegradient
d Downgradient n Not Known

Well Installed By: (Person's Name and Firm)
Richard Kastner
Kramer Well Drilling, Inc
 Yes No

Protective pipe, top elevation 1102.62 ft. MSL
Well casing, top elevation 1102.52 ft. MSL
Ground surface elevation 1100.1 ft. MSL
Surface seal, bottom _____ ft. MSL or _____ ft.

USCS classification of soil near screen:
GP GM GC GW SW SP
SM SC ML MH CL CH
Bedrock
Sieve analysis attached? Yes No
Drilling method used: Rotary 50
Hollow Stem Auger 41
Other _____
Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99
Sealing additives used? Yes No
Describe _____
Source of water (attach analysis): _____



1. Cap and lock?
2. Protective cover pipe:
 - a. Inside diameter: 6.0 in.
 - b. Length: 5.0 ft.
 - c. Material: Steel 04
Other _____
 - d. Additional protection? Yes No
If yes, describe: _____
3. Surface seal:
 - Bentonite 30
 - Concrete 01
 - Other _____
4. Material between well casing and protective pipe:
 - Bentonite 30
 - Annular space seal _____
 - Other _____
5. Annular space seal:
 - a. Granular Bentonite 33
 - b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
 - c. _____ Lbs/gal mud weight . . . Bentonite slurry 31
 - d. _____ % Bentonite Bentonite-cement grout 50
 - e. _____ Ft³ volume added for any of the above
 - f. How installed: Tremie 01
Tremie pumped 02
Gravity 08
6. Bentonite seal:
 - a. Bentonite granules 33
 - b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
 - c. _____ Other _____
7. Fine sand material: Manufacturer, product name & mesh size
a. Badger Silica #20-#40
- b. Volume added _____ ft³
8. Filter pack material: Manufacturer, product name and mesh size
a. 0.25" Washed Pea Gravel
- b. Volume added _____ ft³
9. Well casing:
 - Flush threaded PVC schedule 40 23
 - Flush threaded PVC schedule 80 24
 - Other _____
10. Screen material: PVC
 - a. Screen type: Factory cut 11
Continuous slot 01
Other _____
 - b. Manufacturer _____
 - c. Slot size: 0.010
 - d. Screen length: 5.0
11. Backfill material (below filter pack):
None 14
Other _____

Bentonite seal, top 1069.0 ft. MSL or _____ ft.
Fine sand, top 1067.0 ft. MSL or _____ ft.
Filter pack, top 1066.0 ft. MSL or _____ ft.
Screen joint, top 1064.0 ft. MSL or _____ ft.
Well bottom 1059.0 ft. MSL or _____ ft.
Filter pack, bottom _____ ft. MSL or _____ ft.
Borehole, bottom 1059.0 ft. MSL or _____ ft.
Borehole diameter 7.0 in.
O.D. well casing 2.37 in.
I.D. well casing 2.02 in.

I hereby certify that the information on this form is true and correct to the best of my knowledge.
Signature Shirley R. May Firm Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. See instructions for more information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flambeau Mine</u>	County Name <u>Rusk</u>	Well Name <u>WW-6</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No

2. Well development method

surged with bailer and bailed	<input type="checkbox"/> 41
surged with bailer and pumped	<input type="checkbox"/> 61
surged with block and bailed	<input type="checkbox"/> 42
surged with block and pumped	<input type="checkbox"/> 62
surged with block, bailed and pumped	<input type="checkbox"/> 70
compressed air	<input checked="" type="checkbox"/> 20
bailed only	<input type="checkbox"/> 10
pumped only	<input type="checkbox"/> 51
pumped slowly	<input type="checkbox"/> 50
Other	<input type="checkbox"/>

3. Time spent developing well 30 min.

4. Depth of well (from top of well casing) 43.5 ft.

5. Inside diameter of well 2.02 in.

6. Volume of water in filter pack and well casing 0.0 gal.

7. Volume of water removed from well 90.0 gal.

8. Volume of water added (if any) 0.0 gal.

9. Source of water added NA

10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>24.3</u> ft.	<u>33.34</u> ft.
Date	b. <u>05/23/94</u> m m d d y y	<u>05/23/94</u> m m d d y y
Time	c. <u>10:30</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u>11:00</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<u>/</u> inches	<u>/</u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>Muddy</u>	Clear <input type="checkbox"/> 20 Turbid <input checked="" type="checkbox"/> 25 (Describe) <u>Muddy</u>
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<u>/</u> mg/l	<u>/</u> mg/l
15. COD	<u>/</u> mg/l	<u>/</u> mg/l

16. Additional comments on development:

Well developed by: Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: <u>Richard Kastner</u>	Signature: <u>Richard R. May</u>
Firm: <u>Kramer Well Drilling, Inc</u>	Print Initials: <u>ERM</u>
	Firm: <u>Consulting Mining Geologist.</u>

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

City/Project Name
Flambeau Mine

License, Permit or Monitoring Number
03180

Type of Well Water Table Observation Well 11
Piezometer 12

Distance Well Is From Waste/Source Boundary
ft. _____

Well A Point of Enforcement Std. Application?
 Yes No

Local Grid Location of Well
39,755.0 ft. N. S. 38916.1 ft. E. W

Grid Origin Location
Lat. _____ Long. _____ or
St. Plane _____ ft. N. _____ ft. E.

Section Location of Waste/Source
SW 1/4 of SE 1/4 of Sec. 9, T. 34 N, R. 6 E. W.

Location of Well Relative to Waste/Source
u Upgradient s Sidegradient
d Downgradient n Not Known

Well Name
WW-7

Wis. Unique Well Number _____ DNR Well Number _____

Date Well Installed
05/23/94
m m d d y y

Well Installed By: (Person's Name and Firm)
Richard Kastner
Kramer Well Drilling, Inc

Protective pipe, top elevation 1102.81 ft. MSL

Well casing, top elevation 1102.57 ft. MSL

Land surface elevation 1100.0 ft. MSL

Surface seal, bottom 1098.0 ft. MSL or 2.0 ft.

USCS classification of soil near screen:
GP GM GC GW SW SP
SM SC ML MH CL CH
Bedrock


Sieve analysis attached? Yes No

Drilling method used: Rotary 50
Hollow Stem Auger 41
Air Hammer Other 22

Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99

Sealing additives used? Yes No
Describe NA

Source of water (attach analysis):
NA



1. Cap and lock? Yes No

2. Protective cover pipe:
a. Inside diameter: 6.0 in.
b. Length: 5.0 in.
c. Material: Steel 04
Other _____
d. Additional protection? Yes No
If yes, describe: _____

3. Surface seal: Bentonite 30
Concrete 01
Other _____

4. Material between well casing and protective pipe: Bentonite 30
Annular space seal _____
Other _____

5. Annular space seal:
a. Granular Bentonite 33
b. _____ Lbs/gal mud weight ... Bentonite-sand slurry 35
c. _____ Lbs/gal mud weight ... Bentonite slurry 31
d. _____ % Bentonite ... Bentonite-cement grout 50
e. _____ Ft³ volume added for any of the above
f. How installed: Tremie 01
Tremie pumped 02
Gravity 08

6. Bentonite seal:
a. Bentonite granules 33
b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
c. _____ Other _____

7. Fine sand material: Manufacturer, product name & mesh size
a. Badger Silica #20-#70
b. Volume added _____ ft³

8. Filter pack material: Manufacturer, product name and mesh size
a. 0.25" Washed Pea Gravel
b. Volume added _____ ft³

9. Well casing: Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other _____

10. Screen material: PVC
a. Screen type: Factory cut 11
Continuous slot 12
Other _____
b. Manufacturer _____
c. Slot size: 0.010
d. Slotted length: 5.0

11. Backfill material (below filter pack): None 13
Other _____

I hereby certify that the information on this form is true and correct to the best of my knowledge.
Signature Edward R. May Firm Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats. and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. Information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name Flambeau Mine	County Name Rusk	Well Name WW-7
Facility License, Permit or Monitoring Number 03180	County Code 55	Wis. Unique Well Number DNR Well Number

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other
3. Time spent developing well 30 min.
4. Depth of well (from top of well casing) 37.9 ft.
5. Inside diameter of well 2.02 in.
6. Volume of water in filter pack and well casing 0.0 gal.
7. Volume of water removed from well 210.0 gal.
8. Volume of water added (if any) 0.0 gal.
9. Source of water added NA
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>24.3</u> ft.	<u>33.32</u> ft.
Date	b. <u>05/23/94</u> m m d d y y	<u>05/23/94</u> m m d d y y
Time	c. <u>2:30</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.	<u>7:00</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.
12. Sediment in well bottom	<u>/</u> inches	<u>/</u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>Muddy</u>	Clear <input type="checkbox"/> 20 Turbid <input checked="" type="checkbox"/> 25 (Describe) <u>Muddy</u>
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<u>/</u> mg/l	<u>/</u> mg/l
15. COD	<u>/</u> mg/l	<u>/</u> mg/l

16. Additional comments on development:

Well developed by: Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: <u>Richard Kastner</u>	Signature: <u>Shirley R. May</u>
Firm: <u>Kramer Well Drilling, Inc</u>	Print Initials: <u>ERM</u>
	Firm: <u>Consulting Mining Geologists</u>

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

Facility/Project Name Flambeau Mine	Local Grid Location of Well 40902.9 <input checked="" type="checkbox"/> N. <input type="checkbox"/> S. 39, 520.2 ft. <input checked="" type="checkbox"/> E. <input type="checkbox"/> W.	Well Name WW8
Facility License, Permit or Monitoring Number 03180	Grid Origin Location Lat. _____ Long. _____ or St. Plane _____ ft. N. _____ ft. E.	Wis. Unique Well Number _____ DNR Well Number _____
Type of Well Water Table Observation Well <input type="checkbox"/> 11 Piezometer <input checked="" type="checkbox"/> 12	Section Location of Waste/Source NW 1/4 of SE 1/4 of Sec. 9, T. 34N, R. 6 <input checked="" type="checkbox"/> W.	Date Well Installed 0 7 / 1 3 / 9 4 m m d d y y
Distance Well is From Waste/Source Boundary ft.	Location of Well Relative to Waste/Source	Well Installed By: (Persons Name and Firm) Brad Davis Huntingdon Engineering & Environmental, Inc.
Is Well A Point of Enforcement Std. Application? <input type="checkbox"/> Yes <input type="checkbox"/> No	u <input type="checkbox"/> Upgradient s <input type="checkbox"/> Sidegradient d <input type="checkbox"/> Downgradient n <input type="checkbox"/> Not Known	

- A. Protective pipe, top elevation 1118.24 ft. MSL
- B. Well casing, top elevation 1118.07 ft. MSL
- C. Land surface elevation 1115.02 ft. MSL
- D. Surface seal, bottom 1114.0 ft. MSL or 2.0 ft.

12. USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock Ess + PC


13. Sieve analysis attached? Yes No

14. Drilling method used: Rotary 50
 Hollow Stem Auger 41
 Other

15. Drilling fluid used: Water 02 Air 01
 Drilling Mud 03 None 99

16. Drilling additives used? Yes No
 Describe NA

17. Source of water (attach analysis): NA



- E. Bentonite seal, top _____ ft. MSL or 2.0 ft.
- F. Fine sand, top _____ ft. MSL or 1.5.3 ft.
- G. Filter pack, top _____ ft. MSL or 1.7.3 ft.
- H. Screen joint, top _____ ft. MSL or 1.9.3 ft.
- I. Well bottom _____ ft. MSL or 2.9.3 ft.
- J. Filter pack, bottom _____ ft. MSL or 2.9.8 ft.
- K. Borehole, bottom _____ ft. MSL or 2.9.8 ft.
- L. Borehole, diameter 8.0 in.
- M. O.D. well casing 2.37 in.
- N. I.D. well casing 2.02 in.

- 1. Cap and lock? Yes No
- 2. Protective cover pipe:
 - a. Inside diameter: 4.0 in.
 - b. Length: 7.0 ft.
 - c. Material: Steel 04
Other
 - d. Additional protection? Yes No
If yes, describe: _____
- 3. Surface seal: Bentonite 30
Concrete 01
Other
- 4. Material between well casing and protective pipe:
 - Bentonite 30
 - Annular space seal
 - Other
- 5. Annual space seal:
 - a. Granular Bentonite 33
 - b. ___ lbs/gal mud weight... Bentonite-sand slurry 35
 - c. ___ lbs/gal mud weight..... Bentonite slurry 31
 - d. ___ % Bentonite..... Bentonite-cement grout 50
 - e. 4.2 Ft³ volume added for any of the above
 - f. How installed Tremie 01
Tremie pumped 02
Gravity 08
- 6. Bentonite seal:
 - a. Bentonite granules 33
 - b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
 - c. Chips _____ Other
- 7. Fine sand material: mfr, product name & mesh size
 - a. Badger Mining, Silica #20-#40
 - b. Volume added 0.6 ft³
- 8. Filter pack material: mfr, product name and mesh size
 - a. American Materials, Red Flint #30
 - b. Volume added 9.5 ft³
- 9. Well casing: Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other
- 10. Screen material: SAME
 - a. Screen type: Factory cut 11
Continuous slot 01
Other
 - b. Manufacturer Certainteed Pipe Co.
 - c. Slot size: 0.010 in.
 - d. Slotted length: 1.0.0 ft.
- 11. Backfill material (below filter pack): None 14
Other

I hereby certify that the information on this form is true and correct to the best of my knowledge

Signature _____ Firm
Huntingdon Engineering & Environmental, Inc.

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form any results in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may results in a forfeiture of not more than \$10,000 for each day of violation. NOTE: Shaded areas are for DNR use only. See instructions for more information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Project Name <u>Frambeau Mine</u>	County Name <u>Rusk</u>	Well Name <u>WW 8</u>
Facility License, Permit or Monitoring Number	County Code	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No

2. Well development method

surged with bailer and bailed	<input type="checkbox"/> 41
surged with bailer and pumped	<input checked="" type="checkbox"/> 61
surged with block and bailed	<input type="checkbox"/> 42
surged with block and pumped	<input type="checkbox"/> 62
surged with block, bailed and pumped	<input type="checkbox"/> 70
compressed air	<input type="checkbox"/> 20
bailed only	<input type="checkbox"/> 10
pumped only	<input type="checkbox"/> 51
pumped slowly	<input type="checkbox"/> 50
Other	<input type="checkbox"/>

3. Time spent developing well 144 min.

4. Depth of well (from top of well casing) 31.9 ft.

5. Inside diameter of well 2.00 in.

6. Volume of water in filter pack and well casing 12.4 gal.

7. Volume of water removed from well 138.0 gal.

8. Volume of water added (if any) _____ gal.

9. Source of water added _____

10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>23.40</u> ft.	<u>23.49</u> ft.
Date	b. <u>01,06,95</u> m m d d y y	<u>01,09,95</u> m m d d y y
Time	c. <u>9:35</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u>10:02</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	_____ inches	_____ inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>Very Bk Br to DK Br</u>	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe) <u>Very Slight to Clear</u>
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	_____ mg/l	_____ mg/l
15. COD	_____ mg/l	_____ mg/l

16. Additional comments on development:

Well developed by: Person's Name and Firm

Name: Jack Christman

Firm: Frambeau Mine

I hereby certify that the above information is true and correct to the best of my knowledge.

Signature: [Signature]


Print Initials: _____

Firm: Frambeau Mine

NOTE: Check 1-900-4400 for DNR use only. See instructions for more information including a list of county codes.

Facility/Project Name Flambeau Mine	Local Grid Location of Well N. <input checked="" type="checkbox"/> E. <input type="checkbox"/> 40,591.3 ft. S. 39,160.0 ft.	Well Name WW9
Facility License, Permit or Monitoring Number 03180	Grid Origin Location Lat. _____ Long. _____ or St. Plane _____ ft. N. _____ ft. E.	Wis. Unique Well Number _____ DNR Well Number _____
Type of Well Water Table Observation Well <input type="checkbox"/> 11 Piezometer <input checked="" type="checkbox"/> 12	Section Location of Waste/Source <input type="checkbox"/> E. <input checked="" type="checkbox"/> W. NW 1/4 of SE 1/4 of Sec. 9, T. 34N, R. 6	Date Well Installed 07/13/94 m m d d y y
Distance Well is From Waste/Source Boundary ft.	Location of Well Relative to Waste/Source u <input type="checkbox"/> Upgradient s <input type="checkbox"/> Sidegradient d <input type="checkbox"/> Downgradient n <input type="checkbox"/> Not Known	Well Installed By: (Persons Name and Firm) Brad Davis Huntingdon Engineering & Environmental, Inc.
Is Well A Point of Enforcement Std. Application? <input type="checkbox"/> Yes <input type="checkbox"/> No		

- A. Protective pipe, top elevation 1118.56 ft. MSL
- B. Well casing, top elevation 1118.47 ft. MSL
- C. Land surface elevation 1116.19 ft. MSL
- D. Surface seal, bottom 1114.2 ft. MSL or 2.0 ft.



- 1. Cap and lock? Yes No
- 2. Protective cover pipe:
 - a. Inside diameter: 4.0 in.
 - b. Length: 7.0 ft.
 - c. Material: Steel 04
Other
 - d. Additional protection? Yes No
If yes, describe: _____
- 3. Surface seal: Bentonite 30
Concrete 01
Other
- 4. Material between well casing and protective pipe: Bentonite 30
Annular space seal
Other
- 5. Annual space seal:
 - a. Granular Bentonite 33
 - b. ___ lbs/gal mud weight..Bentonite-sand slurry 35
 - c. ___ lbs/gal mud weight..... Bentonite slurry 31
 - d. ___ % Bentonite..... Bentonite-cement grout 50
 - e. 5.4 Ft³ volume added for any of the above
 - f. How installed Tremie 01
Tremie pumped 02
Gravity 08
- 6. Bentonite seal:
 - a. Bentonite granules 33
 - b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
 - c. Chips _____ Other
- 7. Fine sand material: mfr, product name & mesh size
 - a. Badger Mining, Silica #20-#40
 - b. Volume added 0.6 ft³
- 8. Filter pack material: mfr, product name and mesh size
 - a. American Materials, Red Flint #30
 - b. Volume added 3.9 ft³
- 9. Well casing: Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other
- 10. Screen material: SAME
 - a. Screen type: Factory cut 11
Continuous slot 01
Other
 - b. Manufacturer Certainteed Pipe Co.
 - c. Slot size: 0.010 in.
 - d. Slotted length: 1.0 ft.
- 11. Backfill material (below filter pack): None 14
Other

12. USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock Esst + Pc

13. Sieve analysis attached? Yes No

14. Drilling method used: Rotary 50
Hollow Stem Auger 41
Other

15. Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99

16. Drilling additives used? Yes No
Describe NA

17. Source of water (attach analysis): NA

- E. Bentonite seal, top _____ ft. MSL or 2.0 ft.
- F. Fine sand, top _____ ft. MSL or 1.9 ft.
- G. Filter pack, top _____ ft. MSL or 2.1 ft.
- H. Screen joint, top _____ ft. MSL or 2.3 ft.
- I. Well bottom _____ ft. MSL or 3.3 ft.
- J. Filter pack, bottom _____ ft. MSL or 3.3.5 ft.
- K. Borehole, bottom _____ ft. MSL or 3.3.5 ft.
- L. Borehole, diameter 8.0 in.
- M. O.D. well casing 2.37 in.
- N. I.D. well casing 2.02 in.

I hereby certify that the information on this form is true and correct to the best of my knowledge
 Signature _____ Firm
 Huntingdon Engineering & Environmental, Inc.

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. NOTE: Shaded areas are for DNR use only. See instructions for more information including where the completed form should be sent.


Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

City/Project Name <u>Flambeau Mine</u>	County Name <u>Rusk</u>	Well Name <u>WW-9</u>
Facility License, Permit or Monitoring Number	County Code	Wis. Unique Well Number
		DNR Well Number

- Can this well be purged dry? Yes No
- Well development method
 - surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other
- Time spent developing well 24 min.
- Depth of well (from top of well casing) 35.8 ft.
- Inside diameter of well 2.00 in.
- Volume of water in filter pack and well casing 12.4 gal.
- Volume of water removed from well 13.7 gal.
- Volume of water added (if any) _____ gal.
- Source of water added _____
- Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>27.17</u> ft.	<u>27.17</u> ft.
Date	b. <u>01/06/95</u> m m d d y y	<u>01/12/95</u> m m d d y y
Time	c. <u>10:07</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u>1:05</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.
12. Sediment in well bottom	<u>0.0</u> inches	<u>0.0</u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>Lt Br to</u>	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe) <u>Very slight to clear</u>
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	_____ mg/l	_____ mg/l
15. COD	_____ mg/l	_____ mg/l

16. Additional comments on development:

Well developed by: Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: <u>Jack Christman</u>	Signature: 
Firm: <u>Flambeau Mine</u>	Print Initials: _____
	Firm: <u>Flambeau Mine</u>

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

Facility/Project Name Flambeau Mine	Local Grid Location of Well 40, <u>505.3</u> ft. <input checked="" type="checkbox"/> N. <u>38,986.4</u> ft. <input type="checkbox"/> E. <input type="checkbox"/> W.	Well Name WW10
Facility License, Permit or Monitoring Number <u>03180</u>	Grid Origin Location Lat. _____ Long. _____ or St. Plane _____ ft. N. _____ ft. E.	Wis. Unique Well Number _____ DNR Well Number _____
Type of Well Water Table Observation Well <input type="checkbox"/> 11 Piezometer <input checked="" type="checkbox"/> 12	Section Location of Waste/Source NW1/4 of SE 1/4 of Sec. <u>9</u> , T. <u>24</u> N., R. <u>6</u> <input checked="" type="checkbox"/> W. <input type="checkbox"/> E.	Date Well Installed <u>0 7 / 1 4 / 9 4</u> m m d d y y
Distance Well is From Waste/Source Boundary ft.	Location of Well Relative to Waste/Source u <input type="checkbox"/> Upgradient s <input type="checkbox"/> Sidegradient d <input type="checkbox"/> Downgradient n <input type="checkbox"/> Not Known	Well Installed By: (Persons Name and Firm) <u>Brad Davis</u> <u>Huntingdon Engineering & Environmental, Inc.</u>
Is Well A Point of Enforcement Std. Application? <input type="checkbox"/> Yes <input type="checkbox"/> No		

A. Protective pipe, top elevation <u>1116.46</u> ft. MSL		1. Cap and lock? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
B. Well casing, top elevation <u>1116.31</u> ft. MSL		2. Protective cover pipe: a. Inside diameter: <u>4.0</u> in. b. Length: <u>7.0</u> ft. c. Material: Steel <input checked="" type="checkbox"/> 04 Other <input type="checkbox"/>
C. Land surface elevation <u>1114.00</u> ft. MSL		d. Additional protection? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, describe: _____
D. Surface seal, bottom <u>1112.00</u> ft. MSL or <u>2.0</u> ft.		3. Surface seal: Bentonite <input type="checkbox"/> 30 Concrete <input checked="" type="checkbox"/> 01 Other <input type="checkbox"/>
12. USCS classification of soil near screen: GP <input type="checkbox"/> GM <input type="checkbox"/> GC <input type="checkbox"/> GW <input type="checkbox"/> SW <input type="checkbox"/> SP <input checked="" type="checkbox"/> SM <input type="checkbox"/> SC <input type="checkbox"/> ML <input type="checkbox"/> MH <input type="checkbox"/> CL <input type="checkbox"/> CH <input type="checkbox"/> Bedrock <input checked="" type="checkbox"/> <u>Est & PE</u>		4. Material between well casing and protective pipe: Bentonite <input checked="" type="checkbox"/> 30 Annular space seal <input type="checkbox"/>
13. Sieve analysis attached? <input type="checkbox"/> Yes <input type="checkbox"/> No		5. Annular space seal: a. Granular Bentonite <input type="checkbox"/> 33 b. ___ lbs/gal mud weight... Bentonite-sand slurry <input type="checkbox"/> 35 c. ___ lbs/gal mud weight... Bentonite slurry <input type="checkbox"/> 31 d. ___ % Bentonite... Bentonite-cement grout <input type="checkbox"/> 50 e. <u>6.6</u> Ft ³ volume added for any of the above f. How installed Tremie <input type="checkbox"/> 01 Tremie pumped <input type="checkbox"/> 02 Gravity <input checked="" type="checkbox"/> 08
14. Drilling method used: Rotary <input type="checkbox"/> 50 Hollow Stem Auger <input checked="" type="checkbox"/> 41 Other <input type="checkbox"/>		6. Bentonite seal: a. Bentonite granules <input type="checkbox"/> 33 b. <input type="checkbox"/> 1/4 in. <input checked="" type="checkbox"/> 3/8 in. <input type="checkbox"/> 1/2 in. Bentonite pellets <input type="checkbox"/> 32 c. Chips <input type="checkbox"/> Other <input type="checkbox"/>
15. Drilling fluid used: Water <input type="checkbox"/> 02 Air <input type="checkbox"/> 01 Drilling Mud <input type="checkbox"/> 03 None <input checked="" type="checkbox"/> 99		7. Fine sand material: mfr, product name & mesh size a. <u>Badger Mining, Silica #20-#40</u> b. Volume added <u>0.6</u> ft ³
16. Drilling additives used? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Describe <u>NA</u>		8. Filter pack material: mfr, product name and mesh size a. <u>American Materials, Red Flint #30</u> b. Volume added <u>4.1</u> ft ³
17. Source of water (attach analysis): <u>NA</u>		9. Well casing: Flush threaded PVC schedule 40 <input checked="" type="checkbox"/> 23 Flush threaded PVC schedule 80 <input type="checkbox"/> 24 Other <input type="checkbox"/>
E. Bentonite seal, top _____ ft. MSL or <u>2.0</u> ft.		10. Screen material: <u>SAME</u> a. Screen type: Factory cut <input checked="" type="checkbox"/> 11 Continuous slot <input type="checkbox"/> 01 Other <input type="checkbox"/> b. Manufacturer <u>Certainteed Pipe Co.</u> c. Slot size: <u>0.010</u> in. d. Slotted length: <u>1.0</u> ft.
F. Fine sand, top _____ ft. MSL or <u>2.7</u> ft.		11. Backfill material (below filter pack): None <input checked="" type="checkbox"/> 14 Other <input type="checkbox"/>
G. Filter pack, top _____ ft. MSL or <u>2.7</u> ft.		
H. Screen joint, top _____ ft. MSL or <u>2.7</u> ft.		
I. Well bottom _____ ft. MSL or <u>3.7</u> ft.		
J. Filter pack, bottom _____ ft. MSL or <u>3.7</u> ft.		
K. Borehole, bottom _____ ft. MSL or <u>3.7</u> ft.		
L. Borehole, diameter <u>8.0</u> in.		
M. O.D. well casing <u>2.37</u> in.		
N. I.D. well casing <u>2.02</u> in.		

I hereby certify that the information on this form is true and correct to the best of my knowledge
 Signature _____ Firm Huntingdon Engineering & Environmental, Inc.

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. NOTE: Shaded areas are for DNR use only. See instructions for more information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Project Name: Flambeau Mine County Name: Rusk Well Name: WW-10
 Facility License, Permit or Monitoring Number: _____ County Code: _____ Wis. Unique Well Number: _____ DNR Well Number: _____

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other _____
3. Time spent developing well 150 min.
4. Depth of well (from top of well casing) 39.8 ft.
5. Inside diameter of well 2.00 in.
6. Volume of water in filter pack and well casing 13.6 gal.
7. Volume of water removed from well 134.0 gal.
8. Volume of water added (if any) _____ gal.
9. Source of water added _____
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>26.50</u> ft.	<u>26.50</u> ft.
Date	b. <u>11/6/95</u> m m d d y y	<u>11/9/95</u> m m d d y y
Time	c. <u>10:22</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u>10:45</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<u>5</u> inches	_____ inches
13. Water clarity	Clear <input type="checkbox"/> 10	Clear <input type="checkbox"/> 20
	Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>DK Br T</u> <u>Dr</u>	Turbid <input type="checkbox"/> 25 (Describe) <u>Slight</u> <u>To Clear</u>

Fill in if drilling fluids were used and well is at solid waste facility:

14. Total suspended solids _____ mg/l

15. COD _____ mg/l

16. Additional comments on development:

Well developed by: Person's Name and Firm

Name: _____ Firm: _____

I hereby certify that the above information is true and correct to the best of my knowledge.

Signature: _____
 Print Initials: _____
 Firm: _____

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

Facility/Project Name Flambeau Mine	Local Grid Location of Well 40, 550.5 ft. <input checked="" type="checkbox"/> N. <input type="checkbox"/> E. <input type="checkbox"/> S. 38824.8 ft. <input type="checkbox"/> W.	Well Name WW11
Facility License, Permit or Monitoring Number 03180	Grid Origin Location Lat. _____ Long. _____ or St. Plane _____ ft. N. _____ ft. E.	Wis. Unique Well Number _____ DNR Well Number _____
Type of Well Water Table Observation Well <input type="checkbox"/> L1 Piezometer <input checked="" type="checkbox"/> 12	Section Location of Waste/Source NW 1/4 of SE 1/4 of Sec. 9, T. 34N, R. 6 <input checked="" type="checkbox"/> W.	Date Well Installed 0 7 / 1 4 / 9 4 m m d d y y
Distance Well is From Waste/Source Boundary ft.	Location of Well Relative to Waste/Source u <input type="checkbox"/> Upgradient s <input type="checkbox"/> Sidegradient d <input type="checkbox"/> Downgradient n <input type="checkbox"/> Not Known	Well Installed By: (Persons Name and Firm) Brad Davis Huntingdon Engineering & Environmental, Inc.
Is Well A Point of Enforcement Std. Application? <input type="checkbox"/> Yes <input type="checkbox"/> No		

A. Protective pipe, top elevation 1111.17 ft. MSL

B. Well casing, top elevation 1111.02 ft. MSL

C. Land surface elevation 1108.96 ft. MSL

D. Surface seal, bottom 1106.9 ft. MSL or 2.0 ft.

12. USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock PE ~ E sst


13. Sieve analysis attached? Yes No

14. Drilling method used: Rotary 50
 Hollow Stem Auger 41
 Other

15. Drilling fluid used: Water 02 Air 01
 Drilling Mud 03 None 99

16. Drilling additives used? Yes No
 Describe NA

17. Source of water (attach analysis): NA



1. Cap and lock? Yes No

2. Protective cover pipe:
 a. Inside diameter: 4.0 in.
 b. Length: 7.0 ft.
 c. Material: Steel 04
 Other

d. Additional protection? Yes No
 If yes, describe: _____

3. Surface seal:
 Bentonite 30
 Concrete 01
 Other

4. Material between well casing and protective pipe:
 Bentonite 30
 Annular space seal

5. Annual space seal:
 a. Granular Bentonite 33
 b. ___ lbs/gal mud weight.. Bentonite-sand slurry 35
 c. ___ lbs/gal mud weight..... Bentonite slurry 31
 d. ___ % Bentonite..... Bentonite-cement grout 50
 e. 7.6 Ft³ volume added for any of the above

f. How installed
 Tremie 01
 Tremie pumped 02
 Gravity 08

6. Bentonite seal:
 a. Bentonite granules 33
 b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
 c. Chips _____ Other

7. Fine sand material: mfr, product name & mesh size
 a. Badger Mining, Silica #20-#40
 b. Volume added 0.6 ft³

8. Filter pack material: mfr, product name and mesh size
 a. American Materials, Red Flint #30
 b. Volume added 4.5 ft³

9. Well casing: Flush threaded PVC schedule 40 23
 Flush threaded PVC schedule 80 24
 Other

10. Screen material: SAME
 a. Screen type: Factory cut 11
 Continuous slot 01
 Other

b. Manufacturer Certainteed Pipe Co.
 c. Slot size: 0.010 in.
 d. Slotted length: 10.0 ft.

11. Backfill material (below filter pack):
 None 14
 Other

E. Bentonite seal, top _____ ft. MSL or 2.0 ft.

F. Fine sand, top _____ ft. MSL or 26.0 ft.

G. Filter pack, top _____ ft. MSL or 28.0 ft.

H. Screen joint, top _____ ft. MSL or 30.0 ft.

I. Well bottom _____ ft. MSL or 40.0 ft.

J. Filter pack, bottom _____ ft. MSL or 42.0 ft.

K. Borehole, bottom _____ ft. MSL or 42.0 ft.

L. Borehole, diameter 8.0 in.

M. O.D. well casing 3.37 in.

N. I.D. well casing 2.02 in.

I hereby certify that the information on this form is true and correct to the best of my knowledge

Signature _____ Firm
 Huntingdon Engineering & Environmental, Inc.

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 150, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form any results in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. NOTE: Shaded areas are for DNR use only. See instructions for more information including where the completed form should be sent.

Route 10: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Project Name <u>Flambeau Mining</u>	County Name <u>Rusk</u>	Well Name <u>WW-11</u>
Facility License, Permit or Monitoring Number	County Code	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other
3. Time spent developing well 150 min.
4. Depth of well (from top of well casing) 74.6 ft.
5. Inside diameter of well 2.00 in.
6. Volume of water in filter pack and well casing 14.2 gal.
7. Volume of water removed from well 143.7 gal.
8. Volume of water added (if any) _____ gal.
9. Source of water added _____
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>21.33</u> ft.	<u>21.32</u> ft.
Date	b. <u>11/6/95</u> m m d d y y	<u>11/9/95</u> m m d d y y
Time	c. <u>2:14</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.	<u>11:25</u> <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<u>4.5</u> inches	_____ inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>Br to Lt Br</u>	Clear <input type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe) <u>very slight to clear</u>

Fill in if drilling fluids were used and well is at solid waste facility:

14. Total suspended solids	_____ mg/l	_____ mg/l
15. COD	_____ mg/l	_____ mg/l

16. Additional comments on development:

Well developed by: Person's Name and Firm

Name: Jack Christman

Firm: Flambeau Mining

I hereby certify that the above information is true and correct to the best of my knowledge.

Signature: [Signature]

Print Initials: JAC

Firm: Flambeau Mining

NOTE: Should never be for DNR use only. See instructions for more information including a list of county codes.

Project Name
Flambeau Mine
 License, Permit or Monitoring Number
03180
 Type of Well
 Water Table Observation Well 11
 Piezometer 12
 Distance Well Is From Waste/Source Boundary
 _____ ft.
 Well A Point of Enforcement Std. Application?
 Yes No

Local Grid Location of Well
39748.1 ft. N. 38,963.5 ft. E.
 S. W.
 Grid Origin Location
 Lat. _____ Long. _____ or _____
 St. Plane _____ ft. N. _____ ft. E.
 Section Location of Waste/Source
SW 1/4 of SE 1/4 of Sec. 9 T. 34 N. R. 6 E. W.
 Location of Well Relative to Waste/Source
 u Upgradient s Sidegradient
 d Downgradient n Not Known

Well Name
WW-15
 Wis. Unique Well Number _____ DNR Well Number _____
 Date Well Installed
08/11/94
 m m d d y y
 Well Installed By: (Person's Name and Firm)
Jim Hackney
Ames Construction Co

Protective pipe, top elevation 1084.84 ft. MSL
 Well casing, top elevation 1083.70 ft. MSL
 Land surface elevation 1081.7 ft. MSL
 Surface seal, bottom 1076.7 ft. MSL or 4.0 ft.

USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock


Sieve analysis attached? Yes No
 Drilling method used:
 Rotary 50
 Hollow Stem Auger 41
Per percussion Other 1

Drilling fluid used: Water 02 Air 01
 Drilling Mud 03 None 99

Sealing additives used? Yes No
 Describe _____

Source of water (attach analysis):
NA

Bentonite seal, top 1070.5 ft. MSL or _____ ft.
 Fine sand, top 1068.0 ft. MSL or _____ ft.
 Filter pack, top 1064.0 ft. MSL or _____ ft.
 Screen joint, top 1062.0 ft. MSL or _____ ft.
 Well bottom 1057.0 ft. MSL or _____ ft.
 Filter pack, bottom 1056.5 ft. MSL or _____ ft.
 Borehole, bottom 1056.5 ft. MSL or _____ ft.
 Borehole diameter 5.0 in.
 M. O.D. well casing 2.37 in.
 N. O.D. well casing 2.02 in.



1. Cap and lock? capped Yes No
2. Protective cover pipe:
 - a. Inside diameter: 4.0 in.
 - b. Length: 5.5 ft.
 - c. Material: Steel 01
Other 02
 - d. Additional protection? Yes No
 - If yes, describe: _____
3. Surface seal:
 - Bentonite 30
 - Concrete 01
 - Other 02
4. Material between well casing and protective pipe:
 - Bentonite 30
 - Annular space seal 02
 - Other 01 Drill Cuttings
5. Annular space seal:
 - a. Granular Bentonite 33
 - b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
 - c. _____ Lbs/gal mud weight Bentonite slurry 31
 - d. _____ % Bentonite Bentonite-cement grout 50
 - e. _____ Ft³ volume added for any of the above
 - f. How installed: Tremie 01
Tremie pumped 02
Gravity 08
6. Bentonite seal:
 - a. Bentonite granules 33
 - b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
 - c. _____ Other 02
7. Fine sand material: Manufacturer, product name & mesh size
 - a. Clean Cambrian Sand
 - b. Volume added _____ ft³
8. Filter pack material: Manufacturer, product name and mesh size
 - a. 0.25" washed pea gravel
 - b. Volume added _____ ft³
9. Well casing:
 - Flush threaded PVC schedule 40 23
 - Flush threaded PVC schedule 80 24
 - Other 02
10. Screen material: PVC
 - a. Screen type: Factory cut 11
Continuous slot 10
Other 02
 - b. Manufacturer _____
 - c. Slot size: 0.010 in.
 - d. Slotted length: 5.0 ft.
11. Backfill material (below filter pack):
 - None 10
 - Other 02

I hereby certify that the information on this form is true and correct to the best of my knowledge.

Signature Frank R. May Firm Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$10,000 for each violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each violation.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flambeau Mine</u>	County Name <u>Rusk</u>	Well Name <u>WW-15</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No

2. Well development method

surged with bailer and bailed	<input type="checkbox"/> 41
surged with bailer and pumped	<input type="checkbox"/> 61
surged with block and bailed	<input type="checkbox"/> 42
surged with block and pumped	<input type="checkbox"/> 62
surged with block, bailed and pumped	<input type="checkbox"/> 70
compressed air	<input checked="" type="checkbox"/> 20
bailed only	<input type="checkbox"/> 10
pumped only	<input type="checkbox"/> 51
pumped slowly	<input type="checkbox"/> 50
Other _____	<input type="checkbox"/>

3. Time spent developing well 30 min.

4. Depth of well (from top of well casing) 26.7 ft.

5. Inside diameter of well 2.02 in.

6. Volume of water in filter pack and well casing 0 gal.

7. Volume of water removed from well 10 gal.

8. Volume of water added (if any) 0 gal.

9. Source of water added N/A

10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>15.40</u> ft.	<u>14.61</u> ft.
Date	b. <u>08/11/94</u> m m d d y y	<u>08/11/94</u> m m d d y y
Time	c. <u>12:50</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.	<u>1:16</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.
12. Sediment in well bottom	<u>/</u> inches	<u>/</u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>Muddy</u>	Clear <input type="checkbox"/> 20 Turbid <input checked="" type="checkbox"/> 25 (Describe) <u>Muddy</u>
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<u>/</u> mg/l	<u>/</u> mg/l
15. COD	<u>/</u> mg/l	<u>/</u> mg/l

16. Additional comments on development:

Well developed by: Person's Name and Firm

Name: Jim Hackney

Firm: Ames Construction Co

I hereby certify that the above information is true and correct to the best of my knowledge.

Signature: Shwade R. May

Print Initials: ERM

Firm: Consulting Mining Geologists

NOTE: Check the cap art for DNR use only. See instructions for more information including a list of county codes.

Project Name
Fleming Mine

License, Permit or Monitoring Number
03180

Type of Well
Water Table Observation Well 11
Piezometer 12

Distance Well Is From Waste/Source Boundary
ft. _____

Well A Point of Enforcement Std. Application?
 Yes No

Local Grid Location of Well
39751.6 ft. N. S. 38962.0 ft. E. W.

Grid Origin Location
Lat. _____ Long. _____ or
St. Plane _____ ft. N. _____ ft. E.

Section Location of Waste/Source
SW 1/4 of SE 1/4 of Sec. 9, T. 34N, R. 6 E. W.

Location of Well Relative to Waste/Source
u Upgradient s Sidegradient
d Downgradient n Not Known

Well Name
WW-16

Wis. Unique Well Number _____ DNR Well Number _____

Date Well Installed
08/11/94
m m d d y y

Well Installed By: (Person's Name and Firm)
Jim Hackney
Ames Construction Co

Protective pipe, top elevation 1084.49 ft. MSL

Well casing, top elevation 1084.36 ft. MSL

Ground surface elevation 1081.6 ft. MSL

Surface seal, bottom 1076.6 ft. MSL or 7.0 ft.

USCS classification of soil near screen:
GP GM GC GW SW SP
SM SC ML MH CL CH
Bedrock

Sieve analysis attached? Yes No

Drilling method used:
Rotary 50
Hollow Stem Auger 41
Per percussion Other

Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99

Sealing additives used? Yes No

Describe _____

Source of water (attach analysis):
NA

Bentonite seal, top 1044.7 ft. MSL or _____ ft.

Fine sand, top 1039.7 ft. MSL or _____ ft.

Filter pack, top 1038.2 ft. MSL or _____ ft.

Screen joint, top 1036.2 ft. MSL or _____ ft.

Well bottom 1031.2 ft. MSL or _____ ft.


Filter pack, bottom 1030.7 ft. MSL or _____ ft.

Borehole, bottom 1030.7 ft. MSL or _____ ft.

Borehole diameter 5.0 in.

O.D. well casing 2.37 in.

I.D. well casing 2.02 in.



1. Cap and lock? Capped Yes No

2. Protective cover pipe:
a. Inside diameter: 4.0 in.
b. Length: 5.5 ft.
c. Material: Steel 04
Other

d. Additional protection? Yes No
If yes, describe: _____

3. Surface seal:
Bentonite 30
Concrete 01
Other

4. Material between well casing and protective pipe:
Bentonite 30
Annular space seal

Drill Cuttings Other

5. Annular space seal:
a. Granular Bentonite 33
b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
c. _____ Lbs/gal mud weight Bentonite slurry 31
d. _____ % Bentonite Bentonite-cement grout 50
e. _____ Ft³ volume added for any of the above
f. How installed: Tremie 01
Tremie pumped 02
Gravity 08

6. Bentonite seal:
a. Bentonite granules 33
b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
c. _____ Other

7. Fine sand material: Manufacturer, product name & mesh size
a. Clean Cambrian Sand
b. Volume added _____ ft³

8. Filter pack material: Manufacturer, product name and mesh size
a. 0.25" Washed Pea Gravel
b. Volume added _____ ft³

9. Well casing: Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other

10. Screen material: PVC
a. Screen type: Factory cut 11
Continuous slot 01
Other

b. Manufacturer _____
c. Slot size: 0.010 in.
d. Slotted length: 5.0 ft.

11. Backfill material (below filter pack): Non 14
Other

I hereby certify that the information on this form is true and correct to the best of my knowledge.

Signature Shwade R. May Firm Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats. and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flamborn Mine</u>	County Name <u>Rusk</u>	Well Name <u>WW-16</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other
3. Time spent developing well 30 min.
4. Depth of well (from top of well casing) 53.2 ft.
5. Inside diameter of well 2.02 in.
6. Volume of water in filter pack and well casing 0 gal.
7. Volume of water removed from well 15.0 gal.
8. Volume of water added (if any) 0.0 gal.
9. Source of water added NA
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>15.50</u> ft.	<u>15.81</u> ft.
Date	b. <u>08/11/94</u> m m d d y y	<u>08/11/94</u> m m d d y y
Time	c. <u>1:44</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.	<u>2:30</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.
12. Sediment in well bottom	<u>/</u> inches	<u>/</u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>Muddy</u>	Clear <input type="checkbox"/> 20 Turbid <input checked="" type="checkbox"/> 25 (Describe) <u>Muddy</u>
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<u>/</u> mg/l	<u>/</u> mg/l
15. COD	<u>/</u> mg/l	<u>/</u> mg/l

16. Additional comments on development:

Well developed by Person's Name and Firm

Name: Jim Hackney

Firm: Ames Construction Co

I hereby certify that the above information is true and correct to the best of my knowledge.

Signature: Shirley R. May

Print Initials: ERM

Firm: Consulting Mining Geologist

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

Well Name: WW-17

Local Grid Location of Well: 39794.8 ft. N. 38914.0 ft. E. W. S.

Grid Origin Location: _____

Lat. _____ Long. _____ or _____

Date Well Installed: 08/11/94
 m m d d y y

Well Installed By: (Person's Name and Firm)
Jim Hackney
Ames Construction Co

Section Location of Waste/Source: SW 1/4 of SE 1/4 of Sec. 9, T. 34 N, R. 6 E. W.

Location of Well Relative to Waste/Source:
 u Upgradient s Sidegradient
 d Downgradient n Not Known

Protective pipe, top elevation 1083.19 ft. MSL

Well casing, top elevation 1083.14 ft. MSL

Ground surface elevation 1081.0 ft. MSL

Surface seal, bottom 1077.0 ft. MSL or 4.0 ft.

USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock

Sieve analysis attached? Yes No


Drilling method used: Rotary 50
 Hollow Stem Auger 41
Permutation Other

Drilling fluid used: Water 02 Air 01
 Drilling Mud 03 None 99

Sealing additives used? Yes No

Describe _____

Source of water (attach analysis):
NA



1. Cap and lock? Capped Yes No

2. Protective cover pipe:
 a. Inside diameter: 4.0 in.
 b. Length: 5.5 ft.
 c. Material: Steel 04
 Other
 d. Additional protection? Yes No
 If yes, describe: _____

3. Surface seal:
 Bentonite 30
 Concrete 01
 Other

4. Material between well casing and protective pipe:
 Bentonite 30
 Annular space seal
 Other

5. Annular space seal:
 a. Granular Bentonite 33
 b. _____ Lbs/gal mud weight ... Bentonite-sand slurry 35
 c. _____ Lbs/gal mud weight ... Bentonite slurry 31
 d. _____ % Bentonite ... Bentonite-cement grout 50
 e. _____ Ft³ volume added for any of the above
 f. How installed: Tremie 01
 Tremie pumped 02
 Gravity 08

6. Bentonite seal:
 a. Bentonite granules 33
 b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
 c. _____ Other

7. Fine sand material: Manufacturer, product name & mesh size
 a. Clean Cambrian Sand
 b. Volume added _____ ft³

8. Filter pack material: Manufacturer, product name and mesh size
 a. 0.25" washed pea gravel
 b. Volume added _____ ft³

9. Well casing:
 Flush threaded PVC schedule 40 23
 Flush threaded PVC schedule 80 24
 Other

10. Screen material: PVC
 a. Screen type: Factory cut 11
 Continuous slot 03
 Other
 b. Manufacturer _____
 c. Slot size: 0.10 in.
 d. Slotted length: 5.0 ft.

11. Backfill material (below filter pack):
 None 14
 Other

Bentonite seal, top 1071.4 ft. MSL or _____ ft.

Fine sand, top 1066.9 ft. MSL or _____ ft.

Filter pack, top 1064.9 ft. MSL or _____ ft.

Screen joint, top 1062.9 ft. MSL or _____ ft.

Well bottom 1057.9 ft. MSL or _____ ft.

Filter pack, bottom 1057.4 ft. MSL or _____ ft.

Borehole, bottom 1053.9 ft. MSL or _____ ft.

Borehole, diameter 5.0 in.

I.D. well casing 2.37 in.

O.D. well casing 2.02 in.

I hereby certify that the information on this form is true and correct to the best of my knowledge.

Signature: Shirley R. Marx Firm: Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$10,000 for each violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each violation.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name Flambean Mine	County Name Rusk	Well Name WW-17
Facility License, Permit or Monitoring Number 03180	County Code 55	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No

2. Well development method

surged with boiler and bailed	<input type="checkbox"/> 41
surged with boiler and pumped	<input type="checkbox"/> 61
surged with block and bailed	<input type="checkbox"/> 42
surged with block and pumped	<input type="checkbox"/> 62
surged with block, bailed and pumped	<input type="checkbox"/> 70
compressed air	<input checked="" type="checkbox"/> 20
bailed only	<input type="checkbox"/> 10
pumped only	<input type="checkbox"/> 51
pumped slowly	<input type="checkbox"/> 50
Other _____	<input type="checkbox"/>

3. Time spent developing well 30 min.

4. Depth of well (from top of well casing) 25.2 ft.

5. Inside diameter of well 5.0 in.

6. Volume of water in filter pack and well casing 0.0 gal.

7. Volume of water removed from well 18.0 gal.

8. Volume of water added (if any) 0.0 gal.

9. Source of water added NA

10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>15.82</u> ft.	<u>16.03</u> ft.
Date	b. <u>08/11/94</u> m m d d y y	<u>08/11/94</u> m m d d y y
Time	c. <u>3:37</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.	<u>4:40</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.
12. Sediment in well bottom	<u>/</u> inches	<u>/</u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>Muddy</u>	Clear <input type="checkbox"/> 20 Turbid <input checked="" type="checkbox"/> 25 (Describe) <u>Muddy</u>

Fill in if drilling fluids were used and well is at solid waste facility:

14. Total suspended solids	<u>/</u> mg/l	<u>/</u> mg/l
15. COD	<u>/</u> mg/l	<u>/</u> mg/l

16. Additional comments on development:

Well developed by: Person's Name and Firm

Name: Jim Hackney

Firm: Ames Construction Co

I hereby certify that the above information is true and correct to the best of my knowledge.

Signature: Shirley R. May

Print Initials: F.R.M.

Firm: Consulting Mining Geologists


NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

Project Name: Urban Mine
 License, Permit or Monitoring Number: 03180
 Type of Well: Water Table Observation Well 11
 Piezometer 12
 Distance Well Is From Waste/Source Boundary: _____ ft.
 Well A Point of Enforcement Std. Application? Yes No

Local Grid Location of Well: 39798.3 ft. N. S. 38911.9 ft. E. W.
 Grid Origin Location: _____
 St. Plane: _____ ft. N. _____ ft. E.
 Section Location of Waste/Source: SW 1/4 of SE 1/4 of Sec. 9, T. 34N, R. 6 E. W.
 Location of Well Relative to Waste/Source: u Upgradient s Sidegradient d Downgradient n Not Known

Well Name: WW-18
 Wis. Unique Well Number: _____ DNR Well Number: _____
 Date Well Installed: 08/11/94
 Well Installed By: (Person's Name and Firm) Jim Mackney Ames Construction Co

Protective pipe, top elevation: 1083.90 ft. MSL
 Well casing, top elevation: 1083.38 ft. MSL
 Land surface elevation: 1081.4 ft. MSL
 Surface seal, bottom: 1077.4 ft. MSL or _____ ft.
 USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock
 Sieve analysis attached? Yes No
 Drilling method used: Rotary 50
Percussion Hollow Stem Auger 41
 Other
 Drilling fluid used: Water 02 Air 01
 Drilling Mud 03 None 99
 Sealing additives used? Yes No
 Describe: _____
 Source of water (attach analysis): NA



1. Cap and lock? Cap Yes No
 2. Protective cover pipe:
 a. Inside diameter: 4.0 in.
 b. Length: 5.5 ft.
 c. Material: Steel 04
 Other
 d. Additional protection? Yes No
 If yes, describe: _____
 3. Surface seal: Bentonite 30
 Concrete 01
 Other
 4. Material between well casing and protective pipe: Bentonite 30
 Annular space seal
Drill Cuttings Other
 5. Annular space seal:
 a. Granular Bentonite 33
 b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
 c. _____ Lbs/gal mud weight Bentonite slurry 31
 d. _____ % Bentonite Bentonite-cement grout 50
 e. _____ Ft³ volume added for any of the above
 f. How installed: Tremie 01
 Tremie pumped 02
 Gravity 08
 6. Bentonite seal: a. Bentonite granules 33
 b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
 c. _____ Other
 7. Fine sand material: Manufacturer, product name & mesh size
 a. Clean Cambrian Sand
 b. Volume added _____ ft³
 8. Filter pack material: Manufacturer, product name and mesh size
 a. 0.25" Washed Pea Gravel
 b. Volume added _____ ft³
 9. Well casing: Flush threaded PVC schedule 40 23
 Flush threaded PVC schedule 80 24
 Other
 10. Screen material: PVC
 a. Screen type: Factory cut 11
 Continuous slot 01
 Other
 b. Manufacturer: _____
 c. Slot size: 0.010 in.
 d. Slotted length: 5.0 ft.
 11. Backfill material (below filter pack): None 14
massive Sulfides Other

Bentonite seal, top: 1054.1 ft. MSL or _____ ft.
 Fine sand, top: 1050.1 ft. MSL or _____ ft.
 Filter pack, top: 1048.1 ft. MSL or _____ ft.
 Screen joint, top: 1046.1 ft. MSL or _____ ft.
 Well bottom: 1041.1 ft. MSL or _____ ft.
 Filter pack, bottom: 1040.6 ft. MSL or _____ ft.
 Borehole, bottom: 1025.4 ft. MSL or _____ ft.
 Borehole diameter: 5.0 in.
 O.D. well casing: 2.37 in.
 I.D. well casing: 2.02 in.

I hereby certify that the information on this form is true and correct to the best of my knowledge.
 Signature: Shane R. May Firm: Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. In accordance with ch. 160, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation.

Route 10: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flambeau Mine</u>	County Name <u>Rusk</u>	Well Name <u>WW-18</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No

2. Well development method

surged with bailer and bailed	<input type="checkbox"/> 41
surged with bailer and pumped	<input type="checkbox"/> 61
surged with block and bailed	<input type="checkbox"/> 42
surged with block and pumped	<input type="checkbox"/> 62
surged with block, bailed and pumped	<input type="checkbox"/> 70
compressed air	<input checked="" type="checkbox"/> 20
bailed only	<input type="checkbox"/> 10
pumped only	<input type="checkbox"/> 51
pumped slowly	<input type="checkbox"/> 50
Other _____	<input type="checkbox"/>

3. Time spent developing well 90 min.

4. Depth of well (from top of well casing) 42.3 ft.

5. Inside diameter of well 5.0 in.

6. Volume of water in filter pack and well casing 0.0 gal.

7. Volume of water removed from well 100.0 gal.

8. Volume of water added (if any) 0.0 gal.

9. Source of water added NA

10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>17.86</u> ft.	<u>18.05</u> ft.
Date	b. <u>08/11/94</u> m m d d y y	<u>08/11/94</u> m m d d y y
Time	c. <u>5:10</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.	<u>6:35</u> <input type="checkbox"/> a.m. <input checked="" type="checkbox"/> p.m.
12. Sediment in well bottom	<u>15.5</u> ft	_____ inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>Muddy</u>	Clear <input type="checkbox"/> 20 Turbid <input checked="" type="checkbox"/> 25 (Describe) <u>Muddy</u>
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	_____ mg/l	_____ mg/l
15. COD	_____ mg/l	_____ mg/l

16. Additional comments on development:

Well developed by: Person's Name and Firm

Name: Jim Hackney

Firm: Ames Construction Co

I hereby certify that the above information is true and correct to the best of my knowledge.

Signature: Shirley R. May

Print Initials: ERM

Firm: Consulting Mining Geologist

Well Name: 104-18

Local Grid Location of Well: 39779.6 ft. N S 38989.3 ft. E W

Grid Origin Location: _____

Lat. _____ Long. _____ or _____

St. Plane _____ ft. N. _____ ft. E.

Section Location of Waste/Source: SW 1/4 of SE 1/4 of Sec. 9, T. 34 N, R. 6 E W

Location of Well Relative to Waste/Source: Upgradient S Sidegradient Downgradient n Not Known

Well Installed By: (Person's Name and Firm) Jim Hackney
Ames Construction Co

Unique Well Number: _____ DNR Well Number: _____

Date Well Installed: 09/09/94
m m d d y y

Well Installed By: (Person's Name and Firm) Jim Hackney
Ames Construction Co

Protective pipe, top elevation _____ ft. MSL

Well casing, top elevation 1043.73 ft. MSL

Land surface elevation 1041.7 ft. MSL

Surface seal, bottom _____ ft. MSL or _____ ft.

USCS classification of soil near screen:
GP GM GC GW SW SP
SM SC ML MH CL CH
Bedrock

Sieve analysis attached? Yes No


Drilling method used: Rotary 50
Hollow Stem Auger 41
Percussion Other

Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99

Additives used? Yes No

Describe _____

Source of water (attach analysis): _____



1. Cap and lock? capped Yes No

2. Protective cover pipe:
a. Inside diameter: _____ in.
b. Length: _____ ft.
c. Material: Steel 04
Other _____
d. Additional protection? Yes No
If yes, describe: _____

3. Surface seal: Bentonite 30
Concrete 01
Other _____

4. Material between well casing and protective pipe: Bentonite 30
Annular space seal _____
Drill hole cuttings Other

5. Annular space seal:
a. Granular Bentonite 33
b. _____ Lbs/gal mud weight ... Bentonite-sand slurry 35
c. _____ Lbs/gal mud weight ... Bentonite slurry 31
d. _____ % Bentonite ... Bentonite-cement grout 50
e. _____ Ft³ volume added for any of the above
f. How installed: Tremie 01
Tremie pumped 02
Gravity 08

6. Bentonite seal: a. Bentonite granules 33
b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
c. _____ Other

7. Fine sand material: Manufacturer, product name & mesh size
a. Clean Cambrian Sand
b. Volume added _____ ft³

8. Filter pack material: Manufacturer, product name and mesh size
a. _____
b. Volume added _____ ft³

9. Well casing: Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other _____

10. Screen material: PVC
a. Screen type: Factory cut 11
Continuous slot 01
Other

b. Manufacturer _____
c. Slot size: 0.010 in.
d. Slotted length: 5.0 ft.

11. Backfill material (below filter pack): None 14
Other

Bentonite seal, top 1007.1 ft. MSL or _____ ft.

Fine sand, top 1005.1 ft. MSL or _____ ft.

Filter pack, top 1004.1 ft. MSL or _____ ft.

Screen joint, top _____ ft. MSL or _____ ft.

Well bottom 998.1 ft. MSL or 45.6 ft.

Filter pack, bottom _____ ft. MSL or _____ ft.

Borehole, bottom _____ ft. MSL or _____ ft.

Borehole, diameter 5.0 in.

O.D. well casing 2.37 in.

I.D. well casing 2.02 in.

I, Shirley R. May, certify that the information on this form is true and correct to the best of my knowledge.
Signature: _____ Firm: Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. NOTE: Shaded areas are for DNR use only. See instructions for more information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flambeau Mine</u>	County Name <u>Rusk</u>	Well Name <u>104-18</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No

2. Well development method

surged with bailer and bailed	<input type="checkbox"/> 41
surged with bailer and pumped	<input type="checkbox"/> 61
surged with block and bailed	<input type="checkbox"/> 42
surged with block and pumped	<input type="checkbox"/> 62
surged with block, bailed and pumped	<input type="checkbox"/> 70
compressed air	<input checked="" type="checkbox"/> 20
bailed only	<input type="checkbox"/> 10
pumped only	<input type="checkbox"/> 51
pumped slowly	<input type="checkbox"/> 50
Other	<input type="checkbox"/>

3. Time spent developing well 10 min.

4. Depth of well (from top of well casing) 45.6 ft.

5. Inside diameter of well 2.02 in.

6. Volume of water in filter pack and well casing 0 gal.

7. Volume of water removed from well 40.0 gal.

8. Volume of water added (if any) 0 gal.

9. Source of water added NA

10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>0.00</u> ft.	<u>0.00</u> ft.
Date	b. <u>09/09/94</u> m m d d y y	<u>09/09/94</u> m m d d y y
Time	c. <u>10:00</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u>10:30</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<u>/</u> inches	<u>/</u> inches
13. Water clarity	Clear <input checked="" type="checkbox"/> 10 Turbid <input type="checkbox"/> 15 (Describe)	Clear <input checked="" type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe)
Fill in if drilling fluids were used and well is at solid waste facility:		
14. Total suspended solids	<u>/</u> mg/l	<u>/</u> mg/l
15. COD	<u>/</u> mg/l	<u>/</u> mg/l

16. Additional comments on development:
Artesian < 2 gpm. protector cap on order to be installed in Spring. 10/1/95

Well developed by: Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: <u>Jim Hackney</u>	Signature: <u>Shirley R. May</u>
Firm: <u>Ames Construction Co</u>	Print Initials: <u>ERM</u>
	Firm: <u>Consulting Mining Geologist</u>

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

City/Project Name <u>Flambeau Mine</u>	Local Grid Location of Well 39790.8 ft. <input checked="" type="checkbox"/> N. 38976.6 ft. <input checked="" type="checkbox"/> E. <input type="checkbox"/> S. <input type="checkbox"/> W.	Well Name <u>104-19</u>
Permit or Monitoring Number	Grid Origin Location	Wis. Unique Well Number DNR Well Number
Type of Well Water Table Observation Well <input type="checkbox"/> 11 Piezometer <input checked="" type="checkbox"/> 12	Lat. _____ Long. _____ or St. Plane _____ ft. N. _____ ft. E.	Date Well Installed <u>09/26/94</u> m m d d y y
Distance Well Is From Waste/Source Boundary ft.	Section Location of Waste/Source <u>SW 1/4 of SE 1/4 of Sec. 9, T. 34 N, R. 6</u> <input type="checkbox"/> E. <input checked="" type="checkbox"/> W.	Well Installed By: (Person's Name and Firm) <u>Jim Hackney</u> <u>Ames Construction Co</u>
Well A Point of Enforcement Std. Application? <input type="checkbox"/> Yes <input type="checkbox"/> No	Location of Well Relative to Waste/Source u <input type="checkbox"/> Upgradient s <input type="checkbox"/> Sidegradient d <input type="checkbox"/> Downgradient n <input type="checkbox"/> Not Known	

Protective pipe, top elevation _____ ft. MSL

Well casing, top elevation 1043.91 ft. MSL

Wellhead and surface elevation 1040.6 ft. MSL

Surface seal, bottom _____ ft. MSL or _____ ft.

USCS classification of soil near screen:
GP GM GC GW SW SP
SM SC ML MH CL CH
Bedrock


Sieve analysis attached? Yes No

Drilling method used: Rotary 50
Hollow Stem Auger 41
Percussion Other

Drilling fluid used: Water 02 Air 01
Drilling Mud 03 None 99

Additives used? Yes No
Describe NA

Source of water (attach analysis):
NA



1. Cap and lock? capped Yes No

2. Protective cover pipe:
a. Inside diameter: _____ in.
b. Length: _____ ft.
c. Material: Steel 04
Other

d. Additional protection? Yes No
If yes, describe: _____

3. Surface seal: Bentonite 30
Concrete 01
Other

4. Material between well casing and protective pipe: Bentonite 30
Annular space seal
Drill cuttings Other

5. Annular space seal:
a. Granular Bentonite 33
b. _____ Lbs/gal mud weight . . . Bentonite-sand slurry 35
c. _____ Lbs/gal mud weight Bentonite slurry 31
d. _____ % Bentonite Bentonite-cement grout 50
e. _____ Ft³ volume added for any of the above
f. How installed: Tremie 01
Tremie pumped 02
Gravity 08

6. Bentonite seal:
a. Bentonite granules 33
b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 32
c. _____ Other

7. Fine sand material: Manufacturer, product name & mesh size
a. Clean Cambrian Sand
b. Volume added _____ ft³

8. Filter pack material: Manufacturer, product name and mesh size
a. _____
b. Volume added _____ ft³

9. Well casing: Flush threaded PVC schedule 40 23
Flush threaded PVC schedule 80 24
Other

10. Screen material: PVC
a. Screen type: Factory cut 11
Continuous slot 01
Other

b. Manufacturer _____
c. Slot size: (0.010 in.)
d. Slotted length: 5.0 ft.

11. Backfill material (below filter pack): None 14
Other

I hereby certify that the information on this form is true and correct to the best of my knowledge.
Signature Shane R. May Firm Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. NOTE: Shaded areas are for DNR use only. See instructions for more information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <u>Flambeau Mine</u>	County Name <u>Rusk</u>	Well Name <u>104-19</u>
Facility License, Permit or Monitoring Number <u>03180</u>	County Code <u>55</u>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No

2. Well development method

surged with bailer and bailed	<input type="checkbox"/> 41
surged with bailer and pumped	<input type="checkbox"/> 61
surged with block and bailed	<input type="checkbox"/> 42
surged with block and pumped	<input type="checkbox"/> 62
surged with block, bailed and pumped	<input type="checkbox"/> 70
compressed air	<input checked="" type="checkbox"/> 20
bailed only	<input type="checkbox"/> 10
pumped only	<input type="checkbox"/> 51
pumped slowly	<input type="checkbox"/> 50
Other	<input type="checkbox"/>

3. Time spent developing well 10 min.

4. Depth of well (from top of well casing) 77.6 ft.

5. Inside diameter of well 2.02 in.

6. Volume of water in filter pack and well casing 0 gal.

7. Volume of water removed from well 55.5 gal.

8. Volume of water added (if any) 0 gal.

9. Source of water added NA

10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u>3.00</u> ft.	<u>3.50</u> ft.
Date	b. <u>09/26/94</u> m m d d y y	<u>09/26/94</u> m m d d y y
Time	c. <u>9:30</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u>10:00</u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	_____ inches	_____ inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u>Muddy</u>	Clear <input checked="" type="checkbox"/> 20 Turbid <input type="checkbox"/> 25 (Describe) <u>Almost clear.</u>

Fill in if drilling fluids were used and well is at solid waste facility:

14. Total suspended solids	_____ mg/l	_____ mg/l
15. COD	_____ mg/l	_____ mg/l

16. Additional comments on development:
Protector Cap on order for installation 10/1/95

Well developed by: Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: <u>Jim Hackney</u>	Signature: <u>Shirley R. May</u>
Firm: <u>Ames Construction Co</u>	Print Initials: <u>ERM</u>
	Firm: <u>Consulting Mining Geologist</u>

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

Company/Project Name
Flambeau Mining Company
 License, Permit or Monitoring Number
03180

Local Grid Location of Well
39827.8 ft. N. 38934.0 ft. E.
 S. W.

Well Name
104-20

Type of Well Water Table Observation Well 11
 Piezometer 12

Grid Origin Location
 Lat. _____ Long. _____ or
 St. Plane _____ ft. N. _____ ft. E.

Wis. Unique Well Number _____ DNR Well Number _____

Distance Well Is From Waste/Source Boundary
 _____ ft.

Section Location of Waste/Source
NW 1/4 of SE 1/4 of Sec. 9, T. 34N, R. 6 E. W.

Date Well Installed
09/26/94
 m m d d y y


Well A Point of Enforcement Std. Application?
 Yes No

Location of Well Relative to Waste/Source
 Upgradient s Sidegradient
 Downgradient n Not Known

Well Installed By: (Person's Name and Firm)
Jim Hackney

Ames Construction Co

Protective pipe, top elevation _____ ft. MSL
 Well casing, top elevation 1042.09 ft. MSL
 Land surface elevation 1041.2 ft. MSL
 Surface seal, bottom _____ ft. MSL or _____ ft.



1. Cap and lock? Capped Yes No
2. Protective cover pipe:
 - a. Inside diameter: _____ in.
 - b. Length: _____ ft.
 - c. Material: Steel 0.4 Other
 - d. Additional protection? Yes No
 If yes, describe: _____
3. Surface seal:
 - Bentonite 3.0
 - Concrete 0.1
 - Other
4. Material between well casing and protective pipe:
 - Bentonite 3.0
 - Annular space seal
 - Drill Cuttings Other
5. Annular space seal:
 - a. Granular Bentonite 3.3
 - b. _____ Lbs/gal mud weight ... Bentonite-sand slurry 3.5
 - c. _____ Lbs/gal mud weight ... Bentonite slurry 3.1
 - d. _____ % Bentonite ... Bentonite-cement grout 5.0
 - e. _____ Ft³ volume added for any of the above
 - f. How installed:
 - Tremie 0.1
 - Tremie pumped 0.2
 - Gravity 0.8
6. Bentonite seal:
 - a. Bentonite granules 3.3
 - b. 1/4 in. 3/8 in. 1/2 in. Bentonite pellets 3.2
 - c. _____ Other
7. Fine sand material: Manufacturer, product name & mesh size
 a. Cambrian Sand
- b. Volume added _____ ft³
8. Filter pack material: Manufacturer, product name and mesh size
 a. _____
- b. Volume added _____ ft³
9. Well casing:
 - Flush threaded PVC schedule 40 2.3
 - Flush threaded PVC schedule 80 2.4
 - Other
10. Screen material: PVC 2" Class 40
 - a. Screen type:
 - Factory cut 1.1
 - Continuous slot 0.1
 - Other
 - b. Manufacturer _____
 - c. Slot size: 0.010 in.
 - d. Slotted length: 5.0 ft.
11. Backfill material (below filter pack):
 - None 1.4
 - Other

2. USCS classification of soil near screen:
 GP GM GC GW SW SP
 SM SC ML MH CL CH
 Bedrock

3. Sieve analysis attached? Yes No

4. Drilling method used: Rotary 5.0
 Hollow Stem Auger 4.1
Percussion Other

5. Drilling fluid used: Water 0.2 Air 0.1
 Drilling Mud 0.3 None 9.9

6. _____ additives used? Yes No
 Describe NA

7. Source of water (attach analysis):
NA

3. Bentonite seal, top 1007.6 ft. MSL or _____ ft.
 4. Fine sand, top 1005.6 ft. MSL or _____ ft.
 5. Filter pack, top 1003.6 ft. MSL or _____ ft.
 6. Screen joint, top 1001.6 ft. MSL or _____ ft.
 7. Well bottom 996.6 ft. MSL or 45.5 ft.
 8. Filter pack, bottom _____ ft. MSL or _____ ft.
 9. Borehole, bottom _____ ft. MSL or _____ ft.
 10. Borehole, diameter 5.0 in.
 11. O.D. well casing 2.37 in.
 12. I.D. well casing 2.02 in.

I hereby certify that the information on this form is true and correct to the best of my knowledge.
 Signature Shirley R. May Firm Consulting Mining Geologist

Please complete both sides of this form and return to the appropriate DNR office listed at the top of this form as required by chs. 144, 147 and 160, Wis. Stats., and ch. NR 141, Wis. Ad. Code. In accordance with ch. 144, Wis. Stats., failure to file this form may result in a forfeiture of not less than \$10, nor more than \$5000 for each day of violation. In accordance with ch. 147, Wis. Stats., failure to file this form may result in a forfeiture of not more than \$10,000 for each day of violation. NOTE: Shaded areas are for DNR use only. See instructions for more information including where the completed form should be sent.

Route to: Solid Waste Haz. Waste Wastewater
Env. Response & Repair Underground Tanks Other

Facility/Project Name <i>Flambeau Mining Company</i>	County Name <i>Rusk</i>	Well Name <i>104-20</i>
Facility License, Permit or Monitoring Number <i>03180</i>	County Code <i>55</i>	Wis. Unique Well Number
		DNR Well Number

1. Can this well be purged dry? Yes No
2. Well development method
- surged with bailer and bailed 41
 - surged with bailer and pumped 61
 - surged with block and bailed 42
 - surged with block and pumped 62
 - surged with block, bailed and pumped 70
 - compressed air 20
 - bailed only 10
 - pumped only 51
 - pumped slowly 50
 - Other *NONE*
3. Time spent developing well *10* min.
4. Depth of well (from top of well casing) *45.5* ft.
5. Inside diameter of well *2.02* in.
6. Volume of water in filter pack and well casing *0* gal.
7. Volume of water removed from well *30.0* gal.
8. Volume of water added (if any) *0* gal.
9. Source of water added *NA*
10. Analysis performed on water added? Yes No
(If yes, attach results)

	Before Development	After Development
11. Depth to Water (from top of well casing)	a. <u><i>6.38</i></u> ft.	<u><i>6.21</i></u> ft.
Date	b. <u><i>09/26/94</i></u> m m d d y y	<u><i>09/26/94</i></u> m m d d y y
Time	c. <u><i>11:30</i></u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.	<u><i>12:00</i></u> <input checked="" type="checkbox"/> a.m. <input type="checkbox"/> p.m.
12. Sediment in well bottom	<u><i>/</i></u> inches	<u><i>/</i></u> inches
13. Water clarity	Clear <input type="checkbox"/> 10 Turbid <input checked="" type="checkbox"/> 15 (Describe) <u><i>muddy</i></u>	Clear <input type="checkbox"/> 20 Turbid <input checked="" type="checkbox"/> 25 (Describe) <u><i>Cloudy</i></u>

Fill in if drilling fluids were used and well is at solid waste facility:

14. Total suspended solids	<u><i>/</i></u> mg/l	<u><i>/</i></u> mg/l
15. COD	<u><i>/</i></u> mg/l	<u><i>/</i></u> mg/l

16. Additional comments on development:
Protector pipe on order. 10/1/95

Well developed by: Person's Name and Firm	I hereby certify that the above information is true and correct to the best of my knowledge.
Name: <u><i>Jim Hackney</i></u>	Signature: <u><i>Ernie R. May</i></u>
Firm: <u><i>Ames Construction Co</i></u>	Print Initials: <u><i>ERM</i></u>
	Firm: <u><i>Consulting Mining Geologist</i></u>

NOTE: Shaded areas are for DNR use only. See instructions for more information including a list of county codes.

Appendix J

Liner Repair Documentation



July 13, 1994

Ms. Jana E. Murphy
Supervisor of Environmental Affairs
Flambeau Mining Company
N4100 Highway 27
Ladysmith, Wisconsin 54848

Re: Geomembrane Liner Repair Documentation, Type II Stockpile (Phase 1), Flambeau Mine,
Ladysmith, Wisconsin -- STS Project No. 20961XF

Dear Ms. Murphy:

As you requested, STS Consultants, Ltd., (STS) was at the above referenced site to observe the repair of two geomembrane panels damaged during operations at Flambeau Mine's Type II Stockpile (Phase 1). We understand that the 60 mil high density polyethylene (HDPE) geomembrane liner (panels P-224 and P-225) was damaged due to inappropriate use of the area for traffic by Flambeau contractors.

Damage to the panels consisted of numerous tears, deep scratches, and holes in the geomembrane. The damaged area had been uncovered by Flambeau Mine personnel prior to STS' arrival on site.

Geo-Synthetics Construction, Inc. (GSCI) of Waukesha, Wisconsin, extrusion welded a 6-foot by 12-foot 60 mil HDPE permanent patch over the damaged portion of panel P-225. Vacuum testing of the permanent patch was performed by GSCI and indicated an acceptable weld.

Due to lack of available HDPE, GSCI heat tacked smaller scrap pieces of HDPE as temporary patches over the remaining area of major damage. When additional material for the Phase 2 liner construction arrives at the site, permanent repairs will be performed in these areas. The area of temporary repairs does not receive runoff from the Type II Stockpile or the crushing operations.

Prior to performance of welding of the patches, GSCI performed trial welding to evaluate the performance of their extrusion welding machines and welding personnel. Four peel tests and three shear tests were performed on the trial weld samples and all test samples met the minimum test requirements. Criteria for acceptance of an extrusion welded seam tested in peel was defined as: a) failure by film tear bond (FTB), and b) the yield seam strength for the seam being at least 90 pounds per inch (ppi). Criteria for acceptance of an extrusion welded seam tested in shear was defined as: a) failure by FTB, and b) the yield seam strength for the seam being at least 120 ppi. Refer to the attached Trial Weld Information Form for additional information.

STS Consultants Ltd.
Consulting Engineers

1035 Kepler Drive
Green Bay, Wisconsin 54311
414.468.1978/Fax 414.468.3312



Flambeau Mining Company
STS Project No. 20961XF
July 13, 1994
Page 2

Flambeau Mining Company supplied the 60 mil geomembrane material and extrusion rod for the repairs. The material was leftover from the Phase 1 liner construction.

Please refer to the attached Liner Repair Form for details regarding the repairs.

Sincerely,

STS CONSULTANTS LTD.

A handwritten signature in black ink, appearing to read 'Michael J. Pretti'.

Michael J. Pretti, P.E.
Project Engineer

A handwritten signature in black ink, appearing to read 'Dean A. Sylla'.

Dean A. Sylla, P.E.
Principal

MJP/lmh

Enclosures:

Liner Repair Form
Trial Weld Summary
June 23, 1994, Field Technician Report
Drawing No. 20961XF-1

PROJECT NAME: FLAMBEAU MINE: TYPE II STOCKPILE, PHASE I

PROJECT NO: 20961XF

QA MONITOR: Mike Major

STS Consultants Ltd.

TRIAL WELD SUMMARY

Test No.	Date	Time	Weather	Welder ID	Machine Number	Temp. Setting/Speed	Amb. Temp.	Weld Type	PEEL (PPD)								SHEAR (PPD)	Test (P/F)	Comments							
									Outside Weld				Inside Weld													
									1	2	3	4	1	2	3	4										
1	6-23-94	13:15	Cloudy 70°	RG	EXT 7539	230°C	70	EXT	117	142	126	160	NA	NA	NA	NA	NA	NA	NA	NA	142 138	154 P				



PROJECT NAME: FLAMBEAU MINE: TYPE II STOCKPILE, PHASE 1

PROJECT NO. 20961XF

QA MONITOR:

MILE ABOUT

Date: 6-23-94 STS Consultants, Ltd.

LINER REPAIR FORM

Repair Number	Date Repaired	Time	Oper./Mach.	Repair Location	Description	Size of Repair	Date Vacuum Tested	Vac. Test Results (P/F)
6-23-H	6-23-94		RB	SOUTH OF 1 FOOT WEST OF AUGUR TRENCH ON PANEL P-225	HOLES & SCRATCHES FROM VEHICLE TRAFFIC	6' X 2'	6-23-94	P

STS Construction Technology Group Field Report



The responsibilities and authority of STS and STS' Field Personnel include neither the responsibilities nor the authority of the "Competent Person" for the Project Site as defined by OSHA Regulations: 29 CFR 1926 Subpart P.

Project No. _____
 Project FLAMBEAU Mining Company - WASTE TYPE II STOCKPILE Day/Date Tuesday, June 23, 1994
 Location LADYSMITH, WI Weather/Temp. Cloudy, 74°
 Contractor GSI Client FMC
 (1 of 3 reports for 6.23)

Project Competent Person per 29 CFR Part 1926 (Subpart P)

NAME: _____

FIRM: _____

FIRM ADDRESS: _____

PHONE: _____

Present on Site YES NO

Equipment Rental _____	Arrive Job <u>3:30</u> <u>5:00</u>	TOTAL CHARGEABLE HOURS 4 HOUR MINIMUM <u>2.0</u>
Tolls \$ _____	Depart Job <u>4:00</u> <u>6:30</u>	
Parking \$ _____	Total Hours on Job <u>2.0</u>	
Mileage _____	Travel Time _____	
Project Preparation Time _____		

Summary of Technical and/or Engineering Services Performed, including Field Test Data. Locations, Elevations and Depth are Estimated.

THE DAMAGE DUE TO TRAFFIC IS ON THE SOUTHWEST SIDE OF TYPE II STOCKPILE AREA ON PANELS 229 & 225.

THE DAMAGE IS EXTENSIVE, WITH MANY RIPS, DEEP SCATHES, AND HOLES. FLAMBEAU MINE EMPLOYEES UNCOVERED THE LINER & EXPOSED THE DAMAGED AREAS.

GSI PLACED 1 LARGE PERMANENT PATCH ~~60~~ 6'x12' IN DIMENSION ON P-229⁵, & WELDED TO THE LINER.

GSI ALSO HEAT TACKED SOME SMALLER SCRAP PIECES OF 60 MIL HDPE OVER OTHER MAJOR HOLES. THIS WAS DONE DUE TO THE LACK OF ENOUGH MATERIAL TO COVER THE ENTIRE DAMAGED AREA. MATERIAL (HDPE) WILL BE ARRIVING SOON FOR PHASE II CONSTRUCTION & REPAIRS WILL BE COMPLETED AT THAT TIME. THE AREA IS IN AN AREA THAT DOES NOT RELIEVE ANY PRECIPITATION RUN OFF FROM THE TYPE II STOCKPILE OR THE CRUSHING OPERATIONS.

GSI VACUUM TESTED THE PERMANENT REPAIR & FOUND NO LEAKS.

Field Test Data is Estimated Pending Final Laboratory Test Results. Site Sketch: Indicate North

Representative Jane E. Murphy
 Position Env. Supervisor
 Company Flambeau Mining Co.

By MJ Moroni
 Title SR. ENGR. TECH
 STS Consultants, Ltd.



MATCH LINE SEE DRAWING No. 18904-5

EDGE OF LINER/LOCATION OF ANCHOR TRENCH

LEGEND

- P319 PANEL NUMBER
- S-286 SEAM NUMBER
- XS-24 CROSS SEAM NUMBER
- TOP OF BERM

NOTE: APPROXIMATE DIKE LOCATIONS TAKEN FROM DESIGN DRAWINGS



TYPE II STOCKPILE AREA



CRUSHER AREA

AREA OF REPAIRS

EDGE OF DIKE

EDGE OF LINER/
LOCATION OF ANCHOR TRENCH

TOE OF SLOPE
(TYP.)



REVISION			
DATE	11-3-92	DATE	11-16-92
BY	J.R.L.	BY	D.A.D.
DATE		DATE	11-18-92
BY		BY	R.K.L.
DATE		DATE	
FILE		FILE	C:\DUM\FLAM\F1.DWG

FLAMBEAU MINING COMPANY
LADYSMITH, WISCONSIN

TYPE II STOCKPILES AND CRUSHER AREA GEOMEMBRANE REPAIR LOCATIONS



STS PROJECT NUMBER	20961XF
STS PROJECT FILE	
SCALE	1" = 50'
SHEET NUMBER	20961XF-1



July 13, 1994

Ms. Jana E. Murphy
Supervisor of Environmental Affairs
Flambeau Mining Company
N4100 Highway 27
Ladysmith, Wisconsin 54848

Re: Surge and Runoff Ponds Repairs, Type II Stockpile (Phase 1), Flambeau Mine, Ladysmith, Wisconsin -- STS Project No. 20961XF

Dear Ms. Murphy:

As you requested, STS Consultants, Ltd., (STS) was at the above referenced site on June 23, 1994, to document repairs performed for the surge and runoff ponds. This correspondence briefly summarizes the repairs made to the geomembrane liner in these areas.

Sloughing of the surge pond subgrade soil supporting the pipe and liner on the north slope, west portion in panel P-48, 19 feet north of the anchor trench was being repaired by Cooper Engineering and Flambeau Mining personnel upon STS' arrival at the site. The geomembrane liner had broken away from the pipe collar weld. Cooper personnel had cut a hole in the liner to facilitate backfilling of the sloughed area.

A dry sand-bentonite soil mixture was used to backfill the washout area. We understand the soil work portion of this repair will be documented by Cooper personnel under separate correspondence.

Additional areas of the geomembrane liner requiring repair included:

- Surge Pond: panel P-36 at the 36-inch diameter outlet pipe. The weld collar beneath the liner had curled and tensioned the liner. Additionally, the liner broke away from the weld collar for a length of approximately 9 inches. See Figure 1.
- Surge Pond: panel P-49, 3 feet south of the anchor trench and 5 feet east of seam 45. A deep scratch was observed in the geomembrane liner. See Figure 1.
- Runoff Pond: panel P-339 in the southwest corner. A puncture and small, heavy crease were observed in the liner. See Figure 2.

STS Consultants Ltd.
Consulting Engineers

1035 Kepler Drive
Green Bay, Wisconsin 54311
414.468.1978/Fax 414.468.3312



Flambeau Mining Company
STS Project No. 20961XF
July 13, 1994
Page 2

Geo-Synthetics Construction, Inc. (GSCI) of Waukesha, Wisconsin extrusion welded 60 mil HDPE permanent patches over the holes in P-48 and the other damaged areas mentioned above. Vacuum testing of the patches was performed by GSCI and indicated acceptable welds.

Prior to performance of welding of the patches, GSCI performed trial welding to evaluate the performance of their extrusion welding machines and welding personnel. Four peel tests and three shear tests were performed on the trial weld samples and all test samples met the minimum test requirements. Criteria for acceptance of an extrusion welded seam tested in peel was defined as: a) failure by film tear bond (FTB), and b) the yield seam strength for the seam being at least 90 pounds per inch (ppi). Criteria for acceptance of an extrusion welded seam tested in shear was defined as: a) failure by FTB, and b) the yield seam strength for the seam being at least 120 ppi. Refer to the attached Trial Weld Information Form for additional information.

Flambeau Mining Company supplied the 60 mil geomembrane material and extrusion rod for the repairs. The material was leftover from the Phase 1 liner construction.

Please refer to the attached Liner Repair Form and copies of the STS technician's field reports for details regarding the repairs. If you have any questions or comment, please contact us.

Sincerely,

STS CONSULTANTS LTD.

A handwritten signature in cursive script, appearing to read 'Michael J. Pretti'.

Michael J. Pretti, P.E.
Project Engineer

A handwritten signature in cursive script, appearing to read 'Dean A. Sylla'.

Dean A. Sylla, P.E.
Principal

MJP/lmh

Enclosure:

Liner Repair Form
Trial Weld Information Sheet
Figures 1 and 2
Drawing No. 20961XF-1



PROJECT NAME: FLAMBEAU MINE: TYPE II STOCKPILE, PHA 01

PROJECT NO. 20961XF

Date: 6/23/94 STS Consultants, Ltd.

QA MONITOR: Mike Moran

LINER REPAIR FORM

Repair Number	Date Repaired	Time	Oper/Mach.	Repair Location	Description	Size of Repair	Date Vacuum Tested	Vac. Test Results (P/F)**
6-23-A	6-23-94		RB	Surge Pond. Panel P-48 20' South of N. Anchor Trench, 3'E. of S-46	Hole cut by Cooper Eng. to Repair Soil Washout	3'x3'	6-23-94	P
6-23-B	"		"	Surge Pond. Panel P-48, 14' of N. Anchor Trench, 4'E of S-46	Liner broke away from Weld Collar at Weld ⇒ Rewelded	Reweld	" *	P
6-23-C	"		"	Surge Pond. Panel P-49, 3'S. of N. Anchor Trench, 5'E. of S-45.	Deep Scratch	1'x2'	"	P
6-23-D	"		"	Surge Pond. Panel P-36, 14'S. of N. Anchor Trench, 6'E. of S-36	Pipe Weld Collar Curled and cracked Liner	1'x3'	"	P
6-23-E	"		"	Surge Pond. Panel P-36, 14'S. of N. Anchor Trench, 9'E. of S-36	Liner Broke off of Pipe Weld Collar @ Weld	Reweld	" *	P
6-23-F	"		"	Runoff Pond. Panel P-339, 30'E. of W. Anchor Trench, 3' South of S-295	Hole	2'x4'	"	P
6-23-G	"		"	Runoff Pond. Panel P-339, 5'E. of W. Anchor Trench 7' S. of S-295	Grease	1'x1'	"	P

* Spark Tested. ** (P/F) = Pass/Fail

STS Construction Technology Group Field Report

PAGE 1 OF 3



The responsibilities and authority of STS and STS' Field Personnel include neither the responsibilities nor the authority of the "Competent Person" for the Project Site as defined by OSHA Regulations: 29 CFR 1926 Subpart P.

Project FLAMBEAU MINING COMPANY - SURGE POND.
Location LADYSMITH, WI
Contractor GSI

Project No. _____
Day/Date TUESDAY, JUNE 23, 1994
Weather/Temp. CLOUDY, 74°
Client FMC
(1 of 3 reports for 6.23)

Project Competent Person per 29 CFR Part 1926 (Subpart P)

NAME: _____

RM: _____

FIRM ADDRESS: _____

PHONE: _____

Present on Site YES NO

Equipment Rental _____

Arrive Job 11:00 12:50

Tolls \$ _____

Depart Job 12:00 3:50

Parking \$ _____

Total Hours on Job 9.0

Mileage 210

Travel Time 4.5

Project Preparation Time .5

TOTAL CHARGEABLE HOURS
4 HOUR MINIMUM

9.0

Summary of Technical and/or Engineering Services Performed, including Field Test Data. Locations, Elevations and Depth are Estimated.

I MET WITH JANA MURPHY & VON STANKS OF FMC UPON ARRIVAL. WE WENT TO THE SURGE POND FACILITY TO OBSERVE THE EXTENT OF THE LINER DAMAGE. COOPER ENGINEERING & FMC EMPLOYEES WERE REPAIRING THE UNSUPPORTED AREAS AROUND THE PIPE TO SUPPORT THE LINER FOR REPAIR. THE LOCATION IS THE NORTH SLOPE, WEST PORTION, IN PANEL 48, 19' SOUTH OF THE ANCHOR TRENCH. THE LINER HAS BROKEN AWAY FROM THE WELD ON THE PIPE COLLAR. COOPER ENGR. CUT A HOLE BELOW THE PIPE OUTLET TO FACILITATE BACKFILLING THE UNSUPPORTED AREA. COOPER ENGR. USED A ^{DRY} SAND-BENTONITE MIXTURE FOR BACKFILLING THE UNSUPPORTED AREA. SEE COOPER REPORT FOR SOILS DETAILS. ALSO, AT THE 36" OUTLET, A HARD SPOT IN THE LINER WAS OBSERVED BY COOPER & CUT OPEN BY COOPER TO FIND THE WELD COLLAR UNDER THE LINER HAD CURLED & TENSIONED THE LINER. ALSO, THE LINER HAD BROKEN AWAY (LENGTH 9") FROM THE WELD COLLAR. (CONT. PAGE 2)

Field Test Data is Estimated
 Pending Final Laboratory Test Results.

Site Sketch: Indicate North

Representative Jana E. Murphy
Position Env. Supervisor
Company Flambeau Mining Co.

By MJ Moroni
Title SR. ENGR. TECH.
STS Consultants, Ltd.

STS Construction Technology Group Field Report

Page 2 of 3



The responsibilities and authority of STS and STS' Field Personnel include neither the responsibilities nor the authority of the "Competent Person" for the Project Site as defined by OSHA Regulations: 29 CFR 1926 Subpart P.

Project No. _____
 Day/Date Thursday, June 23, 1994
 Weather/Temp. _____
 Client _____

Project Flambeau Mining Co.
 Location _____
 Contractor _____

Project Competent Person per 29 CFR Part 1926 (Subpart P)
 NAME: _____
 FIRM: _____
 FIRM ADDRESS: _____
 PHONE: _____
 Present on Site YES NO

Equipment Rental _____ Arrive Job _____
 Tolls \$ _____ Depart Job _____
 Parking \$ _____ Total Hours on Job _____
 Mileage _____ Travel Time _____
 Project Preparation Time _____

TOTAL CHARGEABLE HOURS
 4 HOUR MINIMUM
See Page 1

Summary of Technical and/or Engineering Services Performed, including Field Test Data. Locations, Elevations and Depth are Estimated.

A DEEP SCREATCH WAS ALSO OBSERVED IN PANEL 49, 3' SOUTH OF THE ANCHOR TRENCH & 5' EAST OF SEAM 45. OTHER MINOR SURFACE ~~SCREATCHES~~ SCRATCHES ARE NOTED IN THIS AREA, WHICH ADJACENT TO THE ACCESS GATE FOR THE POND. THE SCREATCH WAS REPAIRED BY GSI BY WELDING A PATCH OVER THE AREA.

GSI ALSO REPAIR THE EARLIER MENTIONED DAMAGE AREAS BY WELDING PATCHES OVER THE CUTS AND GRINDING & REWELDING THE LINERS TO THE PIPE COLLARS. SEE TRIAL WELD FORM & REPAIR DATA FORM FOR SPECIFIC INFORMATION ON THE REPAIRS. GSI & VACUUM TESTED THE PATCHES & SPARK TESTED THE PIPE CONNECTIONS & FOUND NO LEAKS.

I ALSO OBSERVED THE PATCH IN THE 36" PIPE & IT APPEARED TO BE IN GOOD CONDITION.

THE SOLE CONDITION BENEATH THE PIPES DOES NOT SHOW ANY SLOUGHING OF SOILS, EXCEPT ^{FOR} THE PIPE OUTFLOW AREA & REPAIRED TODAY.

Field Test Data is Estimated
 Pending Final Laboratory Test Results.
 Site Sketch: Indicate North (cont. Page 3).

Representative _____
 Position _____
 Company _____

By MJ Maroni
 Title Sr. Eng. Tech.
 STS Consultants, Ltd.

STS Construction Technology Group Field Report

PAGE 3 OF 3



The responsibilities and authority of STS and STS' Field Personnel include neither the responsibilities nor the authority of the "Competent Person" for the Project Site as defined by OSHA Regulations: 29 CFR 1926 Subpart P.

Project No. _____
 Project FLAMBEAU MINING CO - SURGE POND. Day/Date THURSDAY, JUNE 23, 1994.
 Location _____ Weather/Temp. _____
 Contractor _____ Client _____

Project Competent Person per 29 CFR Part 1926 (Subpart P)

NAME: _____
 FIRM: _____
 FIRM ADDRESS: _____
 PHONE: _____
 Present on Site YES NO

Equipment Rental _____ Arrive Job _____
 Tolls \$ _____ Depart Job _____
 Parking \$ _____ Total Hours on Job _____
 Mileage _____ Travel Time _____
 Project Preparation Time _____

TOTAL CHARGEABLE HOURS
 4 HOUR MINIMUM

SEE PAGE 1

Summary of Technical and/or Engineering Services Performed, including Field Test Data. Locations, Elevations and Depth are Estimated.

THE SCUFF SHEET BELOW THE 36" PIPE IS IN GOOD CONDITION. HOWEVER, I DID NOTICE A SMALL TEAR IN THE SCUFF SHEET NEAR THE HIGH WATER MARK. THE LINER ITSELF IS NOT DAMAGED. THE TEAR QUITE POSSIBLY COULD HAVE BEEN CAUSED BY ICE ACTION OVER THE WINTER. IT WOULD BE A GOOD IDEA TO PLACE SCUFF STRIPS UNDER THE CORRUGATED PIPES THAT ARE LAYING ON THE LINER. SOME MINOR SCRATCH WAS OBSERVED IN THESE AREAS, AND A SCUFF STRIP WOULD PREVENT ANY SCRATCHING DAMAGE TO THE LINER.

THE 60 MIL HDPE MATERIAL & EXTRUSION ROD WAS SUPPLIED BY FLAMBEAU MINING FOR REPAIRS MADE. MATERIAL CERTS. AVAILABLE FROM FMC. MATERIAL WAS CLEAN & DRY. ITS IS MATERIAL LEFT OVER FROM PREVIOUS LINER CONSTRUCTION.

Field Test Data is Estimated
 Pending Final Laboratory Test Results.

Site Sketch: Indicate North

Field Representative _____
 Position _____
 Company _____

By [Signature]
 Title SR. ENGR. TECH.
 STS Consultants, Ltd.

STS Construction Technology Group Field Report



NOTE: The responsibilities and authority of STS and STS' Field Personnel include neither the responsibilities nor the authority of the "Competent Person" for the Project Site as defined by OSHA Regulations: 29 CFR 1926 Subpart P.

Project Flambeau Mining Company - Run off Pond. Project No. _____
 Location Lady Smith, WI Day/Date Thursday, June 23, 1994
 Contractor GSI Weather/Temp. Cloudy, 74°
 Client FMC.

Project Competent Person per 29 CFR Part 1926 (Subpart P)

NAME: _____

FIRM: _____

FIRM ADDRESS: _____

PHONE: _____

Present on Site YES NO

Equipment Rental _____ Arrive Job 12:00 4:00

Tolls \$ _____ Depart Job 12:30 5:00

Parking \$ _____ Total Hours on Job 1.5

Mileage _____ Travel Time _____

Project Preparation Time _____

TOTAL CHARGEABLE HOURS
4 HOUR MINIMUM

1.5

Summary of Technical and/or Engineering Services Performed, including Field Test Data. Locations, Elevations and Depth are Estimated.

I MADE AN OBSERVATION TOUR OF THE RUN OFF POND TO OBSERVE THE PERFORMANCE OF THE LINER.

I FOUND A PUNCTURE IN THE LINER & A ^{SMALL} ~~ALREADY~~ CREASE IN THE LINER IN THE SOUTH WEST CORNER. (P. 339)
 GSI PATCHED BOTH OF THESE LOCATIONS WITH 60 ML HDPE & EXTRUSION ROD SUPPLIED BY FLAMBEAU MINING. SEE TRIAL WELD LOG & REPAIR SUMMARY FOR SPECIFIC WELDING DATA. GSI VACUUM-TESTED THE REPAIRS & FOUND NO LEAKS.

I NOTICED THAT THE SOILS UNDER THE 32" PIPE ON THE WEST SIDE OF THE POND HAVE SLOUGHED DOWN & CREATED A VOID IN THE AREA IMMEDIATELY BELOW THE PIPE. HOWEVER, AT LOW WATER, THERE WAS NO VISIBLE STRESS ON THE LINER AT THIS TIME.


ALSO, SLOTTED STRIPS ARE RECOMMENDED UNDER EACH OF THE CORRUGATED PIPES TO PREVENT SCRATCHING THE LINER. SOME MINOR SCATHING IS EVIDENT AT EACH PIPE LOCATION.

Field Test Data is Estimated Pending Final Laboratory Test Results.


Site Sketch: Indicate North

Field Representative Jana E. Murphy
 Position Env. Supervisor
 Company Flambeau Mining Co.

By [Signature]
 Title SR. ENGR. TECH.
 STS Consultants, Ltd.



LEGEND

6-23-A  LOCATION OF GEOMEMBRANE REPAIR




STS Consultants Ltd.
Consulting Engineers

PROJECT/CLIENT

FLAMBEAU MINING COMPANY
LADYSMITH, WISCONSIN

GEOMEMBRANE REPAIR LOCATIONS

DRAWN BY	JDS
CHECKED BY	
APPROVED BY	
SCALE	FIGURE NO. 1
STS DRAWING NO. C:\20961ZF\FIG1	



RUNOFF POND

WEST ANCHOR TRENCH

S-295

6-23-F

P-339

6-23-G

SOUTHWEST CORNER SEAM

LEGEND

6-23-F  LOCATION OF GEOMEMBRANE REPAIR



STS Consultants Ltd.
Consulting Engineers

PROJECT/CLIENT

FLAMBEAU MINING COMPANY
LADYSMITH, WISCONSIN

GEOMEMBRANE REPAIR LOCATIONS

DRAWN BY JDS

CHECKED BY

APPROVED BY



SCALE

FIGURE NO.



2

STS DRAWING NO.

C:\20961ZF\FIG2




TYPICAL PIPE PENETRATION DETAIL
NOT TO SCALE




LYSIMETER

- LEGEND**
- P-319 PANEL NUMBER
 - S-286 SEAM NUMBER
 - TOP OF BERM
 - GEOMEMBRANE REPAIR LOCATION
 - 6-23-A


NOTE: APPROXIMATE DIKE LOCATIONS TAKEN FROM DESIGN DRAWINGS



SURGE POND



RUN-OFF POND AND FUEL STORAGE AREA

REVISION				
DATE	10-29-92	BY		
DATE	11-16-92	BY		
DATE	11-18-92	BY		
DRAWN BY	D.J.M.	CHECKED BY	D.A.D.	APPROVED BY
			R.K.L.	C:\20961XF\POND.DWG
FLAMBEAU MINING COMPANY LADYSMITH, WISCONSIN				
SURGE POND, RUNOFF POND, LYSIMETER, AND FUEL STORAGE AREA REPAIR LOCATION DIAGRAM				
 STS Consultants Ltd Consulting Engineers				
SITS PROJECT NUMBER				
20961XF				
SITS PROJECT FILE				
SCALE				
1" = 20'				
SHEET NUMBER				
20961XF-1				



Cooper Engineering Company, Inc.

310 WEST SOUTH STREET • RICE LAKE, WI 54868-2420

TELEPHONE (715) 234-7008 FAX (715) 234-1025

July 27, 1994

Ms. Jana E. Murphy
Supervisor of Environmental Affairs
Flambeau Mining Company
N4100 Hwy 27
Ladysmith, WI 54848

RE: Liner Repairs

Dear Jana:

SURGE POND

Per your request, Craig Walkey, Cooper Engineering Company, arrived at the mine at 7:00 a.m., June 23, 1994 to investigate and coordinate repairs to the liner failure at the discharge pipe in the surge pond. Our goal was to complete adequate repairs with minimal shut-down time.

We met with Von Shanks at the surge pond and with other Flambeau employees associated with the pond operation to listen to their opinions and history of the possible conditions that may have caused the failure. We investigated the liner failure in detail (see attached photos).

We believe that the liner failure at the discharge pipe was caused by the following:

1. The 300± GPM (200,000± GPD) flow from the discharge pipe produces dynamic forces below the discharge that may have caused soil settlement and/or erosion immediately below the liner.
2. The liner material sagged into the downstream depression and caused a stress point at the fixed pipe location.
3. The stress point failed causing separation of the liner material at the pipe.

The repair method we chose was to cut open the liner material below the discharge pipe and pack the subsoil void with a dry bentonite/sand mixture.

Approximately 1/4 c.y. of material was hand placed into the void by Flambeau employees.

Ms. Murphy
July 27, 1994
Page 2

The bentonite/sand mix was chosen because it was readily available, it was easy to place, it will absorb any soil moisture and continue to expand into the void space, it is stable and will remain in place, and it will remain elastic to absorb the dynamic discharge forces.

We have reviewed the July 13, 1994 STS report on the liner patch and weld repair and agree with their description.

STOCKPILE II PHASE I

We worked with the Flambeau crew to expose the boundaries of the vehicle damaged liner material. The remaining quantity of surplus liner material owned by the mine was not large enough to repair the area damaged. We decided not to locate and ship patch material that was not certified for this project. The damaged area is not at a critical location for contaminate containment. Also, Stockpile II Phase II liner installation was expected to begin in July 1994. Sufficient certified liner material would be available to complete a permanent patch.

The damaged liner was tacked patched with the remaining liner material where the greatest damage was apparent. The damaged area remains exposed and the area is barricaded from entry. The upgradient soil was bermed to direct any runoff from the damaged area. See also STS July 13, 1994 report.

OTHER

Cooper, STS, and Flambeau employees inspected the surge and runoff ponds for any other damage that could be repaired by the GSCI crew. These repairs are discussed in the STS repair reports.

We agree with the STS recommendation to add scuff patches under corrugated pipe locations.

Some of the damaged liner (punctures and cuts) are the result of moving equipment on the exposed liner surfaces. This should be avoided or planned with protection in mind.

In our opinion, the Flambeau Mining Company employees are doing a very good job of routine liner inspection and protection.

Sincerely,


Craig Walkey

br:CS94048


cc Dan Willenbring

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN


SURGE POND LINER REPAIR
JUNE 23, 1994




#1 LINER SEPARATION AT DISCHARGE PIPE



#2 SUBSOIL EXPOSED BY COOPER ENGINEERING CO.



#3 PROFILE AT AREA TO BE REPAIRED



#4 VOID PACKED WITH DRY BENTONITE/SAND




#5 PATCHING AND TESTING



#6 COMPLETED REPAIR




#7 PROFILE OF COMPLETED REPAIR



#8 RETURN TO OPERATION

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN

SURGE POND REPAIR
JUNE 23, 1994



#1 TYPICAL PUNCTURE REPAIR



#2 TYPICAL PUNCTURE PATCH



#3 TYPICAL REPAIR TEST

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN

STOCKPILE II PHASE I
JUNE 23, 1994



#1 BERM LINER DAMAGE



#2 EXPOSING LINER DAMAGE



#3 EXPOSING LINER DAMAGE



#4 EXPOSING LINER DAMAGE



#5 TEMPORARY PATCH OVER AREA MOST DAMAGED



Cooper Engineering Company, Inc.

310 WEST SOUTH STREET • RICE LAKE, WI 54868-2420
TELEPHONE (715) 234-7008 FAX (715) 234-1025

October 26, 1994

Ms. Jana E. Murphy
Supervisor of Environmental Affairs
Flambeau Mining Company
N4100 Hwy 27
Ladysmith, WI 54848

RE: Liner Repairs

Dear Jana:

During the period of August 16-29, 1994, repairs were made to the existing HDPE liner systems as Stockpile II, Phase 2 was under construction. The repairs were made by GSCI, Inc. under the direction of Craig Walkey, P.E., Cooper Engineering Company, Inc. The repairs and repair tests were monitored by Jeff Gahen, STS Consultants, Ltd. A summary of the repairs are provided below.

STOCKPILE II, PHASE 1

During the construction of Stockpile II, Phase 2 the existing HDPE liner was exposed to construct the liner tie-in seam between Phase 1 and 2. The liner was exposed using a backhoe bucket to within six inches of the liner material and completed using shovels and broom.

Three damaged areas were exposed that were confirmed to have occurred prior to the Phase 2 project. The locations are shown in the following photographs. The coordinates of the repairs are given in the STS liner repair forms and plan sheet attached.

The repairs to the damaged areas were patched using the approved Phase 2 HDPE liner material. The areas were cleaned with water before seaming by extrusion welding. The patches were tested using the vacuum chamber method.

Ms. Murphy
October 26, 1994
Page 2

PHASE 1 SOUTH BERM

The Phase 1 south berm repair described in the July 29, 1994 Cooper Engineering report was a temporary repair until a sufficient quantity of certified HDPE liner could complete the repair. The repair was completed using the approved Phase 2 HDPE liner material. The area was cleaned with water before seaming by extrusion welding. The patch was tested using the vacuum chamber method.

SCUFF PADS

The STS report of July 13, 1994 recommends that scuff pads be constructed under corrugated pipe entrances to the surge and runoff ponds. These modifications were completed by constructing a patch using the approved Phase 2 HDPE liner material. The patches were placed under the corrugated pipes and welded to the existing liner material by extrusion welding. The patches were tested using the vacuum chamber method. The scuff pads create a double HDPE lined system under the pipes entrances. The location and description of the scuff pads are attached.

SURGE POND DISCHARGE PIPE

The repair to the surge pond discharge pipe described in the July 29, 1994, Cooper Engineering report was successful. However, subsoil erosion continued below the repair. Under the direction of Craig Walkey, the liner below the repair was cut open and the subsoil was replaced using the same 50/50 mixture of course sand and bentonite pellets that was successful for the June 1994 repair. The soil mixture was shaped to form a flume for the discharge water.

The liner was capped using the approved Phase 2 HDPE liner material and extrusion weld seam. The seam was tested using the vacuum chamber method. See attached photographs.

Sincerely,



Craig Walkey

br:CE94081

Date:

LINER REPAIR FORM



Repair Number	Date Repaired	Time	Oper/Mach.	Repair Location	Description	Size of Repair	Date Vacuum Tested	Vac. Test Results (P/F)
35A	8/16/94	AM	SC/6751	Stn. 406+96 N 3' West of West Tie In Seam	2 Cleases / 2 Knots	3" ca	8/23/94	P
36A	8/16	AM	SC/6751	Station N406+90 3' West of West Tie In Seam	2 Knots / 2 Beads	3" ca	8/23	P
37A	8/16	PM	RS/9246	Station N406+85 3' West of West Tie In Seam	Hole / Patch	1.0x1.0	8/23	P
38A	8/16	PM	SC/6751	Station N 406+80-406+84 0-3.5' West of West Tie In	Hole / Patch	1.0x1.0	8/23	P
39A	8/16	PM	RS/4246	Station N 406+77-406+79 3' West of West Tie In Seam	Hole / Patch	1.0x2.0	8/23	P
40A	8/16	PM	RS/4246	Station N 406+75 4' West of West Tie In Seam	Hole / Patch	1.0x1.0	8/23	P
41A	8/16	PM	RS/9246	Station N 406+71-406+75 0-5-2.5' West of West Tie In	Hole / Patch	2.0x2.0	8/23	P
42A	8/16	PM	SC/6751	Station N 406+68-406+76 0-2.5' West of West Tie In Seam	Crease / Knots / Patch	1.2x1.0	8/23	P
43A	8/16	PM	SC/6751	Station N 406+68 4' West of West Tie In Seam	Hole / Patch	1.2x1.1	8/23	P
44A	8/16	PM	SC/6751	Station N 406+66 Along West Tie In Seam	Hole / Patch	1.0x1.0	8/23	P
45A	8/16	PM	SC/6751	Station N 406+55-406+58 0-5-2.5' West of West Tie In	Hole / Patch	1.0x2.5	8/23	P
46A	8/16	PM	S.C./6751	Station N 406+51 2.5' West of West Tie In	Hole	0.8x0.8	8/23	P
47A	8/16	PM	S.C./6751	Station N 406+49 2.5' West of West Tie In Seam	Hole	0.8x0.8	8/23	P
48A	8/16	PM	S.C./6751	Station N 406+49 5' West of West T.I.S.	Hole	0.8x0.8	8/23	P
49A	8/16	PM	S.C./6751	Station N 406+45 3' West of West T.I.S.	Hole	0.8x0.8	8/23	P
50A	8/16	PM	S.C./6751	Station N 406+45 6' West of West T.I.S.	Hole	0.8x0.8	8/23	P
51A	8/16	PM	RS/9246	Station N 406+41-406+43 0-2' West of West T.I.S.	Hole	3.0x2.0	8/23	P

LINER REPAIR FORM

Repair Number	Date Repaired	Time	Oper./Mach.	Repair Location	Description	Size of Repair	Date Vacuum Tested	Vac. Test Results (P/F)
52A	8/16/94	PM	RS/9246	Station N 406+35 2' West of West Tie In Seam	Hole / Patch	0.8x0.8	8/23/94	P
53A	8/16	PM	RS/9246	Station N 406+32-406+34 3'-6" West of West T.I.S.	Hole / Patch	2.0x3.0	8/23	P
54A	8/16	PM	RS/9246	Station N 406+29 3' West of West T.I.S.	Hole / Patch	0.8x0.8	8/23	P
55A	8/16	PM	RS/9246	Station N 406+28 3' West of West T.I.S.	Hole / Patch	0.8x0.8	8/23	P
56A	8/16	PM	RS/9246	Station N 406+23 1' West of West T.I.S.	Hole / Patch	1.8x0.8	8/23	P
57A	8/16	PM	S.C./6751	Station N 406+11-406+15 0'-3" West of West T.I.S.	Crease with Holes/Patch	1.0x5.0	8/23	P
58A	8/16	PM	S.C./6751	Station N 406+9 2' West of West T.I.S.	Hole / Patch	0.8x0.8	8/23	P
59A	8/16	PM	S.C./6751	Station N 406+6 2' West of West T.I.S.	Hole / Patch	0.8x0.8	8/23	P
60A	8/16	PM	S.C./6751	Station N 405+99 1.5' West of West T.I.S.	Hole / Patch	0.8x0.8	8/23	P
61A	8/16	PM	S.C./6751	Station N 405+99 3' West of West T.I.S.	Hole / Patch	0.8x0.8	8/23	P
62A	8/16	PM	S.C./6751	Station N 405+96-405+98 0-2.5' West of West T.I.S.	Hole / Patch	1.5x3.0	8/23	P
63A	8/16	PM	S.C./6751	Station N 405+94 3.5' West of West T.I.S.	Hole / Patch	0.8x0.8	8/23	P
64A	8/16	PM	S.C./6751	Station N 405+92 3.5' West of West T.I.S.	Hole / Patch	0.8x0.8	8/23	P
65A	8/16	PM	S.C./6751	Station N 405+90 1.5' West of West T.I.S.	Hole / Patch	0.8x0.8	8/23	P
66A	8/16	PM	S.C./6751	Station N 405+87-405+89 2-4' West of West Tie-In Seam	Hole / Patch	1.5x2.0	8/23	P
67A	8/16	PM	S.C./6751	Station N 405+87 1.0' West of West T.I.S.	Hole / Patch	0.8x0.8	8/23	P
68A	8/16	PM	S.C./6751	Station N 405+74-405+81 1.0-10.0 West of West T.I.S.	Holes / Patch	7.0x9.0	8/23	P

LINER REPAIR FORM								
Repair Number	Date Repaired	Time	Oper/Mach	Repair Location	Description	Size of Repair	Date Vacuum Tested	Vac. Test Results (P/F)
69A	8/16/94	PM	S.C./6751	Station 405+74 N 1.5' West of West Tie In Seam	Hole	0.8x0.8	8/23/94	P
70A	8/16	PM	S.C./6751	Station N 405+69-405+75 0-2' West of W.T.I.S.	Crease	1.0x5.0	8/23	P
71A	8/16	PM	S.C./6751	Station N 405+71 1.5 and 2.5 West of T.I.S.	Scrape / 2 Beads	4" each	8/23	P
72A	8/16	PM	S.C./6751	Station N 405+69 3.5' West of W.T.I.S.	Scrape / 2 Beads	4" each	8/23	P
73A	8/16	PM	R.S./9246	Station N 405+55-405+63 1.5-3.0' West of W.T.I.S.	Scrape w/ Holes	1.8x8.0	8/23	P
74A	8/16	PM	R.S./9246	Station N 405+44 1.5' West of W.T.I.S.	Hole	1.0x1.0	8/23	P
75A	8/16	PM	S.C./6751	Station N 405+71 0-1.0' West of W.T.I.S.	Hole	1.0x1.5	8/23	P
76A	8/17	PM	RS/9246	Station N 404+96 0.8' West of W.T.I.S.	Hole	1.0x1.0	8/23	P
77A	8/17	PM	RS/9246	Station N 404+79 2.5' West of W.T.I.S.	Scrape / Bead	4"	8/23	P
78A	8/17	PM	RS/9246	Station N 404+75 2.5' West of W.T.I.S.	Hole	0.8x0.8	8/23	P
79A	8/17	PM	RS/9246	Station N 404+74 1.0' West of W.T.I.S.	Hole	0.8x0.8	8/23	P
80A	8/17	PM	RS/9246	Station N 404+55 2.0' West of W.T.I.S.	Scrape / Bead	Bead 1.5'	8/23	P
81A	8/17	2:30 PM	RS/9246	Station N 404+50-404+57 4' West of W.T.I.S.	Hole	0.8x1.8	8/23	P
82A	8/17	11:30 AM	RS/9246	Station N 404+44-404+50 0-5' West of W.T.I.S.	Crease	1.5x7.0	8/23	P
83A	8/17	11:40 AM	RS/9246	Station N 404+43 2' West of W.T.I.S.	Hole	0.8x0.8	8/23	P
84A	8/17	11:20	RS/9246	Station N 404+35-404+44 3'-11' West of W.T.I.S.	Hole	6.0x9.0	8/23	P
85A	8/17	AM	RS/9246	Station N 404+37 4' West of W.T.I.S.	Scrape / Bead	4"	8/23	P

33



REPAIR LOCATIONS TO PHASE I HDPE LINER

LEGEND

8 — DENOTES CLEANOUT

NOTE:
1- PHASE I CONSTRUCTION NOT IN THIS CONTRACT, FOR LIMITS OF PHASE II CONSTRUCTION REFER TO PROJECT SCOPE OF WORK.

PROJECT RECORD DRAWING : COMPILED FROM CONSTRUCTION DATA FURNISHED TO THE ENGINEER BY THE CONTRACTOR, OWNER AND/OR ENGINEERS FIELD REPRESENTATIVE. INFORMATION SHOWN ON THESE DRAWINGS SHOULD BE FIELD VERIFIED BEFORE USING SAME.
REVISED BY M.R.E. 10/10/94 ADDED TYPE II PHASE II STOCKPILE PROJECT RECORD DRAWING DATA.
PREPARED BY COOPER ENGINEERING CO., INC. RICE LAKE, WISC.
NOTE: DRAWING SHALL NOT BE SCALED.

REF.	ENG. NO.	DESCRIPTION	NO.	DATE	REVISIONS	BY	CHKD	ENGR	NO.	DATE	REVISIONS
	210-C-010	DRAINAGE DETAILS	A	8-1-91	FOR QUOTE-EARTHWORK	GLT			2	1-7-93	ADDED PROJECT RECORD DWG. DATA TYPE II PHASE I
	210-C-004	SITE GRADING PLAN	A	8-21-91	FOR PERMIT-LINER	GLT			3	10-10-94	ADDED PROJECT RECORD DWG. DATA TYPE II PHASE II
	210-C-000	SECTIONS & DETAILS	B	8-28-91	FOR QUOTE - EARTHWORK	GLT					
	210-C-014	SECTIONS & DETAILS	B	7-11-91	FOR CONSTRUCTION	GLT					
	210-C-020	UNDERGROUND PIPING PLAN	I	8-2-91	REMOVE 8"-CH407.	GLT	JP				

COOPER ENGINEERING COMPANY
210 WEST WALSH STREET, RICE LAKE, WISCONSIN
TELEPHONE 715-334-7998

FLAMBEAU PROJECT
LADYSMITH, WISCONSIN

FLAMBEAU MINING COMPANY
LADYSMITH, WISCONSIN 54848



TYPE II STOCKPILE
PHASE II
LEACHATE COLLECTION SYSTEM PLAN


MICROFILM	JOB
DRAWING NO.	REV.
DIVISION DRAWING NO.	
SCALE	



Repair Number	Date Repaired	Time	Oper./Mach.	Repair Location	Description	Size of Repair	Date Vacuum Tested	Vac. Test Results (P/F)
R-1	8/23/94	8:45-9:45	RS/9246	South end Phase I	Holes & Gouges	13.5x15	8-31-94	P
R-2	8/23/94	9:50-10:10	RS/9246	South end Phase I	Holes & Gouges	4x12.5	8-31-94	P
RP-1	8/23	11:10-11:25	RS/9246	Runoff Pond	Scuff Pad	3'x6'	8-31-94	P
RP-12	8/23	11:35-11:50	RS/9246	Runoff Pond	Scuff Pad	3'x6'	8-31-94	P
RP-11	8/23	1:55-2:05	RS/9246	Runoff Pond	Scuff Pad	3'x6'	8-31-94	P
RP-10	8/23	2:15-2:25	RS/9246	Runoff Pond	Scuff Pad	3'x6'	8-31-94	P
RP-2	8/23	2:40-2:50	RS/9246	Runoff Pond	Scuff Pad	3'x6'	8-31-94	P
RP-3	8/23	3:30-3:40	RS/9246	Runoff Pond	Scuff Pad	3'x6'	8-31-94	P
RP-4	8/23	4:00-4:10	RS/9246	Runoff Pond	Scuff Pad	3'x6'	8-31-94	P
RP-5	8/23	4:25-4:35	RS/9246	Runoff Pond	Scuff Pad	3'x6'	8-31-94	P
RP-7	8/23	4:50-5:00	RS/9246	Runoff Pond	Scuff Pad	3'x6'	8-31-94	P
RP-8	8/26/94	11:40-11:50	RS/9246	Runoff Pond	Scuff Pad	3'x6'	8-31-94	P
RP-9	8/26	12:10-12:20	RS/9246	Runoff Pond	Scuff Pad	3'x6'	8-31-94	P
RP-6	8/26	11:10-11:20	RS/9246	Runoff Pond	Scuff Pad	3'x6'	8-31-94	P


LINER REPAIR FORM

Repair Number	Date Repaired	Time	Oper/Mach.	Repair Location	Description	Size of Repair	Date Vacuum Tested	Vac. Test Results (P/F)
SP-1	8-26-94	9:50-10:00	RS/9246	middle of North berm Surge Pond	Scuff Pad	6.0x3.0	8-31	P
SP-2	8-26-94	10:20-10:30	RS/9246	middle of west berm Surge Pond	Scuff Pad	3.0x6.0	8-31	P
SP-3	8/29	11:30-11:45	RS/9246	Northwest corner pipe spillway	Patch	2.5x4	8/29	P
SP-4	8/29	11:45-12:00	RS/9246	N.W. corner pipe spillway	Patch	1.5x5	8/29	P
SP-5	8/29	12:00-12:15	RS/9246	N.W. corner pipe spillway	Patch	2x3	8/29	P




DATE	9-13-94
DRAWN BY	SOB
CHECKED BY	
APPROVED BY	
CADFILE	
Flambeau Mine Runoff Pond Scuff Pad Repairs	
 STS Consultants Ltd. Consulting Engineers	
STS PROJECT NO.	20961XF
STS PROJECT FILE	
SCALE	
SHEET NO.	




DRAWN BY SOB		DATE 9-13-94
CHECKED BY		DATE
APPROVED BY		DATE
CADFILE		
Flambeau Mine Surge Pond Scuff Pad Repaires		
 STS Consultants Ltd. Consulting Engineers		
STS PROJECT NO. 20961XF		
STS PROJECT FILE		
SCALE		
SHEET NO.		

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN

STOCKPILE II PHASE I
AUGUST, 1994




STOCKPILE II PHASE I HDPE LINER
LOCATION 1 OF 3 DAMAGE



STOCKPILE II PHASE I HDPE LINER
LOCATION 2 OF 3 DAMAGE

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN

STOCKPILE II PHASE I
AUGUST, 1994



STOCKPILE II PHASE I HDPE LINER
LOCATION 3 OF 3 DAMAGE



STOCKPILE II PHASE I HDPE LINER
LOCATION 2 OF 3 REPAIR (TYPICAL)

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN

STOCKPILE II PHASE I
AUGUST, 1994



SURGE POND DISCHARGE PIPE
HDPE LINER MODIFICATION



SURGE POND DISCHARGE PIPE
HDPE LINER MODIFICATION SEAM TESTING



Cooper Engineering Company, Inc.

310 WEST SOUTH STREET • RICE LAKE, WI 54868-2420
TELEPHONE (715) 234-7008 FAX (715) 234-1025

December 13, 1994

Ms. Jana E. Murphy
Supervisor of Environmental Affairs
Flambeau Mining Company
N4100 Hwy 27
Ladysmith, WI 54848

RE: Runoff Pond Liner Repairs

Dear Ms. Murphy:

Per your request, Craig Walkey, Cooper Engineering Company arrived at the mine at 8:30 a.m., November 21, 1994 to inspect HDPE liner damage and the repairs made by GSI, Inc. The repairs began at approximately 10:00 a.m., November 21 and were completed by 12 noon on November 22. The repairs are documented in the attached sketch and photographs.

DESCRIPTION

Flambeau Mining Company employees discovered and paint located five damaged areas on the runoff pond HDPE liner system. Upon further investigation of the liner, a total of ten damaged areas were identified.

It appears the damage was manmade. There is no evidence to suspect that the damage was the result of the runoff pond operation or weather conditions. At the time of the last inspection on 8-25-94, the damaged areas were not evident.

Close inspection of the damaged areas indicate punctures except for #5. Four of the punctures tore through the liner material #3, #6, #7, and #10. The remaining were stressed dents. Damage #5 was caused when pressure was applied to the liner immediately over a sharp rock. The rock was removed before the repair was completed.

There is no pattern to the damage that would describe a single cause or event.

There is insufficient evidence to draw a conclusion as to the cause of the HDPE liner damage.

Ms. Murphy
December 13, 1994
Page 2

REPAIR

Repairs were made by extrusion welded patches over the holes and extrusion weld fillets in the dents. The patches were made from surplus certified Phase 2 HDPE liner material stored in the building at H&H gate.

The patches were tested using the vacuum box method. Test weld strips were tested for peel strength using a field tensiometer apparatus before the repairs were made.

Craig Walkey inspected the emptied pond for any other damage that needed repair. The pond bottom is covered with a layer of mud and could not be inspected. It is our opinion that the exposed HDPE liner is in adequate condition for continued operation.

RECOMMENDATION

It is recommended that Flambeau Mine Company lock all passage gates into the surge and runoff ponds and that no unauthorized personnel be allowed access without supervision.

It is our opinion that Flambeau Mine Company employees are continuing to do a good job of liner systems inspection.


Sincerely,

Craig Walkey, P.E.

br:CE94081



SCALE 1"=50'



LEGEND
● REPAIR LOCATION

NOTE:
REPAIR NUMBERS ARE IDENTIFIED
IN REPORT AND PHOTOGRAPHS

RUN-OFF POND REPAIRS FLAMBEAU MINING COMPANY NOVEMBER 21-22, 1994



COOPER ENGINEERING COMPANY
310 WEST SOUTH STREET RICE LAKE, WISCONSIN
TELEPHONE 715-234-7008


RUNOFF.DWG 12-8-94 MRE

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN

RUNOFF POND LINER REPAIR
NOVEMBER, 1994




TEST WELD




TEST WELD STRETCH
USING FIELD TENSIOMETER

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN
RUNOFF POND LINER REPAIR
NOVEMBER, 1994



DAMAGE #1, #2, #3, #4 & #7
11/20/94




DAMAGE #5 & #6
11/20/94

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN

RUNOFF POND LINER REPAIR
NOVEMBER, 1994



DAMAGE #1
11/20/94




REPAIR #1
11/20/94

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN

RUNOFF POND LINER REPAIR
NOVEMBER, 1994




DAMAGE #2
11/20/94




REPAIR #2
11/20/94

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN
RUNOFF POND LINER REPAIR
NOVEMBER, 1994



DAMAGE #3
11/20/94




REPAIR #3
11/20/94

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN

RUNOFF POND LINER REPAIR
NOVEMBER, 1994



DAMAGE #4
11/20/94



REPAIR #4
11/20/94

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN

RUNOFF POND LINER REPAIR
NOVEMBER, 1994




REPAIR #5
11/20/94



DAMAGE #6
11/20/94

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN
RUNOFF POND LINER REPAIR
NOVEMBER, 1994



REPAIR #6
11/20/94



TYPICAL VACUUM BOX TEST
REPAIRS #1-#6 11/20/94

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN


RUNOFF POND LINER REPAIR
NOVEMBER, 1994




DAMAGE #7
11/21/94

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN

RUNOFF POND LINER REPAIR
NOVEMBER, 1994



DAMAGE #8
11/21/94



REPAIR #8
11/21/94

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN
RUNOFF POND LINER REPAIR
NOVEMBER, 1994



DAMAGE #10
11/21/94




REPAIR #10
11/21/94

FLAMBEAU MINING CO.
LADYSMITH, WISCONSIN
RUNOFF POND LINER REPAIR
NOVEMBER, 1994



TYPICAL VACUUM BOX TEST
REPAIRS #7-#10 11/21/94



REPAIRS #8, #9 & #10
11/21/94